



SOUTH CAROLINA AERONAUTICS COMMISSION

STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

 LUX - Laurens County Airport



Kimley»»Horn

2022



Contents

Overview	3
Introduction.....	3
System Inventory.....	4
Functional Evaluation.....	7
Pavement Condition Index.....	7
Critical PCI.....	8
PCI Results Summary	8
Pavement Condition Forecast	10
M&R Overview	14
Localized Maintenance and Repair.....	15
Major Rehabilitation Needs.....	15
Appendix A – Exhibits	A-1
Appendix B – Analysis Tables.....	B-1
Appendix C – Maintenance and Rehabilitation Tables.....	C-1
Appendix D – Detailed PCI Results.....	D-1
Appendix E – Re-Inspection Report.....	E-1

Overview

Introduction

For over 20 years, the South Carolina Aeronautics Commission (SCAC) has implemented an airfield pavement management program for publicly owned South Carolina airports. As part of their grant assurances federally obligated airports are required to perform detailed inspections as outlined in the FAA Advisory Circular 150/5380-7B – “Airport Pavement Management Program (PMP)”. All inspections performed within this program follow the guidance documented within the ASTM D5340-20 – “Standard Test Method for Airport Pavement Condition Surveys”. This is an objective process to assess the pavement condition in a consistent and repeatable manner.

Due to ever-changing pavement conditions, the FAA AC 150/5380-7B recommends the PMP be updated every 3 years. The overall pavement conditions are analyzed using the ASTM PCI methodology. It provides decision makers with a comparison of pavement facilities and a relative indication of their required maintenance or level of repair to aid in project prioritization. A detailed explanation of the SCAC airfield pavement management program process and pavement management terminology can be found in the [SCAC Statewide Report](#).

Project elements performed for the 2021-2024 program update included the development and update of pavement inventories, documentation of pavement conditions, performance modeling, and maintenance and rehabilitation (M&R) needs for all participating airports. This report summarizes the results of the SCAC pavement management program update at Laurens County Airport (LUX).

Figure 1 – Airport Layout



System Inventory

The pavements at Laurens County Airport (LUX) include approximately 0.6 million square feet of airfield pavements consisting of runways, taxiways, and aprons. Per the guidance in the ASTM D5340-20, all pavements were divided and subdivided into pavement management units (Network, Branch, Section, Sample). The divisions are documented in the **Network Definition Exhibit** providing the name and location of each branch, section, and sample.


Each pavement update includes review of documentation of any maintenance and major rehabilitation related activities performed on the airfield pavements. The following table summarizes the projects that have occurred since the previous inspection.


Table 1 - Recent Airfield Pavement Construction

Construction Year	Location	Work Type / Pavement Section
2019	TW A	Crack Sealing - AC, Surface Seal - Rejuvenating

The following figure summarizes the inventory items at Laurens County Airport (LUX). The **Estimated Age Exhibit** provides the last major work date for each pavement section based on the collected documentation.

Figure 2 – System Inventory Summary






LEGEND

- RW 13-31 — TYPICAL RUNWAY BRANCH ID
- TW A — TYPICAL TAXIWAY BRANCH ID
- AP S — TYPICAL APRON BRANCH ID
- RW 13-10 — PAVEMENT BRANCH ID: SECTION ID
- AAC 5 of 15 — NUMBER OF SAMPLE UNITS IN SECTION
- PCC — NUMBER OF SAMPLE UNITS TO BE INSPECTED
- AC — PAVEMENT SURFACE TYPE
- RW 13-20 — SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE ESTIMATED AGE EXHIBIT FOR CONSTRUCTION DATES.
- AAC 0 of 5 —
- 100 — INSPECTED SAMPLE UNITS.

TOTAL SAMPLES INSPECTED = 84
AC: 5 PCC: 79






RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





Legend

Estimated Age at Inspection

-  0-5 Years
-  6-10 Years
-  11-15 Years
-  16-20 Years
-  > 20 Years

┌── BRANCH IDENTIFIER
└── SECTION IDENTIFIER
TWA:20 | 1985
└── LAST MAJOR WORK DATE



Functional Evaluation

Pavement Condition Index

A Pavement Condition Index (PCI) survey is the primary means of obtaining and recording pavement distress data. In adherence to FAA Advisory Circular 150/5380-7B, the SCAC Airfield Pavement Management System (APMS) Update utilizes the PCI survey methodology to collect pavement distress data and analyze the condition. This method uses a visual statistical sampling of pavements for recording primary distress types, associated severities, and quantities as defined by the ASTM D5340-20.

Visual condition data collected during the PCI survey is analyzed and used to calculate the current PCI for each inspected sample unit and section. The PCI is a value ranging from 0 to 100, which indicates the apparent structural integrity and surface operational condition of the pavement, with **“100” indicating a pavement in new condition and “0” indicating a failed pavement section**. Pavement Condition Ratings are associated with PCI categories that range from Failed to Good. Representative photos of varying Pavement Condition Ratings are displayed in **Figure 3**.

Figure 3 – Representation of Pavement Condition Index Values



Poor/Failed Pavement

Pavements that are Poor to Failed require significant and costly interventions such as reconstruction to restore the pavement to operational service.




Fair Pavement

Pavements with a Fair condition rating typically require rehabilitation, or maintenance activities if rehabilitation cannot be immediately performed.



Good/New Pavement

Pavements classified as Good require either no treatment or would benefit from the application of preventive maintenance activities such as crack sealing.




Critical PCI

From a pavement management perspective, one of the most valuable aspects of the PCI methodology is the ability to save money by effectively prioritizing the rehabilitation of pavement assets. Critical PCI refers to the condition beyond which the rate of pavement deterioration and the cost of applying a treatment increases significantly. In other words, it is the condition at which maintenance may no longer be cost effective and major rehabilitation should be considered. Based on the 2019 FAA Order 5100.38D Change 1 Airport Improvement Program Handbook, the FAA has established recommended PCI thresholds for pavement M&R. Accordingly, **the Critical PCI for all SCAC airfield pavements is defined at 70.**

PCI Results Summary


The PCI survey for Laurens County Airport (LUX) was performed in September 2021. **The overall area-weighted average PCI value of the network was 97**, representing a condition rating of **Good**. All of inspected pavements are in Good or Satisfactory condition as summarized in **Figure 4**.

Figure 4 – Overall Network PCI Results



The area-weighted average PCIs by branch use are summarized in the figure below. The current PCIs at a section-level are displayed graphically on the **2021 Airfield Pavement Condition Index (PCI) Exhibit** and are summarized in **Table 2**.

Figure 5 – Area Weighted Average Pavement Condition





STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

LUX - Laurens County Airport

Table 2 – Current Pavement Condition Index Summary - Section


Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
LUX	AP 01	Apron	10	93,075	PCC	99	Good	69	0	31
LUX	RW 8	Runway	10	175,320	PCC	100	Good	94	0	6
LUX	RW 8	Runway	15	58,440	PCC	97	Good	96	0	4
LUX	RW 8	Runway	20	58,440	PCC	98	Good	100	0	0
LUX	RW 8	Runway	25	6,975	PCC	98	Good	100	0	0
LUX	RW 8	Runway	30	2,325	PCC	93	Good	100	0	0
LUX	RW 8	Runway	35	2,325	PCC	93	Good	100	0	0
LUX	TL 01	Taxilane	10	10,175	PCC	100	Good	11	0	89
LUX	TL 01	Taxilane	15	18,849	AC	82	Satisfactory	100	0	0
LUX	TL 01	Taxilane	20	15,063	AC	96	Good	100	0	0
LUX	TL 01	Taxilane	25	1,063	PCC	100	Good	80	0	20
LUX	TL 01	Taxilane	30	1,094	PCC	100	Good	80	0	20
LUX	TW A	Taxiway	10	50,982	PCC	99	Good	100	0	0
LUX	TW A	Taxiway	20	19,193	PCC	99	Good	0	0	100
LUX	TW A	Taxiway	25	54,180	AC	79	Satisfactory	100	0	0
LUX	TW A	Taxiway	30	9,113	PCC	99	Good	100	0	0
LUX	TW A1	Taxiway	10	4,017	PCC	100	Good	0	5	95
LUX	TW A1	Taxiway	15	4,107	PCC	100	Good	35	0	65
LUX	TW A2	Taxiway	10	10,457	PCC	96	Good	41	0	59
LUX	TW A3	Taxiway	10	9,372	PCC	98	Good	100	0	0
LUX	TW A4	Taxiway	10	9,698	PCC	100	Good	12	49	39
LUX	TW RU 8	Taxiway	10	6,075	PCC	99	Good	0	0	100

*For further PCI details and photos see Appendix D – Detailed PCI Results.

Pavement Condition Forecast

A primary objective of this APMS is to estimate the future condition of each individual pavement section. PAVER™ was utilized to develop prediction curves and determine typical deterioration rates that are then used to forecast a future PCI. This value will assist decision makers in determining at what point in time certain pavement sections will require rehabilitation. The figure below shows the current and 5-year area-weighted forecasted pavement condition distribution of each functional use (Runway, Taxiway, Taxilane, Apron) found at the Airport. The forecasted 5-year PCIs at a section-level are displayed graphically on the **2026 Forecasted Airfield Pavement Condition Index Exhibit** and are summarized in **Table 3**. All forecasts presented assume that no maintenance or rehabilitation is performed within the 5-year analysis period. **Figure 6** displays the forecasted pavement conditions at the branch-level for LUX.

Figure 6 – Forecasted 5-Year PCI by Branch Use




All condition forecasts are based on historical observations and analysis of South Carolina airfield pavements. The forecasts are not a guarantee of future PCI:- rather, they are a planning tool to aid in the timing of maintenance and rehabilitation activities.



LUX - Laurens County Airport

Table 3 – Forecasted (2022-2026) Pavement Condition Index Summary - Section

Network ID	Branch ID	Section ID	Current PCI	Forecasted PCI				
				2022	2023	2024	2025	2026
LUX	AP 01	10	99	99	98	98	97	96
LUX	RW 8	10	100	100	100	100	99	99
LUX	RW 8	15	97	96	96	95	94	93
LUX	RW 8	20	98	98	97	96	95	95
LUX	RW 8	25	98	98	97	96	95	95
LUX	RW 8	30	93	92	91	90	89	88
LUX	RW 8	35	93	92	91	90	89	88
LUX	TL 01	10	100	100	100	100	99	99
LUX	TL 01	15	82	81	80	80	80	79
LUX	TL 01	20	96	94	90	88	85	83
LUX	TL 01	25	100	100	100	100	99	99
LUX	TL 01	30	100	100	100	100	99	99
LUX	TW A	10	99	99	98	98	97	96
LUX	TW A	20	99	99	98	98	97	96
LUX	TW A	25	79	79	78	77	75	73
LUX	TW A	30	99	99	98	98	97	96
LUX	TW A1	10	100	100	100	100	99	99
LUX	TW A1	15	100	100	100	100	99	99
LUX	TW A2	10	96	95	95	94	93	92
LUX	TW A3	10	98	98	97	96	95	95
LUX	TW A4	10	100	100	100	100	99	99
LUX	TW RU 8	10	99	99	98	98	97	96




Legend

2021 Pavement Condition Index

- PCI 86-100 Good
- PCI 71-85 Satisfactory
- PCI 56-70 Fair
- PCI 41-55 Poor
- PCI 26-40 Very Poor
- PCI 11-25 Serious
- PCI 0-10 Failed

— BRANCH IDENTIFIER
 — SECTION IDENTIFIER
TWA:20 (84)
 — PCI





Legend

2026 Forecasted Pavement Condition Index

- PCI 86-100 Good
- PCI 71-85 Satisfactory
- PCI 56-70 Fair
- PCI 41-55 Poor
- PCI 26-40 Very Poor
- PCI 11-25 Serious
- PCI 0-10 Failed

— BRANCH IDENTIFIER
— SECTION IDENTIFIER
TWA:20 (84)
— FORECASTED PCI




M&R Overview

An analysis was performed to assess the pavement maintenance and rehabilitation (M&R) needs at LUX over a 5-year period. The analysis compared the forecasted condition of each pavement section to Critical PCI threshold to develop a resultant recommendation and associated cost for each year of the 5-year plan. The M&R analysis should enable responsible parties to do the following:

- ➔ **Maintain** existing airport infrastructure at an acceptable condition
- ➔ Make timely and cost-effective **decisions** to appropriately allocate funding
- ➔ **Apply** global maintenance, localized maintenance, and major M&R activities in a timely manner to maintain an acceptable operational condition of a pavement network.

M&R planning considers various methods of repair to address the cause of the problem rather than just treating the symptom. As pavements deteriorate, repair costs can increase significantly. Once pavements have deteriorated below a certain condition threshold (the Critical PCI value), the pavement benefits more from substantial rehabilitation in lieu of maintenance activities. The figure below illustrates how the cost of pavement repairs can exponentially increase if M&R activities are delayed.

Figure 7 – Pavement Life and the Effect of Treatments



Localized Maintenance and Repair

Localized maintenance is best used as a preservation measure and is applied to slow the rate of deterioration. These activities typically include crack sealing and patching. Localized maintenance differs from major rehabilitation in that it is applied based on the distresses observed rather than based on a PCI value. Treatments are selected based on the appropriate corrective measure for a given distress type and severity level. Localized maintenance applied on pavements with PCIs above the Critical PCI of 70 is known as Preventive Localized Maintenance, while Stopgap Localized Maintenance is typically applied to pavement sections that are at or below the Critical PCI value as a temporary repair due to safety concerns. The current localized maintenance needs are summarized in the table below.

Table 4 – Localized Maintenance Summary by Policy Type

Localized Maintenance Category	Localized Work Type	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
Localized Preventive Maintenance	AC Crack Sealing Narrow	5,524	LF	\$ 22,110
	PCC Joint Seal	4,346	LF	\$ 30,440
<i>Localized Preventive Maintenance Total =</i>				\$ 52,550
Localized Stopgap Maintenance	N/A	-	-	\$ -
<i>Localized Stopgap Maintenance Total =</i>				\$ -
<i>Total Planning-Level Localized Maintenance Needs =</i>				\$ 52,550

Major Rehabilitation Needs

Major rehabilitation needs are identified by analyzing the Airport's pavement condition in relationship to Critical PCI values, density of load-related distresses, and major rehabilitation policies, assuming there are no budget constraints. The needs analysis is performed over a 5-year analysis period. Major rehabilitation resets the PCI value to 100 and is divided into two policy categories:


- **Intermediate Major Rehabilitation (PCI 56 to 70)** –
 - **AC:** Milling of the upper surface course and replacing with new AC with isolated areas of full-depth reconstruction
 - **PCC:** Combination of crack sealing, joint seal replacement, limited patching, and slab replacement
- **Full-Depth Reconstruction (PCI 0 to 55)** – Removal and replacement of the existing pavement section down to the subgrade


The 5-year major rehabilitation needs analysis at LUX resulted in no major rehabilitation needs for the 5-year analysis duration. The **5-Year Major Rehabilitation Needs Exhibit** graphically depicts the major rehabilitation needs at a section-level which are also summarized in **Table 5** with rounded costs. Annual needs are displayed graphically in **Figure 8**.

Table 5 – 5-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate	
<i>*No Major Rehabilitation Needs identified or forecasted during the 5-Year planning period</i>									
<i>Total 5-Year Major Rehabilitation Needs =</i>								\$	-

Figure 8 – 5-Year Major Rehabilitation Needs by Program Year





Legend

5-Year Major Rehabilitation Needs

- Year 1 Reconstruction Needs
- Year 1 Rehabilitation Needs
- Year 2 Rehabilitation Needs
- Year 3 Rehabilitation Needs
- Year 4 Rehabilitation Needs
- Year 5 Rehabilitation Needs

M&R COST
 BRANCH IDENTIFIER
 SECTION IDENTIFIER
TWA:20 M&R WORK TYPE
\$9.38 M | AC RECON
PCI = 52 | 1987
 PCI LAST MAJOR WORK DATE

THIS EXHIBIT REPRESENTS NEEDS SOLEY BASED ON CURRENT AND FORECASTED CONDITIONS FURTHER PRIORITIZATION AND CONSIDERATIONS SHOULD BE MADE BEYOND THIS STUDY.




SECTION I

Appendices















Appendix A – Exhibits




LEGEND

-  RW 13-31 — TYPICAL RUNWAY BRANCH ID
-  TW A — TYPICAL TAXIWAY BRANCH ID
-  AP S — TYPICAL APRON BRANCH ID
-  RW 13-10 — PAVEMENT BRANCH ID: SECTION ID
-  AAC 5 of 15 — NUMBER OF SAMPLE UNITS IN SECTION
-  AAC 0 of 5 — NUMBER OF SAMPLE UNITS TO BE INSPECTED
-  100 — PAVEMENT SURFACE TYPE
-  RW 13-20 — SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE ESTIMATED AGE EXHIBIT FOR CONSTRUCTION DATES.
-  AAC 0 of 5 — SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE ESTIMATED AGE EXHIBIT FOR CONSTRUCTION DATES.
-  100 — INSPECTED SAMPLE UNITS.

TOTAL SAMPLES INSPECTED = 84
AC: 5 PCC: 79

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.






Legend

Estimated Age at Inspection

- 0-5 Years
- 6-10 Years
- 11-15 Years
- 16-20 Years
- > 20 Years

┌───┐ BRANCH IDENTIFIER
└───┘ SECTION IDENTIFIER
TWA:20 | 1985
└───┘ LAST MAJOR WORK DATE






Legend

2021 Pavement Condition Index

- PCI 86-100 Good
- PCI 71-85 Satisfactory
- PCI 56-70 Fair
- PCI 41-55 Poor
- PCI 26-40 Very Poor
- PCI 11-25 Serious
- PCI 0-10 Failed

— BRANCH IDENTIFIER
 — SECTION IDENTIFIER
TWA:20 (84)
 — PCI






Legend

2026 Forecasted Pavement Condition Index

- PCI 86-100 Good
- PCI 71-85 Satisfactory
- PCI 56-70 Fair
- PCI 41-55 Poor
- PCI 26-40 Very Poor
- PCI 11-25 Serious
- PCI 0-10 Failed

— BRANCH IDENTIFIER
— SECTION IDENTIFIER
TWA:20 (84)
— FORECASTED PCI





Legend

5-Year Major Rehabilitation Needs

- Year 1 Reconstruction Needs
- Year 1 Rehabilitation Needs
- Year 2 Rehabilitation Needs
- Year 3 Rehabilitation Needs
- Year 4 Rehabilitation Needs
- Year 5 Rehabilitation Needs

M&R COST
 BRANCH IDENTIFIER
 SECTION IDENTIFIER
TWA:20 M&R WORK TYPE
\$9.38 M | AC RECON
PCI = 52 | 1987
 PCI LAST MAJOR WORK DATE

THIS EXHIBIT REPRESENTS NEEDS SOLEY BASED ON CURRENT AND FORECASTED CONDITIONS FURTHER PRIORITIZATION AND CONSIDERATIONS SHOULD BE MADE BEYOND THIS STUDY.





Appendix B – Analysis Tables



Table B1 – System Inventory Data - Section

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
LUX	AP 01	Apron	10	93,075	PCC	1/1/2013
LUX	RW 8	Runway	10	175,320	PCC	1/1/2013
LUX	RW 8	Runway	15	58,440	PCC	1/1/2013
LUX	RW 8	Runway	20	58,440	PCC	1/1/2013
LUX	RW 8	Runway	25	6,975	PCC	1/1/2013
LUX	RW 8	Runway	30	2,325	PCC	1/1/2013
LUX	RW 8	Runway	35	2,325	PCC	1/1/2013
LUX	TL 01	Taxilane	10	10,175	PCC	1/1/2017
LUX	TL 01	Taxilane	15	18,849	AC	1/1/2011
LUX	TL 01	Taxilane	20	15,063	AC	1/1/2011
LUX	TL 01	Taxilane	25	1,063	PCC	1/1/2017
LUX	TL 01	Taxilane	30	1,094	PCC	1/1/2017
LUX	TW A	Taxiway	10	50,982	PCC	1/1/2017
LUX	TW A	Taxiway	20	19,193	PCC	1/1/2013
LUX	TW A	Taxiway	25	54,180	AC	9/1/2006
LUX	TW A	Taxiway	30	9,113	PCC	1/1/2013
LUX	TW A1	Taxiway	10	4,017	PCC	1/1/2017
LUX	TW A1	Taxiway	15	4,107	PCC	1/1/2013
LUX	TW A2	Taxiway	10	10,457	PCC	1/1/2013
LUX	TW A3	Taxiway	10	9,372	PCC	1/1/2013
LUX	TW A4	Taxiway	10	9,698	PCC	1/1/2013
LUX	TW RU 8	Taxiway	10	6,075	PCC	1/1/2017

Table B2 – Current Pavement Condition Index Summary - Branch

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Area-Weighted Avg PCI	Condition Rating
AP 01	Apron	1	93,075	99	Good
RW 8	Runway	6	303,825	99	Good
TL 01	Taxilane	5	46,244	91	Good
TW A	Taxiway	4	133,468	91	Good
TW A1	Taxiway	2	8,124	100	Good
TW A2	Taxiway	1	10,457	96	Good
TW A3	Taxiway	1	9,372	98	Good
TW A4	Taxiway	1	9,698	100	Good
TW RU 8	Taxiway	1	6,075	99	Good



STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

LUX - Laurens County Airport

Table B3 – Current (2021) Pavement Condition Index Summary - Section

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
LUX	AP 01	Apron	10	93,075	PCC	99	Good	69	0	31	6	30
LUX	RW 8	Runway	10	175,320	PCC	100	Good	94	0	6	26	130
LUX	RW 8	Runway	15	58,440	PCC	97	Good	96	0	4	9	44
LUX	RW 8	Runway	20	58,440	PCC	98	Good	100	0	0	9	44
LUX	RW 8	Runway	25	6,975	PCC	98	Good	100	0	0	1	5
LUX	RW 8	Runway	30	2,325	PCC	93	Good	100	0	0	1	2
LUX	RW 8	Runway	35	2,325	PCC	93	Good	100	0	0	1	2
LUX	TL 01	Taxilane	10	10,175	PCC	100	Good	11	0	89	2	8
LUX	TL 01	Taxilane	15	18,849	AC	82	Satisfactory	100	0	0	1	4
LUX	TL 01	Taxilane	20	15,063	AC	96	Good	100	0	0	1	3
LUX	TL 01	Taxilane	25	1,063	PCC	100	Good	80	0	20	1	1
LUX	TL 01	Taxilane	30	1,094	PCC	100	Good	80	0	20	1	1
LUX	TW A	Taxiway	10	50,982	PCC	99	Good	100	0	0	9	42
LUX	TW A	Taxiway	20	19,193	PCC	99	Good	0	0	100	1	5
LUX	TW A	Taxiway	25	54,180	AC	79	Satisfactory	100	0	0	3	11
LUX	TW A	Taxiway	30	9,113	PCC	99	Good	100	0	0	2	7
LUX	TW A1	Taxiway	10	4,017	PCC	100	Good	0	5	95	1	4
LUX	TW A1	Taxiway	15	4,107	PCC	100	Good	35	0	65	1	4
LUX	TW A2	Taxiway	10	10,457	PCC	96	Good	41	0	59	3	12
LUX	TW A3	Taxiway	10	9,372	PCC	98	Good	100	0	0	2	10
LUX	TW A4	Taxiway	10	9,698	PCC	100	Good	12	49	39	2	8
LUX	TW RU 8	Taxiway	10	6,075	PCC	99	Good	0	0	100	1	4



LUX - Laurens County Airport

Table B4 –Forecasted (2022-2026) Pavement Condition Index Summary - Section

Network ID	Branch ID	Section ID	Current PCI	Forecasted PCI				
				2022	2023	2024	2025	2026
LUX	AP 01	10	99	99	98	98	97	96
LUX	RW 8	10	100	100	100	100	99	99
LUX	RW 8	15	97	96	96	95	94	93
LUX	RW 8	20	98	98	97	96	95	95
LUX	RW 8	25	98	98	97	96	95	95
LUX	RW 8	30	93	92	91	90	89	88
LUX	RW 8	35	93	92	91	90	89	88
LUX	TL 01	10	100	100	100	100	99	99
LUX	TL 01	15	82	81	80	80	80	79
LUX	TL 01	20	96	94	90	88	85	83
LUX	TL 01	25	100	100	100	100	99	99
LUX	TL 01	30	100	100	100	100	99	99
LUX	TW A	10	99	99	98	98	97	96
LUX	TW A	20	99	99	98	98	97	96
LUX	TW A	25	79	79	78	77	75	73
LUX	TW A	30	99	99	98	98	97	96
LUX	TW A1	10	100	100	100	100	99	99
LUX	TW A1	15	100	100	100	100	99	99
LUX	TW A2	10	96	95	95	94	93	92
LUX	TW A3	10	98	98	97	96	95	95
LUX	TW A4	10	100	100	100	100	99	99
LUX	TW RU 8	10	99	99	98	98	97	96



Appendix C – Maintenance and Rehabilitation Tables



STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

LUX - Laurens County Airport

Table C1 – Localized Maintenance Summary by Policy Type

Localized Maintenance Category	Localized Work Type	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
Localized Preventive Maintenance	AC Crack Sealing Narrow	5,524	LF	\$ 22,110
	PCC Joint Seal	4,346	LF	\$ 30,440
Localized Preventive Maintenance Total =				\$ 52,550
Localized Stopgap Maintenance	N/A	-	-	\$ -
Localized Stopgap Maintenance Total =				\$ -
Total Planning-Level Localized Maintenance Needs =				\$ 52,550

Table C2 – Section – Level Year 1 Localized Maintenance Planning Cost Summary

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
LUX	AP 01	10	93,075	99	99	\$ -
LUX	RW 8	10	175,320	100	100	\$ 19,930
LUX	RW 8	15	58,440	97	98	\$ 210
LUX	RW 8	20	58,440	98	98	\$ -
LUX	RW 8	25	6,975	98	98	\$ -
LUX	RW 8	30	2,325	93	100	\$ 5,150
LUX	RW 8	35	2,325	93	100	\$ 5,150
LUX	TL 01	10	10,175	100	100	\$ -
LUX	TL 01	15	18,849	82	87	\$ 3,250
LUX	TL 01	20	15,063	96	96	\$ 180
LUX	TL 01	25	1,063	100	100	\$ -
LUX	TL 01	30	1,094	100	100	\$ -
LUX	TW A	10	50,982	99	99	\$ -
LUX	TW A	20	19,193	99	99	\$ -
LUX	TW A	25	54,180	79	79	\$ 18,680
LUX	TW A	30	9,113	99	99	\$ -
LUX	TW A1	10	4,017	100	100	\$ -
LUX	TW A1	15	4,107	100	100	\$ -
LUX	TW A2	10	10,457	96	96	\$ -
LUX	TW A3	10	9,372	98	98	\$ -
LUX	TW A4	10	9,698	100	100	\$ -
LUX	TW RU 8	10	6,075	99	99	\$ -



STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

LUX - Laurens County Airport

Table C3 – Localized Maintenance and Repair Needs Based on Current Distresses

Network ID	Branch ID	Section ID	Description	Severity	Distress Qty	Distress Unit	Distress Density	Policy Type	Localized Work Type	Work Qty	Work Unit	Unit Cost	Work Cost
LUX	RW 8	10	JT SEAL DMG	Medium	120	Slabs	3.9%	Preventive	PCC Joint Seal	2,847	LF	\$ 7.00	\$ 19,930
LUX	RW 8	15	JT SEAL DMG	Medium	120	Slabs	11.5%	Preventive	PCC Joint Seal	30	LF	\$ 7.00	\$ 210
LUX	RW 8	30	JT SEAL DMG	Medium	41	Slabs	100.0%	Preventive	PCC Joint Seal	735	LF	\$ 7.00	\$ 5,150
LUX	RW 8	35	JT SEAL DMG	Medium	41	Slabs	100.0%	Preventive	PCC Joint Seal	735	LF	\$ 7.00	\$ 5,150
LUX	TL 01	15	L & T CR	Low	540	LF	2.9%	Preventive	AC Crack Sealing Narrow	540	LF	\$ 4.00	\$ 2,160
LUX	TL 01	15	L & T CR	Medium	272	LF	1.4%	Preventive	AC Crack Sealing Narrow	272	LF	\$ 4.00	\$ 1,090
LUX	TL 01	20	L & T CR	Low	44	LF	0.3%	Preventive	AC Crack Sealing Narrow	44	LF	\$ 4.00	\$ 180
LUX	TW A	25	L & T CR	Low	4,668	LF	8.6%	Preventive	AC Crack Sealing Narrow	4,668	LF	\$ 4.00	\$ 18,680

Table C4 – 5-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
<i>*No Major Rehabilitation Needs identified or forecasted during the 5-Year planning period</i>								
Total 5-Year Major Rehabilitation Needs =								\$ -



Appendix D – Detailed PCI Results

LUX - Laurens County Airport

AP 01

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP 01	APRON	1	93,075	99	Good

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	93,075	PCC	2013	-	99	Good	69	0	31



AP 01-10



AP 01-10

LUX - Laurens County Airport

RW 8

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 8	RUNWAY	6	303,825	99	Good

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	175,320	PCC	2013	-	100	Good	94	0	6
15	58,440	PCC	2013	-	97	Good	96	0	4
20	58,440	PCC	2013	-	98	Good	100	0	0
25	6,975	PCC	2013	-	98	Good	100	0	0
30	2,325	PCC	2013	-	93	Good	100	0	0
35	2,325	PCC	2013	-	93	Good	100	0	0



RW 8-10



RW 8-10



RW 8-20

LUX - Laurens County Airport

TW A

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A	TAXIWAY	4	133,468	91	Good

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	50,982	PCC	2017	-	99	Good	100	0	0
20	19,193	PCC	2013	-	99	Good	0	0	100
25	54,180	AC	2006	2019	79	Satisfactory	100	0	0
30	9,113	PCC	2013	-	99	Good	100	0	0



TW A-10



TW A-25



TW A-30

LUX - Laurens County Airport

TW A1

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A1	TAXIWAY	2	8,124	100	Good

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	4,017	PCC	2017	-	100	Good	0	5	95
15	4,107	PCC	2013	-	100	Good	35	0	65



TW A1-10



TW A1-15

TW A2

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A2	TAXIWAY	1	10,457	96	Good

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	10,457	PCC	2013	-	96	Good	41	0	59



TW A2-10



TW A2-10

LUX - Laurens County Airport

TW A3

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A3	TAXIWAY	1	9,372	98	Good

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	9,372	PCC	2013	-	98	Good	100	0	0



TW A3-10



TW A3-10

TW A4

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A4	TAXIWAY	1	9,698	100	Good

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	9,698	PCC	2013	-	100	Good	12	49	39



TW A4-10

TW RU 8

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW RU 8	TAXIWAY	1	6,075	99	Good

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	6,075	PCC	2017	-	99	Good	0	0	100



TW A4-10

TL 01

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TL 01	TAXILANE	5	46,244	91	Good

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	10,175	PCC	2017	-	100	Good	11	0	89
15	18,849	AC	2011	2017	82	Satisfactory	100	0	0
20	15,063	AC	2011	2017	96	Good	100	0	0
25	1,063	PCC	2017	-	100	Good	80	0	20
30	1,094	PCC	2017	-	100	Good	80	0	20



TL 01-10



TL 01-15



TL 01-20



Appendix E – Re-Inspection Report

Re-Inspection Report

SCAC_2021

Generated Date

5/29/2022

Page 1 of 23

Network: LUX **Name:** Laurens County Airport

Branch: AP 01 **Name:** MAIN APRON **Use:** APRON **Area:** 93,075 SqFt

Section: 10 of 1 **From:** - **To:** - **Last Const.:** 1/1/2013

Surface: PCC **Family:** SC III & IV-PCC **Zone:** **Category:** G **Rank:** S

Area: 93,075 SqFt **Length:** 325 Ft **Width:** 24 Ft

Slabs: 596 **Slab Length:** 12 Ft **Slab Width:** 12 Ft **Joint Length:** 899 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 6/1/1992 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 6/1/1992 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 6/1/1992 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 6/1/1997 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

Work Date: 1/1/2013 **Work Type:** Complete Reconstruction - PCC **Code:** CR-PC **Is Major M&R:** True

Last Insp. Date: 9/21/2021 **Total Samples:** 30 **Surveyed:** 6

Conditions: PCI: 99

Inspection Comments:

Sample Number: 05 **Type:** R **Area:** 20.00 Slabs **PCI:** 98

Sample Comments:

65 JT SEAL DMG L 20.00 Slabs

Sample Number: 07 **Type:** R **Area:** 24.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>

Sample Number: 12 **Type:** R **Area:** 20.00 Slabs **PCI:** 99

Sample Comments:

73 SHRINKAGE CR N 1.00 Slabs

Sample Number: 17 **Type:** R **Area:** 20.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>

Sample Number: 25 **Type:** R **Area:** 24.00 Slabs **PCI:** 97


Sample Comments:

73 SHRINKAGE CR N 4.00 Slabs

Sample Number: 29 **Type:** R **Area:** 20.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>



Network:	LUX	Name:	Laurens County Airport						
Branch:	RW 8	Name:	RUNWAY 8/26	Use:	RUNWAY	Area:	303,825 SqFt		
Section:	10	of	6	From:	-	To:	-	Last Const.:	1/1/2013
Surface:	PCC	Family:	SC III & IV-PCC	Zone:		Category:	G	Rank:	P
Area:	175,320 SqFt	Length:	3,900 Ft	Width:	75 Ft				
Slabs:	3,117	Slab Length:	7 Ft	Slab Width:	7 Ft	Joint Length:	74,025 Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	6/1/1992	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Work Date:	6/1/1992	Work Type:	Surface Course - AC (Layer Construct)		Code:	SU-AC	Is Major M&R:	False	
Work Date:	6/1/1992	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R:	False	
Work Date:	6/1/1997	Work Type:	Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False	
Work Date:	1/1/2013	Work Type:	Complete Reconstruction - PCC		Code:	CR-PC	Is Major M&R:	True	
Last Insp. Date:	9/21/2021	TotalSamples:	130	Surveyed:	26				
Conditions:	PCI: 100								
Inspection Comments:									
Sample Number:	05	Type:	R	Area:	24.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG	L		24.00	Slabs				
Sample Number:	10	Type:	R	Area:	24.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									
Sample Number:	100	Type:	R	Area:	24.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									
Sample Number:	105	Type:	R	Area:	24.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									
Sample Number:	110	Type:	R	Area:	24.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									
Sample Number:	115	Type:	R	Area:	24.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									
Sample Number:	120	Type:	R	Area:	24.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									
Sample Number:	125	Type:	R	Area:	24.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									
Sample Number:	130	Type:	R	Area:	24.00 Slabs	PCI:	93		
Sample Comments:									
65	JT SEAL DMG	M		24.00	Slabs				
Sample Number:	15	Type:	R	Area:	24.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									

Sample Number: 20	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			
Sample Number: 25	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			
Sample Number: 30	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			
Sample Number: 35	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			
Sample Number: 40	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			
Sample Number: 45	Type: R	Area: 24.00 Slabs	PCI: 97
Sample Comments: 74 JOINT SPALL L 2.00 Slabs			
Sample Number: 50	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			
Sample Number: 55	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			
Sample Number: 60	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			
Sample Number: 65	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			
Sample Number: 70	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			
Sample Number: 75	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			
Sample Number: 80	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			
Sample Number: 85	Type: R	Area: 24.00 Slabs	PCI: 99
Sample Comments: 73 SHRINKAGE CR N 1.00 Slabs			
Sample Number: 90	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			
Sample Number: 95	Type: R	Area: 24.00 Slabs	PCI: 100
Sample Comments: <No Distress>			

Network:	LUX	Name:	Laurens County Airport						
Branch:	RW 8	Name:	RUNWAY 8/26	Use:	RUNWAY	Area:	303,825 SqFt		
Section:	15	of	6	From:	-	To:	-	Last Const.:	1/1/2013
Surface:	PCC	Family:	SC III & IV-PCC	Zone:		Category:	G	Rank:	P
Area:	58,440 SqFt	Length:	3,900 Ft	Width:	4 Ft				
Slabs:	1,039	Slab Length:	7 Ft	Slab Width:	7 Ft	Joint Length:	256 Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	6/1/1992	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R:	False	
Work Date:	6/1/1992	Work Type:	Surface Course - AC (Layer Construct)		Code:	SU-AC	Is Major M&R:	False	
Work Date:	6/1/1992	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Work Date:	6/1/1997	Work Type:	Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False	
Work Date:	1/1/2013	Work Type:	Complete Reconstruction - PCC		Code:	CR-PC	Is Major M&R:	True	
Last Insp. Date:	9/21/2021	TotalSamples:	44	Surveyed:	9				
Conditions:	PCI: 97								
Inspection Comments:									
Sample Number:	03	Type:	R	Area:	24.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									
Sample Number:	08	Type:	R	Area:	24.00 Slabs	PCI:	93		
Sample Comments:									
65	JT SEAL DMG		M	24.00	Slabs				
Sample Number:	13	Type:	R	Area:	24.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG		L	24.00	Slabs				
Sample Number:	18	Type:	R	Area:	24.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG		L	24.00	Slabs				
Sample Number:	23	Type:	R	Area:	24.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG		L	24.00	Slabs				
Sample Number:	28	Type:	R	Area:	24.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG		L	24.00	Slabs				
Sample Number:	33	Type:	R	Area:	24.00 Slabs	PCI:	96		
Sample Comments:									
65	JT SEAL DMG		L	24.00	Slabs				
73	SHRINKAGE CR		N	3.00	Slabs				
Sample Number:	38	Type:	R	Area:	24.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG		L	24.00	Slabs				
Sample Number:	43	Type:	R	Area:	16.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG		L	16.00	Slabs				

Network:	LUX	Name:	Laurens County Airport						
Branch:	RW 8	Name:	RUNWAY 8/26	Use:	RUNWAY	Area:	303,825 SqFt		
Section:	20	of	6	From:	-	To:	-	Last Const.:	1/1/2013
Surface:	PCC	Family:	SC III & IV-PCC	Zone:		Category:	G	Rank:	P
Area:	58,440 SqFt	Length:	3,900 Ft	Width:	6 Ft				
Slabs:	1,039	Slab Length:	7 Ft	Slab Width:	7 Ft	Joint Length:	2,334 Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	6/1/1992	Work Type:	Base Course - Aggregate	Code:	BA-AG	Is Major M&R:	False		
Work Date:	6/1/1992	Work Type:	Surface Course - AC (Layer Construct)	Code:	SU-AC	Is Major M&R:	False		
Work Date:	6/1/1992	Work Type:	New Construction - Initial	Code:	NU-IN	Is Major M&R:	True		
Work Date:	6/1/1997	Work Type:	Crack Sealing - AC	Code:	CS-AC	Is Major M&R:	False		
Work Date:	1/1/2013	Work Type:	Complete Reconstruction - PCC	Code:	CR-PC	Is Major M&R:	True		
Last Insp. Date:	9/21/2021	TotalSamples:	44	Surveyed:	9				
Conditions:	PCI: 98								
Inspection Comments:									
Sample Number:	03	Type:	R	Area:	24.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG	L		24.00	Slabs				
Sample Number:	08	Type:	R	Area:	24.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG	L		24.00	Slabs				
Sample Number:	13	Type:	R	Area:	24.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG	L		24.00	Slabs				
Sample Number:	18	Type:	R	Area:	24.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									
Sample Number:	23	Type:	R	Area:	24.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									
Sample Number:	28	Type:	R	Area:	24.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG	L		24.00	Slabs				
Sample Number:	33	Type:	R	Area:	24.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG	L		24.00	Slabs				
Sample Number:	38	Type:	R	Area:	24.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG	L		24.00	Slabs				
Sample Number:	43	Type:	R	Area:	16.00 Slabs	PCI:	98		
Sample Comments:									
65	JT SEAL DMG	L		16.00	Slabs				

Network:	LUX	Name:	Laurens County Airport				
Branch:	RW 8	Name:	RUNWAY 8/26	Use:	RUNWAY	Area:	303,825 SqFt
Section:	25	of 6	From:	-	To:	-	Last Const.: 1/1/2013
Surface:	PCC	Family:	SC III & IV-PCC	Zone:		Category:	
Area:	6,975 SqFt	Length:	250 Ft	Width:	40 Ft	Rank:	P
Slabs:	124	Slab Length:	7 Ft	Slab Width:	7 Ft	Joint Length:	2,377 Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/2013	Work Type:	New Construction - Initial	Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	9/21/2021	Total Samples:	5	Surveyed:	1		
Conditions:	PCI: 98						
Inspection Comments:							
Sample Number:	05	Type:	R	Area:	30.00 Slabs	PCI:	98
Sample Comments:							
65	JT SEAL DMG	L		30.00	Slabs		



Network:	LUX	Name:	Laurens County Airport				
Branch:	RW 8	Name:	RUNWAY 8/26	Use:	RUNWAY	Area:	303,825 SqFt
Section:	30	of 6	From:	-	To:	-	Last Const.: 1/1/2013
Surface:	PCC	Family:	SC III & IV-PCC	Zone:		Category:	
Area:	2,325 SqFt	Length:	250 Ft	Width:	15 Ft	Rank:	P
Slabs:	41	Slab Length:	7 Ft	Slab Width:	7 Ft	Joint Length:	735 Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/2013	Work Type:	New Construction - Initial	Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	9/21/2021	Total Samples:	2	Surveyed:	1		
Conditions:	PCI: 93						
Inspection Comments:							
Sample Number:	01	Type:	R	Area:	24.00 Slabs	PCI:	93
Sample Comments:							
65	JT SEAL DMG	M		24.00	Slabs		



Network:	LUX	Name:	Laurens County Airport				
Branch:	RW 8	Name:	RUNWAY 8/26	Use:	RUNWAY	Area:	303,825 SqFt
Section:	35	of 6	From:	-	To:	-	Last Const.: 1/1/2013
Surface:	PCC	Family:	SC III & IV-PCC	Zone:		Category:	
Area:	2,325 SqFt	Length:	250 Ft	Width:	15 Ft	Rank:	P
Slabs:	41	Slab Length:	7 Ft	Slab Width:	7 Ft	Joint Length:	735 Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/2013	Work Type:	New Construction - Initial	Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	9/21/2021	Total Samples:	2	Surveyed:	1		
Conditions:	PCI: 93						
Inspection Comments:							
Sample Number:	01	Type:	R	Area:	24.00 Slabs	PCI:	93
Sample Comments:							
65	JT SEAL DMG	M		24.00	Slabs		



Network: LUX **Name:** Laurens County Airport

Branch: TL 01 **Name:** TAXILANE 01 **Use:** TAXILANE **Area:** 46,244 SqFt

Section: 10 of 5 **From:** - **To:** - **Last Const.:** 1/1/2017

Surface: PCC **Family:** SC III & IV-PCC **Zone:** **Category:** G **Rank:** T

Area: 10,175 SqFt **Length:** 334 Ft **Width:** 35 Ft

Slabs: 170 **Slab Length:** 10 Ft **Slab Width:** 6 Ft **Joint Length:** 2,748 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 6/1/1967 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 6/1/1967 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 1/1/2017 **Work Type:** Complete Reconstruction - PCC **Code:** CR-PC **Is Major M&R:** True

Last Insp. Date: 9/21/2021 **TotalSamples:** 8 **Surveyed:** 2

Conditions: PCI: 100

Inspection Comments:

Sample Number: 05 **Type:** R **Area:** 20.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>

Sample Number: 07 **Type:** R **Area:** 19.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>



Network:	LUX	Name:	Laurens County Airport						
Branch:	TL 01	Name:	TAXILANE 01	Use:	TAXILANE	Area:	46,244 SqFt		
Section:	15	of	5	From:	-	To:	-	Last Const.:	1/1/2011
Surface:	AC	Family:	SC III & IV-TW-TL-AC	Zone:		Category:		Rank:	P
Area:	18,849 SqFt	Length:	292 Ft	Width:	74 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2011	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Work Date:	1/1/2015	Work Type:	Surface Seal - Rejuvenating		Code:	SS-RE	Is Major M&R:	False	
Work Date:	1/1/2017	Work Type:	Surface Seal - Rejuvenating		Code:	SS-RE	Is Major M&R:	False	
Last Insp. Date:	9/21/2021	TotalSamples:	4	Surveyed:	1				
Conditions:	PCI:	82							
Inspection Comments:									
Sample Number:	04	Type:	R	Area:	4435.00 SqFt	PCI:	82		
Sample Comments:									
48	L & T CR	L	127.00	Ft					
48	L & T CR	M	64.00	Ft					



Network:	LUX	Name:	Laurens County Airport						
Branch:	TL 01	Name:	TAXILANE 01	Use:	TAXILANE	Area:	46,244 SqFt		
Section:	20	of	5	From:	-	To:	-	Last Const.:	1/1/2011
Surface:	AC	Family:	SC III & IV-TW-TL-AC	Zone:		Category:		Rank:	P
Area:	15,063 SqFt	Length:	325 Ft	Width:	56 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2011	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Work Date:	1/1/2017	Work Type:	Surface Seal - Rejuvenating		Code:	SS-RE	Is Major M&R:	False	
Last Insp. Date:	9/21/2021	Total Samples:	3	Surveyed:	1				
Conditions:	PCI: 96								
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	5137.00 SqFt	PCI:	96		
Sample Comments:									
48	L & T CR	L	15.00	Ft					



Network: LUX **Name:** Laurens County Airport

Branch: TL 01 **Name:** TAXILANE 01 **Use:** TAXILANE **Area:** 46,244 SqFt

Section: 25 of 5 **From:** - **To:** - **Last Const.:** 1/1/2017

Surface: PCC **Family:** SC III & IV-PCC **Zone:** **Category:** **Rank:** P

Area: 1,063 SqFt **Length:** 28 Ft **Width:** 57 Ft

Slabs: 24 **Slab Length:** 7 Ft **Slab Width:** 6 Ft **Joint Length:** 396 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2011 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 1/1/2017 **Work Type:** Complete Reconstruction - PCC **Code:** CR-PC **Is Major M&R:** True

Last Insp. Date: 9/21/2021 **Total Samples:** 1 **Surveyed:** 1

Conditions: PCI: 100

Inspection Comments:

Sample Number: 01 **Type:** R **Area:** 27.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>



Network: LUX **Name:** Laurens County Airport

Branch: TL 01 **Name:** TAXILANE 01 **Use:** TAXILANE **Area:** 46,244 SqFt

Section: 30 of 5 **From:** - **To:** - **Last Const.:** 1/1/2017

Surface: PCC **Family:** SC III & IV-PCC **Zone:** **Category:** **Rank:** P

Area: 1,094 SqFt **Length:** 28 Ft **Width:** 53 Ft

Slabs: 24 **Slab Length:** 7 Ft **Slab Width:** 6 Ft **Joint Length:** 359 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2011 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 1/1/2017 **Work Type:** Complete Reconstruction - PCC **Code:** CR-PC **Is Major M&R:** True

Last Insp. Date: 9/21/2021 **Total Samples:** 1 **Surveyed:** 1

Conditions: PCI: 100

Inspection Comments:

Sample Number: 01 **Type:** R **Area:** 28.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>



Network: LUX **Name:** Laurens County Airport

Branch: TW A **Name:** TAXIWAY A **Use:** TAXIWAY **Area:** 133,468 SqFt

Section: 10 of 4 **From:** - **To:** - **Last Const.:** 1/1/2017

Surface: PCC **Family:** SC III & IV-PCC **Zone:** **Category:** G **Rank:** P

Area: 50,982 SqFt **Length:** 1,456 Ft **Width:** 35 Ft

Slabs: 65 **Slab Length:** 7 Ft **Slab Width:** 9 Ft **Joint Length:** 11,580 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 6/1/1992 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 6/1/1992 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 6/1/1992 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 6/1/1997 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

Work Date: 1/1/2017 **Work Type:** Overlay-PCC **Code:** OL-PCC **Is Major M&R:** True

Last Insp. Date: 9/21/2021 **TotalSamples:** 42 **Surveyed:** 9

Conditions: PCI: 99

Inspection Comments:

Sample Number: 03 **Type:** R **Area:** 20.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>

Sample Number: 07 **Type:** R **Area:** 20.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>

Sample Number: 11 **Type:** R **Area:** 20.00 Slabs **PCI:** 98

Sample Comments:

65 JT SEAL DMG L 20.00 Slabs

Sample Number: 15 **Type:** R **Area:** 20.00 Slabs **PCI:** 98

Sample Comments:

65 JT SEAL DMG L 20.00 Slabs

Sample Number: 20 **Type:** R **Area:** 20.00 Slabs **PCI:** 98

Sample Comments:

65 JT SEAL DMG L 20.00 Slabs

Sample Number: 24 **Type:** R **Area:** 20.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>

Sample Number: 28 **Type:** R **Area:** 20.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>

Sample Number: 32 **Type:** R **Area:** 20.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>

Sample Number: 39 **Type:** R **Area:** 20.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>

Network: LUX **Name:** Laurens County Airport

Branch: TW A **Name:** TAXIWAY A **Use:** TAXIWAY **Area:** 133,468 SqFt

Section: 20 of 4 **From:** - **To:** - **Last Const.:** 1/1/2013

Surface: PCC **Family:** SC III & IV-PCC **Zone:** **Category:** G **Rank:** S

Area: 19,193 SqFt **Length:** 548 Ft **Width:** 35 Ft

Slabs: 131 **Slab Length:** 12 Ft **Slab Width:** 12 Ft **Joint Length:** 2,591 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 6/1/1992 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 6/1/1992 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 6/1/1992 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 6/1/1997 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

Work Date: 1/1/2013 **Work Type:** Complete Reconstruction - PCC **Code:** CR-PC **Is Major M&R:** True

Last Insp. Date: 9/21/2021 **TotalSamples:** 5 **Surveyed:** 1

Conditions: PCI: 99

Inspection Comments:

Sample Number: 02 **Type:** R **Area:** 27.00 Slabs **PCI:** 99

Sample Comments:

73 SHRINKAGE CR N 1.00 Slabs



Network: LUX **Name:** Laurens County Airport

Branch: TW A **Name:** TAXIWAY A **Use:** TAXIWAY **Area:** 133,468 SqFt

Section: 25 of 4 **From:** - **To:** - **Last Const.:** 9/1/2006

Surface: AC **Family:** SC III & IV-TW-TL-AC **Zone:** **Category:** **Rank:** P

Area: 54,180 SqFt **Length:** 1,650 Ft **Width:** 35 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 9/1/2006 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 1/1/2013 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Work Date: 1/1/2019 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Work Date: 1/1/2019 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

Last Insp. Date: 9/21/2021 **TotalSamples:** 11 **Surveyed:** 3

Conditions: PCI: 79

Inspection Comments:

Sample Number: 03 **Type:** R **Area:** 5250.00 SqFt **PCI:** 81

Sample Comments:

48 L & T CR L 389.00 Ft

Sample Number: 07 **Type:** R **Area:** 5250.00 SqFt **PCI:** 74

Sample Comments:

48 L & T CR L 664.00 Ft

Sample Number: 11 **Type:** R **Area:** 5250.00 SqFt **PCI:** 84

Sample Comments:

48 L & T CR L 304.00 Ft



Network: LUX **Name:** Laurens County Airport

Branch: TW A **Name:** TAXIWAY A **Use:** TAXIWAY **Area:** 133,468 SqFt

Section: 30 of 4 **From:** - **To:** - **Last Const.:** 1/1/2013

Surface: PCC **Family:** SC III & IV-PCC **Zone:** **Category:** G **Rank:** S

Area: 9,113 SqFt **Length:** 260 Ft **Width:** 35 Ft

Slabs: 358 **Slab Length:** 7 Ft **Slab Width:** 7 Ft **Joint Length:** 2,218 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 6/1/1992 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 6/1/1992 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 6/1/1992 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 6/1/1997 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

Work Date: 1/1/2013 **Work Type:** Complete Reconstruction - PCC **Code:** CR-PC **Is Major M&R:** True

Last Insp. Date: 9/21/2021 **TotalSamples:** 7 **Surveyed:** 2

Conditions: PCI: 99

Inspection Comments:

Sample Number: 03 **Type:** R **Area:** 25.00 Slabs **PCI:** 98


Sample Comments:

65 JT SEAL DMG L 25.00 Slabs

Sample Number: 06 **Type:** R **Area:** 25.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>



Network: LUX **Name:** Laurens County Airport

Branch: TW A1 **Name:** TAXIWAY A1 **Use:** TAXIWAY **Area:** 8,124 SqFt

Section: 10 of 2 **From:** - **To:** - **Last Const.:** 1/1/2017

Surface: PCC **Family:** SC III & IV-PCC **Zone:** **Category:** G **Rank:** S

Area: 4,017 SqFt **Length:** 92 Ft **Width:** 35 Ft

Slabs: 96 **Slab Length:** 6 Ft **Slab Width:** 7 Ft **Joint Length:** 870 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 6/1/1992 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 6/1/1992 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 6/1/1992 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 6/1/1997 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

Work Date: 1/1/2017 **Work Type:** Overlay-PCC **Code:** OL-PCC **Is Major M&R:** True

Last Insp. Date: 9/21/2021 **TotalSamples:** 4 **Surveyed:** 1

Conditions: PCI: 100

Inspection Comments:

Sample Number: 02 **Type:** R **Area:** 27.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>



Network:	LUX	Name:	Laurens County Airport				
Branch:	TW A1	Name:	TAXIWAY A1	Use:	TAXIWAY	Area:	8,124 SqFt
Section:	15	of 2	From:	-	To:	-	Last Const.: 1/1/2013
Surface:	PCC	Family:	SC III & IV-PCC	Zone:		Category:	
Area:	4,107 SqFt	Length:	94 Ft	Width:	50 Ft	Rank:	P
Slabs:	114	Slab Length:	6 Ft	Slab Width:	6 Ft	Joint Length:	1,423 Ft
Shoulder:		Street Type:		Grade:	0	Lanes:	0
Section Comments:							
Work Date:	1/1/2013	Work Type:	New Construction - Initial	Code:	NU-IN	Is Major M&R:	True
Last Insp. Date:	9/21/2021	TotalSamples:	4	Surveyed:	1		
Conditions:	PCI: 100						
Inspection Comments:							
Sample Number:	03	Type:	R	Area:	24.00 Slabs	PCI:	100
Sample Comments:							
<No Distress>							



Network: LUX **Name:** Laurens County Airport

Branch: TW A2 **Name:** TAXIWAY A2 **Use:** TAXIWAY **Area:** 10,457 SqFt

Section: 10 of 1 **From:** - **To:** - **Last Const.:** 1/1/2013

Surface: PCC **Family:** SC III & IV-PCC **Zone:** **Category:** G **Rank:** S

Area: 10,457 SqFt **Length:** 185 Ft **Width:** 40 Ft

Slabs: 248 **Slab Length:** 6 Ft **Slab Width:** 6 Ft **Joint Length:** 2,052 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 6/1/1992 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 6/1/1992 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 6/1/1992 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 6/1/1997 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

Work Date: 1/1/2013 **Work Type:** Complete Reconstruction - PCC **Code:** CR-PC **Is Major M&R:** True

Last Insp. Date: 9/21/2021 **TotalSamples:** 12 **Surveyed:** 3

Conditions: PCI: 96

Inspection Comments:

Sample Number: 04 **Type:** R **Area:** 24.00 Slabs **PCI:** 91

Sample Comments:

65 JT SEAL DMG L 24.00 Slabs
71 FAULTING L 2.00 Slabs

Sample Number: 07 **Type:** R **Area:** 18.00 Slabs **PCI:** 98


Sample Comments:

65 JT SEAL DMG L 18.00 Slabs

Sample Number: 11 **Type:** R **Area:** 24.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>



Network: LUX **Name:** Laurens County Airport

Branch: TW A3 **Name:** TAXIWAY A3 **Use:** TAXIWAY **Area:** 9,372 SqFt

Section: 10 of 1 **From:** - **To:** - **Last Const.:** 1/1/2013

Surface: PCC **Family:** SC III & IV-PCC **Zone:** **Category:** G **Rank:** S

Area: 9,372 SqFt **Length:** 150 Ft **Width:** 40 Ft

Slabs: 191 **Slab Length:** 7 Ft **Slab Width:** 7 Ft **Joint Length:** 1,524 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 6/1/1992 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 6/1/1992 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 6/1/1992 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 6/1/1997 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

Work Date: 1/1/2013 **Work Type:** Complete Reconstruction - PCC **Code:** CR-PC **Is Major M&R:** True

Last Insp. Date: 9/21/2021 **TotalSamples:** 10 **Surveyed:** 2

Conditions: PCI: 98

Inspection Comments:

Sample Number: 05 **Type:** R **Area:** 24.00 Slabs **PCI:** 98


Sample Comments:

65 JT SEAL DMG L 24.00 Slabs

Sample Number: 09 **Type:** R **Area:** 25.00 Slabs **PCI:** 98

Sample Comments:

65 JT SEAL DMG L 25.00 Slabs



Network: LUX **Name:** Laurens County Airport

Branch: TW A4 **Name:** TAXIWAY A4 **Use:** TAXIWAY **Area:** 9,698 SqFt

Section: 10 of 1 **From:** - **To:** - **Last Const.:** 1/1/2013

Surface: PCC **Family:** SC III & IV-PCC **Zone:** **Category:** G **Rank:** P

Area: 9,698 SqFt **Length:** 240 Ft **Width:** 35 Ft

Slabs: 185 **Slab Length:** 7 Ft **Slab Width:** 7 Ft **Joint Length:** 2,045 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 6/1/1992 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 6/1/1992 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 6/1/1992 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 6/1/1997 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

Work Date: 1/1/2013 **Work Type:** Complete Reconstruction - PCC **Code:** CR-PC **Is Major M&R:** True

Last Insp. Date: 9/21/2021 **TotalSamples:** 8 **Surveyed:** 2

Conditions: PCI: 100

Inspection Comments:

Sample Number: 03 **Type:** R **Area:** 25.00 Slabs **PCI:** 100


Sample Comments:

<No Distress>

Sample Number: 07 **Type:** R **Area:** 25.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>



Network:	LUX	Name:	Laurens County Airport						
Branch:	TW RU 8	Name:	TURNAROUND RW 8	Use:	TAXIWAY	Area:	6,075 SqFt		
Section:	10	of	1	From:	-	To:	-	Last Const.:	1/1/2017
Surface:	PCC	Family:	SC III & IV-PCC	Zone:		Category:	G	Rank:	S
Area:	6,075 SqFt	Length:	127 Ft	Width:	52 Ft				
Slabs:	99	Slab Length:	7 Ft	Slab Width:	9 Ft	Joint Length:	1,515 Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	6/1/1992	Work Type:	Surface Course - AC (Layer Construct)		Code:	SU-AC	Is Major M&R:	False	
Work Date:	6/1/1992	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R:	False	
Work Date:	6/1/1992	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Work Date:	1/1/2017	Work Type:	Overlay-PCC		Code:	OL-PCC	Is Major M&R:	True	
Last Insp. Date:	9/21/2021	TotalSamples:	4		Surveyed:	1			
Conditions:	PCI: 99								
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	32.00 Slabs	PCI:	99		
Sample Comments:									
66	SMALL PATCH	L	1.00 Slabs						





Kimley»»Horn