



SOUTH CAROLINA AERONAUTICS COMMISSION

STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

 SMS - Sumter Airport



Kimley»»Horn

2023



Contents

Overview	3
Introduction.....	3
System Inventory.....	4
Functional Evaluation	7
Pavement Condition Index.....	7
Critical PCI.....	8
PCI Results	8
Pavement Condition Forecast.....	11
M&R Overview	14
Localized Maintenance and Repair.....	15
Major Rehabilitation Needs.....	15
Appendix A – Exhibits.....	A-1
Appendix B – Analysis Tables.....	B-1
Appendix C – Maintenance and Rehabilitation Tables	C-1
Appendix D – PCI Results Summary	D-1
Appendix E – Re-Inspection Report.....	E-1

Overview

Introduction

For over 20 years, the South Carolina Aeronautics Commission (SCAC) has implemented an airfield pavement management program for publicly owned South Carolina airports. As part of their grant assurances federally obligated airports are required to perform detailed inspections as outlined in the FAA Advisory Circular 150/5380-7B – “Airport Pavement Management Program (PMP)”. All inspections performed within this program follow the guidance documented within the ASTM D5340-20 – “Standard Test Method for Airport Pavement Condition Surveys”. This is an objective process to assess the pavement condition in a consistent and repeatable manner.

Due to ever-changing pavement conditions, the FAA AC 150/5380-7B recommends the PMP be updated every 3 years. The overall pavement conditions are analyzed using the ASTM PCI methodology. It provides decision makers with a comparison of pavement facilities and a relative indication of their required maintenance or level of repair to aid in project prioritization. A detailed explanation of the SCAC airfield pavement management program process and pavement management terminology can be found in the SCAC Statewide Report.

Project elements performed for this 2021-2024 program update include the development and updates of pavement inventories, documentation of pavement conditions, performance modeling, and maintenance and rehabilitation (M&R) needs for all participating airports. This report summarizes the results of the SCAC pavement program update at Sumter Airport (SMS).

Figure 1 – Airport Layout



System Inventory

The pavements at Sumter Airport (SMS) include approximately 1.3 million square feet of airfield pavements consisting of runways, taxiways, taxilanes and aprons. Per the guidance in the ASTM D5340-20, all pavements were divided and subdivided into pavement management units (Network, Branch, Section, Sample). The divisions are documented in the **Network Definition Exhibit** providing the name and location of each branch, section, and sample.


Each pavement update included a review of documentation of any maintenance and major rehabilitation related activities performed on the airfield pavements. The following table summarizes the projects that have occurred since the previous inspection.


Table 1 - Recent Airfield Pavement Construction

Construction Year	Location	Work Type / Pavement Section
2018	AP 01, RW 5, TL 01, TW A, TW A1, TWA2, TWA4, TWA5, TW A6	Surface Seal - Rejuvenating
2023	AP 01	Reconstruction - PCC 8" P-501, 6" P-209, P-152

The following figure summarizes the inventory items at Sumter Airport (SMS). The **Estimated Age Exhibit** provides the last major work date for each pavement section based on the collected documentation.

Figure 2 – System Inventory Summary






LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID
- RW 13-10 PAVEMENT BRANCH ID: SECTION ID
- AAC NUMBER OF SAMPLE UNITS IN SECTION
- 5 NUMBER OF SAMPLE UNITS TO BE INSPECTED
- PCC PAVEMENT SURFACE TYPE
- RW 13-20 SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE ESTIMATED AGE EXHIBIT FOR CONSTRUCTION DATES.
- AAC
- 0 OF 5
- 100 INSPECTED SAMPLE UNITS.

TOTAL SAMPLES INSPECTED = 62
AC: 58 PCC: 4

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





Legend

- Estimated Age at Inspection**
- 0-5 Years
 - 6-10 Years
 - 11-15 Years
 - 16-20 Years
 - > 20 Years
- ┌─── BRANCH IDENTIFIER
└─── SECTION IDENTIFIER
TWA:20 | 1985
└─── LAST MAJOR WORK DATE



Functional Evaluation

Pavement Condition Index

A Pavement Condition Index (PCI) survey is the primary means of obtaining and recording pavement distress data. In adherence to FAA Advisory Circular 150/5380-7B, the SCAC Airfield Pavement Management System (APMS) Update utilizes the PCI survey methodology to collect pavement distress data and analyze the condition. This method uses a visual statistical sampling of pavements for recording primary distress types, associated severities, and quantities as defined by the ASTM D5340-20.

Visual condition data collected during the PCI survey is analyzed and used to calculate the current PCI for each inspected sample unit and section. The PCI is a value ranging from 0 to 100, which indicates the apparent structural integrity and surface operational condition of the pavement, with “100” indicating a pavement in new condition and “0” indicating a failed pavement section. Pavement Condition Ratings are associated with PCI categories that range from “Failed” to “Good”. Representative photos of varying Pavement Condition Ratings are displayed in **Figure 3**.

Figure 3 – Representation of Pavement Condition Index Values



Poor/Failed Pavement

Pavements that are Poor to Failed require significant and costly interventions such as reconstruction to restore the pavement to operational service.




Fair Pavement

Pavements with a Fair condition rating typically require rehabilitation, or maintenance activities if rehabilitation cannot be immediately performed.



Good/New Pavement

Pavements classified as Good require either no treatment or would benefit from the application of preventive maintenance activities such as crack sealing.




Critical PCI

From a pavement management perspective, one of the most valuable aspects of the PCI methodology is the ability to save money by effectively prioritizing the rehabilitation of pavement assets. Critical PCI refers to the condition beyond which the rate of pavement deterioration and the cost of applying a treatment increases significantly. In other words, it is the condition at which maintenance may no longer be cost effective and major rehabilitation should be considered. Based on the 2019 FAA Order 5100.38D Change 1 Airport Improvement Program Handbook, the FAA has established recommended PCI thresholds for pavement M&R. Accordingly, **the Critical PCI for all SCAC airfield pavements is defined at 70.**

PCI Results


The PCI survey for Sumter Airport (SMS) was performed in January 2023. **The overall area-weighted average PCI value of the network was 80**, representing a condition rating of **Satisfactory**. Approximately 88% of inspected pavements are in Good or Satisfactory condition, 12% of inspected pavements are in Fair condition, and no pavements are in Poor or worse condition as summarized in **Figure 4**.

Figure 4 – Overall Network PCI Results



The area-weighted average PCIs by branch use are summarized in the figure below. The current PCIs at a section-level are displayed graphically on the **2023 Airfield Pavement Condition Index Exhibit** and are summarized in **Table 2**.

Figure 5 – Area Weighted Average Pavement Condition






STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

SMS - Sumter Airport

Table 2 – Current Pavement Condition Index Summary - Section

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI% Climate	PCI% Load	PCI% Other
SMS	AP 01	Apron	10	166,385	PCC	100	Good	0	0	0
SMS	AP 01	Apron	25	61,104	AAC	69	Fair	96	0	4
SMS	AP 01	Apron	30	70,755	PCC	97	Good	0	48	52
SMS	AP 01	Apron	40	31,530	AC	79	Satisfactory	100	0	0
SMS	AP 01	Apron	50	16,612	AC	95	Good	100	0	0
SMS	RW 5	Runway	10	480,000	AAC	77	Satisfactory	100	0	0
SMS	RW 5	Runway	20	70,000	AAC	73	Satisfactory	100	0	0
SMS	TL01	Taxilane	10	55,984	AAC	71	Satisfactory	81	14	5
SMS	TW A	Taxiway	10	34,889	AC	78	Satisfactory	100	0	0
SMS	TW A	Taxiway	20	10,259	AAC	75	Satisfactory	100	0	0
SMS	TW A	Taxiway	30	25,285	AAC	74	Satisfactory	96	0	4
SMS	TW A	Taxiway	40	99,506	AAC	70	Fair	100	0	0
SMS	TW A	Taxiway	50	36,093	AAC	76	Satisfactory	100	0	0
SMS	TW A1	Taxiway	10	15,117	AAC	78	Satisfactory	100	0	0
SMS	TW A2	Taxiway	10	19,527	AAC	76	Satisfactory	100	0	0
SMS	TW A3	Taxiway	10	36,699	AAC	71	Satisfactory	93	0	7
SMS	TW A4	Taxiway	10	31,651	AAC	73	Satisfactory	95	0	5
SMS	TW A5	Taxiway	10	22,826	AAC	74	Satisfactory	97	0	3
SMS	TW A6	Taxiway	10	17,699	AC	83	Satisfactory	100	0	0

*For further PCI details and photos see Appendix D – Detailed PCI Results.



Legend

2023 Pavement Condition Index

- PCI 86-100 Good
- PCI 71-85 Satisfactory
- PCI 56-70 Fair
- PCI 41-55 Poor
- PCI 26-40 Very Poor
- PCI 11-25 Serious
- PCI 0-10 Failed


— BRANCH IDENTIFIER
 — SECTION IDENTIFIER
TWA:20 (84)
 — PCI



Pavement Condition Forecast

A primary objective of this APMS is to estimate the future condition of each individual pavement section. PAVER™ was utilized to develop prediction curves and determine typical deterioration rates that are then used to forecast a future PCI value. This value will assist decision makers in determining at what point in time certain pavement sections will require rehabilitation. The figure below shows the current and 5-year area-weighted forecasted pavement condition distribution of each functional use (Runway, Taxiway, Taxilane, Apron) found at the Airport. The forecasted 5-year PCIs at a section-level are displayed graphically on the **2028 Forecasted Airfield Pavement Condition Index Exhibit** and are summarized in **Table 3**. All forecasts presented assume that no maintenance or rehabilitation is performed within the 5-year analysis period. **Figure 6** displays the forecasted pavement conditions at the branch-level for SMS.

Figure 6 – Forecasted 5-Year PCI by Branch Use



All condition forecasts are based on historical observations and analysis of South Carolina airfield pavements. The forecasts are not a guarantee of future PCI: - rather, they are a planning tool to aid in the timing of maintenance and rehabilitation activities.




STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

SMS - Sumter Airport

Table 3 – Forecast (2024-2028) Section Pavement Condition Index - Section

Network ID	Branch ID	Section ID	Current PCI	Forecasted PCI				
				2024	2025	2026	2027	2028
SMS	AP 01	10	100	100	99	99	98	97
SMS	AP 01	25	69	68	66	65	64	63
SMS	AP 01	30	97	96	96	95	95	94
SMS	AP 01	40	79	77	76	74	72	71
SMS	AP 01	50	95	93	91	89	87	85
SMS	RW 5	10	77	76	75	74	73	72
SMS	RW 5	20	73	72	71	70	69	68
SMS	TL 01	10	71	70	68	67	65	64
SMS	TW A	10	78	77	75	74	72	71
SMS	TW A	20	75	74	72	71	69	68
SMS	TW A	30	74	73	71	70	68	67
SMS	TW A	40	70	69	67	66	64	63
SMS	TW A	50	76	75	73	72	70	69
SMS	TW A1	10	78	77	75	74	72	71
SMS	TW A2	10	76	75	73	72	70	69
SMS	TW A3	10	71	70	68	67	65	64
SMS	TW A4	10	73	72	70	69	67	66
SMS	TW A5	10	74	73	71	70	68	67
SMS	TW A6	10	83	82	80	79	77	76



Legend

2028 Forecasted Pavement Condition Index

- PCI 86-100 Good
- PCI 71-85 Satisfactory
- PCI 56-70 Fair
- PCI 41-55 Poor
- PCI 26-40 Very Poor
- PCI 11-25 Serious
- PCI 0-10 Failed

— BRANCH IDENTIFIER
 — SECTION IDENTIFIER
TWA:20 (84)
 — FORECASTED PCI




M&R Overview

An analysis was performed to assess the pavement maintenance and rehabilitation (M&R) needs at SMS over a 5-year period. The analysis compared the forecasted condition of each pavement section to the Critical PCI threshold to develop a resultant recommendation and associated cost for each year of the 5-year plan. The M&R analysis should enable responsible parties to do the following:

- ➔ **Maintain** existing airport infrastructure at an acceptable condition
- ➔ Make timely and cost-effective **decisions** to appropriately allocate funding
- ➔ **Apply** global maintenance, localized maintenance, and major M&R activities in a timely manner to maintain an acceptable operational condition of a pavement network.

M&R planning considers various methods of repair to address the cause of the problem rather than just treating the symptom. As pavements deteriorate, repair costs can increase significantly. Once pavements have deteriorated below a certain condition threshold (the Critical PCI value), the pavement benefits more from substantial rehabilitation in lieu of maintenance activities. The figure below illustrates how the cost of pavement repairs can exponentially increase if M&R activities are delayed.

Figure 7 – Pavement Life and the Effect of Treatments



Localized Maintenance and Repair

Localized maintenance is best used as a preservation measure and is applied to slow the rate of deterioration. These activities typically include crack sealing and patching. Localized maintenance differs from major rehabilitation in that it is applied based on the distresses observed rather than based on a PCI value. Treatments are selected based on the appropriate corrective measure for a given distress type and severity level. Localized maintenance applied on pavements with PCIs above the Critical PCI of 70 is known as Preventive Localized Maintenance, while Stopgap Localized Maintenance is typically applied to pavement sections that are at or below the Critical PCI value as a temporary repair due to safety concerns. The current localized maintenance needs are summarized in the table below.

Table 4 – Localized Maintenance Summary by Policy Type

Localized Maintenance Category	Localized Work Type	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
Localized Preventive Maintenance	AC Crack Sealing Narrow	40,061	LF	\$ 140,310
	Surface Seal	241,440	SF	\$ 398,450
	AC Full-Depth Patching	728	SF	\$ 20,900
	PCC Crack Sealing	59	LF	\$ 420
	PCC Partial-Depth Patching	11	SF	\$ 960
Localized Preventive Maintenance Total =				\$ 561,040
Localized Stopgap Maintenance	Surface Seal	29,965	SF	\$ 49,450
Localized Stopgap Maintenance Total =				\$ 49,450
Planning-Level Localized M&R Needs =				\$ 610,490

Major Rehabilitation Needs

Major rehabilitation needs are identified by analyzing the Airport’s pavement condition in relationship to the Critical PCI value, density of load-related distresses, and major rehabilitation policies, assuming there are no budget constraints. The needs analysis is performed over a 5-year analysis period. Major rehabilitation is divided into two policy categories:


- ➔ **Intermediate Major Rehabilitation (PCI 56 to 70)** –
 - **AC:** Milling of the upper surface course and replacing with new AC with isolated areas of full-depth reconstruction
 - **PCC:** Combination of crack sealing, joint seal replacement, limited patching, and slab replacement
- ➔ **Full-Depth Reconstruction (PCI 0 to 55)** – Removal and replacement of the existing pavement section down to the subgrade


The 5-year major rehabilitation needs analysis at SMS results in a total 5-year cost of \$5.62M. The **5-Year Major Rehabilitation Needs Exhibit** graphically depicts the major rehabilitation needs at a section-level which are also summarized in **Table 5** with rounded costs. Annual needs are displayed graphically in **Figure 8**.

Table 5 – 5-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2024	SMS	AP 01	25	AAC	61,104	68	AC Rehabilitation	\$ 703,000
2024	SMS	TL01	10	AAC	55,984	70	AC Rehabilitation	\$ 644,000
2024	SMS	TW A	40	AAC	99,506	69	AC Rehabilitation	\$ 1,145,000
2024	SMS	TW A3	10	AAC	36,699	70	AC Rehabilitation	\$ 423,000
2026	SMS	TW A	30	AAC	25,285	70	AC Rehabilitation	\$ 309,000
2026	SMS	TW A4	10	AAC	31,651	69	AC Rehabilitation	\$ 387,000
2026	SMS	TW A5	10	AAC	22,826	70	AC Rehabilitation	\$ 279,000
2027	SMS	RW 5	20	AAC	70,000	69	AC Rehabilitation	\$ 880,000
2027	SMS	TW A	20	AAC	10,259	69	AC Rehabilitation	\$ 129,000
2028	SMS	TW A	50	AAC	36,093	69	AC Rehabilitation	\$ 468,000
2028	SMS	TW A2	10	AAC	19,527	69	AC Rehabilitation	\$ 253,000
Total 5-Year Major Rehabilitation Needs =								\$ 5,620,000

Figure 8 – 5-Year Major Rehabilitation Needs by Program Year






Legend

5-Year Major Rehabilitation Needs

-  Year 1 Reconstruction Needs
-  Year 1 Rehabilitation Needs
-  Year 2 Rehabilitation Needs
-  Year 3 Rehabilitation Needs
-  Year 4 Rehabilitation Needs
-  Year 5 Rehabilitation Needs



THIS EXHIBIT REPRESENTS NEEDS SOLEY BASED ON CURRENT AND FORECASTED CONDITIONS FURTHER PRIORITIZATION AND CONSIDERATIONS SHOULD BE MADE BEYOND THIS STUDY.




SECTION I

Appendices





Appendix A – Exhibits




LEGEND

- RW 13-31 TYPICAL RUNWAY BRANCH ID
- TW A TYPICAL TAXIWAY BRANCH ID
- AP S TYPICAL APRON BRANCH ID
- RW 13-10 PAVEMENT BRANCH ID: SECTION ID
AAC 5 of 15 NUMBER OF SAMPLE UNITS IN SECTION
10 NUMBER OF SAMPLE UNITS TO BE INSPECTED
PCC PAVEMENT SURFACE TYPE
- RW 13-20 SECTION NOT INSPECTED DUE TO RECENT CONSTRUCTION. SEE ESTIMATED AGE EXHIBIT FOR CONSTRUCTION DATES.
- AAC 0 of 5
- 100 INSPECTED SAMPLE UNITS.

TOTAL SAMPLES INSPECTED = 62
AC: 58 PCC: 4

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.






Legend

2023 Pavement Condition Index

- PCI 86-100 Good
- PCI 71-85 Satisfactory
- PCI 56-70 Fair
- PCI 41-55 Poor
- PCI 26-40 Very Poor
- PCI 11-25 Serious
- PCI 0-10 Failed

— BRANCH IDENTIFIER
— SECTION IDENTIFIER
TWA:20 (84)
— PCI






Legend

2028 Forecasted Pavement Condition Index

- PCI 86-100 Good
- PCI 71-85 Satisfactory
- PCI 56-70 Fair
- PCI 41-55 Poor
- PCI 26-40 Very Poor
- PCI 11-25 Serious
- PCI 0-10 Failed

— BRANCH IDENTIFIER
 — SECTION IDENTIFIER
TWA:20 (84)
 — FORECASTED PCI






Legend

5-Year Major Rehabilitation Needs

- Year 1 Reconstruction Needs
- Year 1 Rehabilitation Needs
- Year 2 Rehabilitation Needs
- Year 3 Rehabilitation Needs
- Year 4 Rehabilitation Needs
- Year 5 Rehabilitation Needs



THIS EXHIBIT REPRESENTS NEEDS SOLEY BASED ON CURRENT AND FORECASTED CONDITIONS FURTHER PRIORITIZATION AND CONSIDERATIONS SHOULD BE MADE BEYOND THIS STUDY.





Appendix B – Analysis Tables



STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

SMS - Sumter Airport

Table B1 – System Inventory Data - Section

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
SMS	AP 01	Apron	10	166,385	PCC	2/1/2023
SMS	AP 01	Apron	25	61,104	AAC	4/1/2003
SMS	AP 01	Apron	30	70,755	PCC	1/1/2015
SMS	AP 01	Apron	40	31,530	AC	1/1/2000
SMS	AP 01	Apron	50	16,612	AC	7/1/2016
SMS	RW 5	Runway	10	480,000	AAC	1/1/2006
SMS	RW 5	Runway	20	70,000	AAC	1/1/2006
SMS	TL01	Taxilane	10	55,984	AAC	6/1/2003
SMS	TW A	Taxiway	10	34,889	AC	8/1/2007
SMS	TW A	Taxiway	20	10,259	AAC	4/1/2003
SMS	TW A	Taxiway	30	25,285	AAC	4/1/2003
SMS	TW A	Taxiway	40	99,506	AAC	4/1/2003
SMS	TW A	Taxiway	50	36,093	AAC	4/1/2003
SMS	TW A1	Taxiway	10	15,117	AAC	4/1/2003
SMS	TW A2	Taxiway	10	19,527	AAC	4/1/2003
SMS	TW A3	Taxiway	10	36,699	AAC	4/1/2003
SMS	TW A4	Taxiway	10	31,651	AAC	4/1/2003
SMS	TW A5	Taxiway	10	22,826	AAC	4/1/2003
SMS	TW A6	Taxiway	10	17,699	AC	8/1/2007

Table B2 – Current Pavement Condition Index Summary - Branch

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Area-Weighted Avg PCI	Condition Rating
AP 01	Apron	5	346,386	92	Good
RW 5	Runway	2	550,000	76	Satisfactory
TL01	Taxilane	1	55,984	71	Satisfactory
TW A	Taxiway	5	206,032	73	Satisfactory
TW A1	Taxiway	1	15,117	78	Satisfactory
TW A2	Taxiway	1	19,527	76	Satisfactory
TW A3	Taxiway	1	36,699	71	Satisfactory
TW A4	Taxiway	1	31,651	73	Satisfactory
TW A5	Taxiway	1	22,826	74	Satisfactory
TW A6	Taxiway	1	17,699	83	Satisfactory

Table B3 – Current (2023) Pavement Condition Index Summary - Section

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
SMS	AP 01	Apron	10	166,385	PCC	100	Good	0	0	0	0	0
SMS	AP 01	Apron	25	61,104	AAC	69	Fair	96	0	4	3	11
SMS	AP 01	Apron	30	70,755	PCC	97	Good	0	48	52	4	17
SMS	AP 01	Apron	40	31,530	AC	79	Satisfactory	100	0	0	2	6
SMS	AP 01	Apron	50	16,612	AC	95	Good	100	0	0	1	4
SMS	RW 5	Runway	10	480,000	AAC	77	Satisfactory	100	0	0	20	96
SMS	RW 5	Runway	20	70,000	AAC	73	Satisfactory	100	0	0	4	14
SMS	TL 01	Taxilane	10	55,984	AAC	71	Satisfactory	81	14	5	4	11
SMS	TW A	Taxiway	10	34,889	AC	78	Satisfactory	100	0	0	2	9
SMS	TW A	Taxiway	20	10,259	AAC	75	Satisfactory	100	0	0	1	2
SMS	TW A	Taxiway	30	25,285	AAC	74	Satisfactory	96	0	4	2	5
SMS	TW A	Taxiway	40	99,506	AAC	70	Fair	100	0	0	5	25
SMS	TW A	Taxiway	50	36,093	AAC	76	Satisfactory	100	0	0	3	10
SMS	TW A1	Taxiway	10	15,117	AAC	78	Satisfactory	100	0	0	1	4
SMS	TW A2	Taxiway	10	19,527	AAC	76	Satisfactory	100	0	0	2	4
SMS	TW A3	Taxiway	10	36,699	AAC	71	Satisfactory	93	0	7	3	8
SMS	TW A4	Taxiway	10	31,651	AAC	73	Satisfactory	95	0	5	2	7
SMS	TW A5	Taxiway	10	22,826	AAC	74	Satisfactory	97	0	3	2	5
SMS	TW A6	Taxiway	10	17,699	AC	83	Satisfactory	100	0	0	1	4



STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

SMS - Sumter Airport

Table B4 –Forecasted (2024-2028) Pavement Condition Index Summary - Section

Network ID	Branch ID	Section ID	Current PCI	Forecasted PCI				
				2024	2025	2026	2027	2028
SMS	AP 01	10	100	100	99	99	98	97
SMS	AP 01	25	69	68	66	65	64	63
SMS	AP 01	30	97	96	96	95	95	94
SMS	AP 01	40	79	77	76	74	72	71
SMS	AP 01	50	95	93	91	89	87	85
SMS	RW 5	10	77	76	75	74	73	72
SMS	RW 5	20	73	72	71	70	69	68
SMS	TL 01	10	71	70	68	67	65	64
SMS	TW A	10	78	77	75	74	72	71
SMS	TW A	20	75	74	72	71	69	68
SMS	TW A	30	74	73	71	70	68	67
SMS	TW A	40	70	69	67	66	64	63
SMS	TW A	50	76	75	73	72	70	69
SMS	TW A1	10	78	77	75	74	72	71
SMS	TW A2	10	76	75	73	72	70	69
SMS	TW A3	10	71	70	68	67	65	64
SMS	TW A4	10	73	72	70	69	67	66
SMS	TW A5	10	74	73	71	70	68	67
SMS	TW A6	10	83	82	80	79	77	76



Appendix C – Maintenance and Rehabilitation Tables

Table C1 – Localized Maintenance Summary by Policy Type

Localized Maintenance Category	Localized Work Type	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
Localized Preventive Maintenance	AC Crack Sealing Narrow	40,061	LF	\$ 140,310
	Surface Seal	241,440	SF	\$ 398,450
	AC Full-Depth Patching	728	SF	\$ 20,900
	PCC Crack Sealing	59	LF	\$ 420
	PCC Partial-Depth Patching	11	SF	\$ 960
Localized Preventive Maintenance Total =				\$ 561,040
Localized Stopgap Maintenance	Surface Seal	29,965	SF	\$ 49,450
Localized Stopgap Maintenance Total =				\$ 49,450
Planning-Level Localized M&R Needs =				\$ 610,490

Table C2 – Section – Level Year 1 Localized Maintenance Planning Cost Summary

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
SMS	AP 01	10	166,385	100	100	\$ -
SMS	AP 01	25	61,104	69	73	\$ 24,820
SMS	AP 01	30	70,755	97	98	\$ 1,370
SMS	AP 01	40	31,530	79	85	\$ 3,270
SMS	AP 01	50	16,612	95	95	\$ -
SMS	RW 5	10	480,000	77	82	\$ 295,550
SMS	RW 5	20	70,000	73	78	\$ 42,050
SMS	TL01	10	55,984	71	76	\$ 29,670
SMS	TW A	10	34,889	78	83	\$ 10,370
SMS	TW A	20	10,259	75	85	\$ 14,080
SMS	TW A	30	25,285	74	78	\$ 22,810
SMS	TW A	40	99,506	70	75	\$ 24,630
SMS	TW A	50	36,093	76	81	\$ 15,100
SMS	TW A1	10	15,117	78	83	\$ 8,150
SMS	TW A2	10	19,527	76	81	\$ 8,160
SMS	TW A3	10	36,699	71	76	\$ 20,040
SMS	TW A4	10	31,651	73	81	\$ 45,110
SMS	TW A5	10	22,826	74	83	\$ 42,410
SMS	TW A6	10	17,699	83	87	\$ 2,790



STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

SMS - Sumter Airport

Table C3 – Localized Maintenance and Repair Needs Based on Current Distresses

Network ID	Branch ID	Section ID	Description	Severity	Distress Qty	Distress Unit	Distress Density	Policy Type	Localized Work Type	Work Qty	Work Unit	Unit Cost	Work Cost
SMS	AP 01	30	LINEAR CR	Low	4	Slabs	1.3%	Preventive	PCC Crack Sealing	59	LF	\$ 7.00	\$ 420
SMS	AP 01	30	SMALL PATCH	Medium	4	Slabs	1.3%	Preventive	PCC Partial-Depth Patching	11	SF	\$ 90.00	\$ 960
SMS	AP 01	40	L & T CR	Low	517	LF	1.6%	Preventive	AC Crack Sealing Narrow	517	LF	\$ 3.50	\$ 1,820
SMS	AP 01	40	L & T CR	Medium	416	LF	1.3%	Preventive	AC Crack Sealing Narrow	416	LF	\$ 3.50	\$ 1,460
SMS	RW 5	10	L & T CR	Low	19,949	LF	4.2%	Preventive	AC Crack Sealing Narrow	19,949	LF	\$ 3.50	\$ 69,830
SMS	RW 5	10	WEATHERING	Medium	136,800	SF	28.5%	Preventive	Surface Seal	136,800	SF	\$ 1.65	\$ 225,730
SMS	RW 5	20	L & T CR	Low	4,588	LF	6.6%	Preventive	AC Crack Sealing Narrow	4,589	LF	\$ 3.50	\$ 16,060
SMS	RW 5	20	WEATHERING	Medium	15,750	SF	22.5%	Preventive	Surface Seal	15,750	SF	\$ 1.65	\$ 25,990
SMS	TL 01	10	ALLIGATOR CR	Low	40	SF	0.1%	Preventive	AC Full-Depth Patching	70	SF	\$ 28.75	\$ 2,000
SMS	TL 01	10	L & T CR	Low	2,276	LF	4.1%	Preventive	AC Crack Sealing Narrow	2,276	LF	\$ 3.50	\$ 7,970
SMS	TL 01	10	L & T CR	Medium	229	LF	0.4%	Preventive	AC Crack Sealing Narrow	229	LF	\$ 3.50	\$ 810
SMS	TL 01	10	PATCHING	Medium	558	SF	1.0%	Preventive	AC Full-Depth Patching	658	SF	\$ 28.75	\$ 18,900
SMS	TW A	10	L & T CR	Low	1,311	LF	3.8%	Preventive	AC Crack Sealing Narrow	1,311	LF	\$ 3.50	\$ 4,590
SMS	TW A	10	RAVELING	Low	10	SF	0.0%	Preventive	Surface Seal	10	SF	\$ 1.65	\$ 20
SMS	TW A	10	WEATHERING	Medium	3,489	SF	10.0%	Preventive	Surface Seal	3,489	SF	\$ 1.65	\$ 5,760
SMS	TW A	20	L & T CR	Low	394	LF	3.8%	Preventive	AC Crack Sealing Narrow	394	LF	\$ 3.50	\$ 1,390
SMS	TW A	20	WEATHERING	Medium	7,695	SF	75.0%	Preventive	Surface Seal	7,695	SF	\$ 1.65	\$ 12,700
SMS	TW A	30	L & T CR	Low	1,451	LF	5.7%	Preventive	AC Crack Sealing Narrow	1,451	LF	\$ 3.50	\$ 5,080
SMS	TW A	30	WEATHERING	Medium	10,745	SF	42.5%	Preventive	Surface Seal	10,745	SF	\$ 1.65	\$ 17,730
SMS	TW A	50	L & T CR	Low	1,760	LF	4.9%	Preventive	AC Crack Sealing Narrow	1,760	LF	\$ 3.50	\$ 6,160
SMS	TW A	50	WEATHERING	Medium	5,414	SF	15.0%	Preventive	Surface Seal	5,414	SF	\$ 1.65	\$ 8,940
SMS	TW A1	10	L & T CR	Low	544	LF	3.6%	Preventive	AC Crack Sealing Narrow	544	LF	\$ 3.50	\$ 1,910
SMS	TW A1	10	WEATHERING	Medium	3,779	SF	25.0%	Preventive	Surface Seal	3,779	SF	\$ 1.65	\$ 6,240
SMS	TW A2	10	L & T CR	Low	949	LF	4.9%	Preventive	AC Crack Sealing Narrow	949	LF	\$ 3.50	\$ 3,330
SMS	TW A2	10	WEATHERING	Medium	2,930	SF	15.0%	Preventive	Surface Seal	2,930	SF	\$ 1.65	\$ 4,840
SMS	TW A3	10	L & T CR	Low	2,263	LF	6.2%	Preventive	AC Crack Sealing Narrow	2,263	LF	\$ 3.50	\$ 7,930
SMS	TW A3	10	WEATHERING	Medium	7,340	SF	20.0%	Preventive	Surface Seal	7,340	SF	\$ 1.65	\$ 12,120
SMS	TW A4	10	L & T CR	Low	1,697	LF	5.4%	Preventive	AC Crack Sealing Narrow	1,697	LF	\$ 3.50	\$ 5,950
SMS	TW A4	10	WEATHERING	Medium	23,738	SF	75.0%	Preventive	Surface Seal	23,739	SF	\$ 1.65	\$ 39,170
SMS	TW A5	10	L & T CR	Low	1,355	LF	5.9%	Preventive	AC Crack Sealing Narrow	1,355	LF	\$ 3.50	\$ 4,750
SMS	TW A5	10	RAVELING	Low	11	SF	0.1%	Preventive	Surface Seal	12	SF	\$ 1.65	\$ 20
SMS	TW A5	10	WEATHERING	Medium	22,815	SF	100.0%	Preventive	Surface Seal	22,814	SF	\$ 1.65	\$ 37,650
SMS	TW A6	10	L & T CR	Low	361	LF	2.0%	Preventive	AC Crack Sealing Narrow	361	LF	\$ 3.50	\$ 1,270



STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

SMS - Sumter Airport

Network ID	Branch ID	Section ID	Description	Severity	Distress Qty	Distress Unit	Distress Density	Policy Type	Localized Work Type	Work Qty	Work Unit	Unit Cost	Work Cost
SMS	TW A6	10	RAVELING	Low	43	SF	0.2%	Preventive	Surface Seal	43	SF	\$ 1.65	\$ 80
SMS	TW A6	10	WEATHERING	Medium	881	SF	5.0%	Preventive	Surface Seal	882	SF	\$ 1.65	\$ 1,460
SMS	AP 01	25	WEATHERING	Medium	15,038	SF	24.6%	Stopgap	Surface Seal	15,038	SF	\$ 1.65	\$ 24,820
SMS	TW A	40	WEATHERING	Medium	14,926	SF	15.0%	Stopgap	Surface Seal	14,926	SF	\$ 1.65	\$ 24,630



STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

SMS - Sumter Airport

Table C4 – 5-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2024	SMS	AP 01	25	AAC	61,104	68	AC Rehabilitation	\$ 703,000
2024	SMS	TL 01	10	AAC	55,984	70	AC Rehabilitation	\$ 644,000
2024	SMS	TW A	40	AAC	99,506	69	AC Rehabilitation	\$ 1,145,000
2024	SMS	TW A3	10	AAC	36,699	70	AC Rehabilitation	\$ 423,000
2026	SMS	TW A	30	AAC	25,285	70	AC Rehabilitation	\$ 309,000
2026	SMS	TW A4	10	AAC	31,651	69	AC Rehabilitation	\$ 387,000
2026	SMS	TW A5	10	AAC	22,826	70	AC Rehabilitation	\$ 279,000
2027	SMS	RW 5	20	AAC	70,000	69	AC Rehabilitation	\$ 880,000
2027	SMS	TW A	20	AAC	10,259	69	AC Rehabilitation	\$ 129,000
2028	SMS	TW A	50	AAC	36,093	69	AC Rehabilitation	\$ 468,000
2028	SMS	TW A2	10	AAC	19,527	69	AC Rehabilitation	\$ 253,000
Total 5-Year Major Rehabilitation Needs =								\$ 5,620,000



Appendix D – PCI Results Summary

RW 5

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 5	RUNWAY	2	550,000	76	Satisfactory

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	480,000	AAC	2006	2018	77	Satisfactory	100	0	0
20	70,000	AAC	2006	2018	73	Satisfactory	100	0	0



RW 5-10



RW 5-10



RW 5-20



RW 5-20


TW A

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A	TAXIWAY	5	206,032	73	Satisfactory

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	34,889	AC	2007	2018	78	Satisfactory	100	0	0
20	10,259	AAC	2003	2018	75	Satisfactory	100	0	0
30	25,285	AAC	2003	2018	74	Satisfactory	96	0	4
40	99,506	AAC	2003	2018	70	Fair	100	0	0
50	36,093	AAC	2003	2018	76	Satisfactory	100	0	0



TW A-10



TW A-20



TW A-30



TW A-40

TW A1

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A1	TAXIWAY	1	15,117	78	Satisfactory

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	15,117	AAC	2003	2018	78	Satisfactory	100	0	0



TW A1-10

TW A2

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A2	TAXIWAY	1	19,527	76	Satisfactory

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	19,527	AAC	2003	2018	76	Satisfactory	100	0	0



TW A2-10

TW A3

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A3	TAXIWAY	1	36,699	71	Satisfactory

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	36,699	AAC	2003	2018	71	Satisfactory	93	0	7




TW A3-10

TW A4

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A4	TAXIWAY	1	31,651	73	Satisfactory

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	31,651	AAC	2003	2018	73	Satisfactory	95	0	5



TW A4-10

TW A5

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A5	TAXIWAY	1	22,826	74	Satisfactory

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	22,826	AAC	2003	2018	74	Satisfactory	97	0	3



TW A5-10

TW A6

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A6	TAXIWAY	1	17,699	83	Satisfactory

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	17,699	AC	2007	2018	83	Satisfactory	100	0	0



TW A6-10

TL 01

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TL01	TAXILANE	1	55,984	71	Satisfactory

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	55,984	AAC	2003	2018	71	Satisfactory	81	14	5



TL 01-10

AP 01

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP 01	APRON	5	346,386	92	Good

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	166,385	PCC	2023	-	100	Good	0	0	0
25	61,104	AAC	2003	-	69	Fair	96	0	4
30	70,755	PCC	2015	-	97	Good	0	48	52
40	31,530	AC	2000	2018	79	Satisfactory	100	0	0
50	16,612	AC	2016	2018	95	Good	100	0	0



AP 01-25



AP 01-30



AP 01-40



AP 01-50



Appendix E – Re-Inspection Report

Re-Inspection Report

SCAC_2023

Generated Date

5/31/2023

Page 1 of 22

Network: SMS	Name: Sumter Municipal Airport	
Branch: AP 01	Name: APRON 01	Use: APRON Area: 346,386 SqFt
Section: 10 of 5	From: -	To: - Last Const.: 2/1/2023
Surface: PCC	Family: SC 234 NonRW PCC	Zone: Category: G Rank: P
Area: 166,385 SqFt	Length: 484 Ft	Width: 348 Ft
Slabs: 739	Slab Length: 15 Ft	Slab Width: 15 Ft Joint Length: 21,626 Ft
Shoulder:	Street Type:	Grade: 0 Lanes: 0

Section Comments:

Work Date: 7/1/1967	Work Type: Surface Course - AC (Layer Construct)	Code: SU-AC	Is Major M&R: False
Work Date: 7/1/1967	Work Type: Surface Treatment - Double Bitum. (Layer Construct)	Code: SU-DB	Is Major M&R: False
Work Date: 7/1/1967	Work Type: Base Course - Aggregate	Code: BA-AG	Is Major M&R: False
Work Date: 11/1/1988	Work Type: Surface Treatment - Seal Coat	Code: ST-SCT	Is Major M&R: False
Work Date: 11/1/1988	Work Type: New Construction - Initial	Code: NU-IN	Is Major M&R: True
Work Date: 11/1/1988	Work Type: Surface Course - AC (Layer Construct)	Code: LC-AC	Is Major M&R: True
Work Date: 4/1/2003	Work Type: Overlay - AC Structural	Code: OL-AS	Is Major M&R: True
Work Date: 1/1/2018	Work Type: Surface Seal - Rejuvenating	Code: SS-RE	Is Major M&R: False
Work Date: 1/31/2023	Work Type: Demolish Existing	Code: DEMO	Is Major M&R: False
Work Date: 2/1/2023	Work Type: Reconstruction - PCC	Code: RC-PC	Is Major M&R: True
Work Date: 2/1/2023	Work Type: Base Course - Aggregate	Code: BA-AG	Is Major M&R: False
Work Date: 2/2/2023	Work Type: Surface Course - PCC (Layer Construct)	Code: SU-PC	Is Major M&R: False

Last Insp. Date: 10/13/2016 **Total Samples:** 24 **Surveyed:** 5
Conditions: PCI: 73 **NOTE: *** Pre-Construction PCI *****

Inspection Comments:

Sample Number: 16	Type: R	Area: 5000.00 SqFt	PCI: 77
Sample Comments:			
48	LONGITUDINAL/TRANSVERSE L	206.00 Ft	
	CRACKING		
52	RAVELING L	150.00 SqFt	
57	WEATHERING L	4850.00 SqFt	
Sample Number: 2	Type: R	Area: 5000.00 SqFt	PCI: 67
Sample Comments:			
48	LONGITUDINAL/TRANSVERSE L	489.00 Ft	
	CRACKING		
52	RAVELING L	200.00 SqFt	
57	WEATHERING L	4800.00 SqFt	
Sample Number: 23	Type: R	Area: 4109.00 SqFt	PCI: 78
Sample Comments:			
48	LONGITUDINAL/TRANSVERSE L	157.00 Ft	
	CRACKING		
52	RAVELING L	123.00 SqFt	
57	WEATHERING L	3986.00 SqFt	
Sample Number: 5	Type: R	Area: 5000.00 SqFt	PCI: 72
Sample Comments:			
48	LONGITUDINAL/TRANSVERSE L	362.00 Ft	
	CRACKING		

52	RAVELING	L	100.00	SqFt
57	WEATHERING	L	4900.00	SqFt

Sample Number: 9 **Type:** R **Area:** 5000.00 SqFt **PCI:** 72

Sample Comments:

48	LONGITUDINAL/TRANSVERSE CRACKING	L	394.00	Ft
52	RAVELING	L	50.00	SqFt
57	WEATHERING	L	4950.00	SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: AP 01 **Name:** APRON 01 **Use:** APRON **Area:** 346,386 SqFt

Section: 25 of 5 **From:** - **To:** - **Last Const.:** 4/1/2003

Surface: AAC **Family:** SC2_AP_AC **Zone:** **Category:** G **Rank:** P

Area: 61,104 SqFt **Length:** 250 Ft **Width:** 240 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 7/1/1967 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 7/1/1967 **Work Type:** Surface Treatment - Double Bitum. (Layer Construct) **Code:** SU-DB **Is Major M&R:** False

Work Date: 7/1/1967 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 6/1/1980 **Work Type:** Surface Course - AC (Layer Construct) **Code:** LC-AC **Is Major M&R:** True

Work Date: 6/1/1980 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 4/1/2003 **Work Type:** Overlay - AC Structural **Code:** OL-AS **Is Major M&R:** True

Last Insp. Date: 1/4/2023 **TotalSamples:** 11 **Surveyed:** 3

Conditions: PCI: 69

Inspection Comments:

Sample Number: 02 **Type:** R **Area:** 6383.00 SqFt **PCI:** 64

Sample Comments:

48	L & T CR	L	789.00	Ft
57	WEATHERING	L	3191.00	SqFt
57	WEATHERING	M	3192.00	SqFt

Sample Number: 07 **Type:** R **Area:** 6100.00 SqFt **PCI:** 69

Sample Comments:

48	L & T CR	L	519.00	Ft
56	SWELLING	L	30.00	SqFt
57	WEATHERING	L	5812.00	SqFt
57	WEATHERING	M	288.00	SqFt

Sample Number: 11 **Type:** R **Area:** 4241.00 SqFt **PCI:** 77

Sample Comments:

48	L & T CR	L	172.00	Ft
57	WEATHERING	L	3605.00	SqFt
57	WEATHERING	M	636.00	SqFt

Network: SMS **Name:** Sumter Municipal Airport

Branch: AP 01 **Name:** APRON 01 **Use:** APRON **Area:** 346,386 SqFt

Section: 30 of 5 **From:** - **To:** - **Last Const.:** 1/1/2015

Surface: PCC **Family:** SC 234 NonRW PCC **Zone:** **Category:** G **Rank:** P

Area: 70,755 SqFt **Length:** 500 Ft **Width:** 150 Ft

Slabs: 314 **Slab Length:** 15 Ft **Slab Width:** 15 Ft **Joint Length:** 9,350 Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2015 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 1/2/2015 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 1/3/2015 **Work Type:** Surface Course - PCC (Layer Construct) **Code:** LC-PC **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **TotalSamples:** 17 **Surveyed:** 4

Conditions: PCI: 97

Inspection Comments:

Sample Number: 04 **Type:** R **Area:** 20.00 Slabs **PCI:** 98

Sample Comments:

66 SMALL PATCH L 1.00 Slabs

73 SHRINKAGE CR N 1.00 Slabs

Sample Number: 08 **Type:** R **Area:** 20.00 Slabs **PCI:** 100

Sample Comments:

<No Distress>

Sample Number: 10 **Type:** R **Area:** 20.00 Slabs **PCI:** 95

Sample Comments:

63 LINEAR CR L 1.00 Slabs

Sample Number: 17 **Type:** R **Area:** 20.00 Slabs **PCI:** 97

Sample Comments:

66 SMALL PATCH M 1.00 Slabs



Network: SMS **Name:** Sumter Municipal Airport

Branch: AP 01 **Name:** APRON 01 **Use:** APRON **Area:** 346,386 SqFt

Section: 40 of 5 **From:** - **To:** - **Last Const.:** 1/1/2000

Surface: AC **Family:** SC2_AP_AC **Zone:** **Category:** **Rank:** P

Area: 31,530 SqFt **Length:** 323 Ft **Width:** 170 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 1/1/2000 **Work Type:** New Construction - AC **Code:** NC-AC **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **TotalSamples:** 6 **Surveyed:** 2

Conditions: PCI: 79

Inspection Comments:

Sample Number: 02 **Type:** R **Area:** 5000.00 SqFt **PCI:** 83

Sample Comments:

48 L & T CR L 18.00 Ft

48 L & T CR M 36.00 Ft

57 WEATHERING L 5000.00 SqFt

Sample Number: 06 **Type:** R **Area:** 6150.00 SqFt **PCI:** 75

Sample Comments:

48 L & T CR L 165.00 Ft

48 L & T CR M 111.00 Ft

57 WEATHERING L 6150.00 SqFt




Network:	SMS	Name:	Sumter Municipal Airport						
Branch:	AP 01	Name:	APRON 01	Use:	APRON	Area:	346,386 SqFt		
Section:	50	of	5	From:	-	To:	-	Last Const.:	7/1/2016
Surface:	AC	Family:	SC2_AP_AC	Zone:		Category:		Rank:	P
Area:	16,612 SqFt	Length:	210 Ft	Width:	160 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	7/1/2016	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/1/2018	Work Type:	Surface Seal - Rejuvenating		Code:	SS-RE	Is Major M&R:	False	
Last Insp. Date:	1/4/2023	Total Samples:	4		Surveyed:	1			
Conditions:	PCI: 95								
Inspection Comments:									
Sample Number:	02	Type:	R	Area:	4080.00 SqFt	PCI:	95		
Sample Comments:									
57	WEATHERING	L	2040.00 SqFt						



Network:	SMS	Name:	Sumter Municipal Airport						
Branch:	RW 5	Name:	RUNWAY 5-23	Use:	RUNWAY	Area:	550,000 SqFt		
Section:	10	of	2	From:	-	To:	-	Last Const.:	1/1/2006
Surface:	AAC	Family:	SC2_RW_AC	Zone:		Category:	G	Rank:	P
Area:	480,000 SqFt	Length:	4,800 Ft	Width:	100 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	7/1/1967	Work Type:	Surface Course - AC (Layer Construct)		Code:	SU-AC	Is Major M&R:	False	
Work Date:	7/1/1967	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R:	False	
Work Date:	7/1/1967	Work Type:	Surface Treatment - Double Bitum. (Layer Construct)		Code:	SU-DB	Is Major M&R:	False	
Work Date:	6/1/1980	Work Type:	New Construction - Initial		Code:	NU-IN	Is Major M&R:	True	
Work Date:	6/1/1980	Work Type:	Surface Course - AC (Layer Construct)		Code:	LC-AC	Is Major M&R:	True	
Work Date:	1/1/2006	Work Type:	Overlay - AC Structural		Code:	OL-AS	Is Major M&R:	True	
Work Date:	1/1/2018	Work Type:	Surface Seal - Rejuvenating		Code:	SS-RE	Is Major M&R:	False	

Last Insp. Date:	1/4/2023	TotalSamples:	96	Surveyed:	20
Conditions:	PCI: 77				

Inspection Comments:							
Sample Number:	03	Type:	R	Area:	5000.00 SqFt	PCI:	73
Sample Comments:							
48	L & T CR	L	308.00	Ft			
57	WEATHERING	L	2500.00	SqFt			
57	WEATHERING	M	2500.00	SqFt			
Sample Number:	07	Type:	R	Area:	5000.00 SqFt	PCI:	80
Sample Comments:							
48	L & T CR	L	138.00	Ft			
57	WEATHERING	L	3750.00	SqFt			
57	WEATHERING	M	1250.00	SqFt			
Sample Number:	11	Type:	R	Area:	5000.00 SqFt	PCI:	79
Sample Comments:							
48	L & T CR	L	160.00	Ft			
57	WEATHERING	L	3750.00	SqFt			
57	WEATHERING	M	1250.00	SqFt			
Sample Number:	14	Type:	R	Area:	5000.00 SqFt	PCI:	73
Sample Comments:							
48	L & T CR	L	299.00	Ft			
57	WEATHERING	L	3750.00	SqFt			
57	WEATHERING	M	1250.00	SqFt			
Sample Number:	19	Type:	R	Area:	5000.00 SqFt	PCI:	80
Sample Comments:							
48	L & T CR	L	156.00	Ft			
57	WEATHERING	L	3750.00	SqFt			
57	WEATHERING	M	1250.00	SqFt			
Sample Number:	24	Type:	R	Area:	5000.00 SqFt	PCI:	79
Sample Comments:							
48	L & T CR	L	178.00	Ft			
57	WEATHERING	L	3750.00	SqFt			
57	WEATHERING	M	1250.00	SqFt			
Sample Number:	29	Type:	R	Area:	5000.00 SqFt	PCI:	77
Sample Comments:							



48	L & T CR	L	208.00	Ft
57	WEATHERING	L	3750.00	SqFt
57	WEATHERING	M	1250.00	SqFt

Sample Number: 34 **Type:** R **Area:** 5000.00 SqFt **PCI:** 80

Sample Comments:

48	L & T CR	L	144.00	Ft
57	WEATHERING	L	3750.00	SqFt
57	WEATHERING	M	1250.00	SqFt

Sample Number: 39 **Type:** R **Area:** 5000.00 SqFt **PCI:** 77

Sample Comments:

48	L & T CR	L	216.00	Ft
57	WEATHERING	L	3750.00	SqFt
57	WEATHERING	M	1250.00	SqFt

Sample Number: 44 **Type:** R **Area:** 5000.00 SqFt **PCI:** 79

Sample Comments:

48	L & T CR	L	161.00	Ft
57	WEATHERING	L	3750.00	SqFt
57	WEATHERING	M	1250.00	SqFt

Sample Number: 49 **Type:** R **Area:** 5000.00 SqFt **PCI:** 76

Sample Comments:

48	L & T CR	L	222.00	Ft
57	WEATHERING	L	3750.00	SqFt
57	WEATHERING	M	1250.00	SqFt

Sample Number: 54 **Type:** R **Area:** 5000.00 SqFt **PCI:** 78

Sample Comments:

48	L & T CR	L	182.00	Ft
57	WEATHERING	L	4000.00	SqFt
57	WEATHERING	M	1000.00	SqFt

Sample Number: 59 **Type:** R **Area:** 5000.00 SqFt **PCI:** 79

Sample Comments:

48	L & T CR	L	109.00	Ft
57	WEATHERING	L	3500.00	SqFt
57	WEATHERING	M	1500.00	SqFt

Sample Number: 64 **Type:** R **Area:** 5000.00 SqFt **PCI:** 78

Sample Comments:

48	L & T CR	L	193.00	Ft
57	WEATHERING	L	3750.00	SqFt
57	WEATHERING	M	1250.00	SqFt

Sample Number: 69 **Type:** R **Area:** 5000.00 SqFt **PCI:** 75

Sample Comments:

48	L & T CR	L	165.00	Ft
57	WEATHERING	L	2500.00	SqFt
57	WEATHERING	M	2500.00	SqFt

Sample Number: 74 **Type:** R **Area:** 5000.00 SqFt **PCI:** 78

Sample Comments:

48	L & T CR	L	189.00	Ft
57	WEATHERING	L	3750.00	SqFt
57	WEATHERING	M	1250.00	SqFt

Sample Number: 79 **Type:** R **Area:** 5000.00 SqFt **PCI:** 77


Sample Comments:

48	L & T CR	L	206.00	Ft
57	WEATHERING	L	3500.00	SqFt
57	WEATHERING	M	1500.00	SqFt

Sample Number: 84 **Type:** R **Area:** 5000.00 SqFt **PCI:** 76

Sample Comments:

48	L & T CR	L	229.00	Ft
----	----------	---	--------	----



57	WEATHERING	L	3750.00	SqFt
57	WEATHERING	M	1250.00	SqFt

Sample Number: 89 **Type:** R **Area:** 5000.00 SqFt **PCI:** 72

Sample Comments:

48	L & T CR	L	325.00	Ft
57	WEATHERING	L	3000.00	SqFt
57	WEATHERING	M	2000.00	SqFt

Sample Number: 94 **Type:** R **Area:** 5000.00 SqFt **PCI:** 71

Sample Comments:

48	L & T CR	L	368.00	Ft
57	WEATHERING	L	3750.00	SqFt
57	WEATHERING	M	1250.00	SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: RW 5 **Name:** RUNWAY 5-23 **Use:** RUNWAY **Area:** 550,000 SqFt

Section: 20 of 2 **From:** - **To:** - **Last Const.:** 1/1/2006

Surface: AAC **Family:** SC2_RW_AC **Zone:** **Category:** G **Rank:** P

Area: 70,000 SqFt **Length:** 700 Ft **Width:** 100 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 2/1/1989 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 2/1/1989 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 2/1/1989 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 1/1/2006 **Work Type:** Overlay - AC Structural **Code:** OL-AS **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **TotalSamples:** 14 **Surveyed:** 4

Conditions: PCI: 73

Inspection Comments:

Sample Number: 03 **Type:** R **Area:** 5000.00 SqFt **PCI:** 69

Sample Comments:

48 L & T CR L 434.00 Ft
57 WEATHERING L 3750.00 SqFt
57 WEATHERING M 1250.00 SqFt

Sample Number: 06 **Type:** R **Area:** 5000.00 SqFt **PCI:** 71

Sample Comments:

48 L & T CR L 371.00 Ft
57 WEATHERING L 3750.00 SqFt
57 WEATHERING M 1250.00 SqFt

Sample Number: 09 **Type:** R **Area:** 5000.00 SqFt **PCI:** 71


Sample Comments:

48 L & T CR L 356.00 Ft
57 WEATHERING L 3750.00 SqFt
57 WEATHERING M 1250.00 SqFt

Sample Number: 12 **Type:** R **Area:** 5000.00 SqFt **PCI:** 80

Sample Comments:

48 L & T CR L 150.00 Ft
57 WEATHERING L 4250.00 SqFt
57 WEATHERING M 750.00 SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: TL 01 **Name:** TAXILANE 01 **Use:** TAXILANE **Area:** 55,984 SqFt

Section: 10 of 1 **From:** - **To:** - **Last Const.:** 6/1/2003

Surface: AAC **Family:** SC2_TWTL_AC **Zone:** **Category:** G **Rank:** T

Area: 55,984 SqFt **Length:** 140 Ft **Width:** 120 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 6/1/1997 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 6/1/1997 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 6/1/2003 **Work Type:** Overlay - AC Non-Structural **Code:** OL-UN **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **TotalSamples:** 11 **Surveyed:** 4

Conditions: PCI: 71

Inspection Comments:

Sample Number: 01 **Type:** R **Area:** 4500.00 SqFt **PCI:** 66

Sample Comments:

48 L & T CR L 460.00 Ft
48 L & T CR M 39.00 Ft
57 WEATHERING L 4500.00 SqFt

Sample Number: 07 **Type:** R **Area:** 5100.00 SqFt **PCI:** 78

Sample Comments:

41 ALLIGATOR CR L 14.00 SqFt
48 L & T CR L 186.00 Ft
57 WEATHERING L 5100.00 SqFt

Sample Number: 09 **Type:** R **Area:** 3450.00 SqFt **PCI:** 68


Sample Comments:

45 DEPRESSION L 8.00 SqFt
48 L & T CR L 37.00 Ft
50 PATCHING M 195.00 SqFt
57 WEATHERING L 3255.00 SqFt

Sample Number: 11 **Type:** R **Area:** 6509.00 SqFt **PCI:** 70

Sample Comments:

45 DEPRESSION L 72.00 SqFt
48 L & T CR L 112.00 Ft
48 L & T CR M 41.00 Ft
50 PATCHING L 332.00 SqFt
57 WEATHERING L 6177.00 SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: TW A **Name:** TAXIWAY A **Use:** TAXIWAY **Area:** 206,032 SqFt

Section: 10 of 5 **From:** - **To:** - **Last Const.:** 8/1/2007

Surface: AC **Family:** SC2_TWTL_AC **Zone:** **Category:** **Rank:** P

Area: 34,889 SqFt **Length:** 965 Ft **Width:** 35 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 8/1/2007 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **TotalSamples:** 9 **Surveyed:** 2

Conditions: PCI: 78

Inspection Comments:

Sample Number: 03 **Type:** R **Area:** 3500.00 SqFt **PCI:** 76

Sample Comments:

48 L & T CR L 157.00 Ft

57 WEATHERING L 3150.00 SqFt

57 WEATHERING M 350.00 SqFt

Sample Number: 08 **Type:** R **Area:** 3500.00 SqFt **PCI:** 79

Sample Comments:

48 L & T CR L 106.00 Ft

52 RAVELING L 2.00 SqFt

57 WEATHERING L 3148.00 SqFt

57 WEATHERING M 350.00 SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: TW A **Name:** TAXIWAY A **Use:** TAXIWAY **Area:** 206,032 SqFt

Section: 20 of 5 **From:** - **To:** - **Last Const.:** 4/1/2003

Surface: AAC **Family:** SC2_TWTL_AC **Zone:** **Category:** G **Rank:** P

Area: 10,259 SqFt **Length:** 217 Ft **Width:** 40 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 11/1/1988 **Work Type:** Surface Course - AC (Layer Construct) **Code:** LC-AC **Is Major M&R:** True

Work Date: 11/1/1988 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 4/1/2003 **Work Type:** Overlay - AC Structural **Code:** OL-AS **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **TotalSamples:** 2 **Surveyed:** 1

Conditions: PCI: 75

Inspection Comments:

Sample Number: 01 **Type:** R **Area:** 5073.00 SqFt **PCI:** 75

Sample Comments:

48 L & T CR L 195.00 Ft
57 WEATHERING L 1268.00 SqFt
57 WEATHERING M 3805.00 SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: TW A **Name:** TAXIWAY A **Use:** TAXIWAY **Area:** 206,032 SqFt

Section: 30 of 5 **From:** - **To:** - **Last Const.:** 4/1/2003

Surface: AAC **Family:** SC2_TWTL_AC **Zone:** **Category:** G **Rank:** P

Area: 25,285 SqFt **Length:** 490 Ft **Width:** 40 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 11/1/1988 **Work Type:** Surface Course - AC (Layer Construct) **Code:** LC-AC **Is Major M&R:** True

Work Date: 11/1/1988 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 11/1/1995 **Work Type:** Maintenance (Localized MR) **Code:** MAINT **Is Major M&R:** False

Work Date: 4/1/2003 **Work Type:** Overlay - AC Structural **Code:** OL-AS **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **TotalSamples:** 5 **Surveyed:** 2

Conditions: PCI: 74

Inspection Comments:

Sample Number: 02 **Type:** R **Area:** 4001.00 SqFt **PCI:** 76

Sample Comments:

48 L & T CR L 188.00 Ft
57 WEATHERING L 3001.00 SqFt
57 WEATHERING M 1000.00 SqFt

Sample Number: 04 **Type:** R **Area:** 4000.00 SqFt **PCI:** 73

Sample Comments:

48 L & T CR L 271.00 Ft
56 SWELLING L 11.00 SqFt
57 WEATHERING L 1600.00 SqFt
57 WEATHERING M 2400.00 SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: TW A **Name:** TAXIWAY A **Use:** TAXIWAY **Area:** 206,032 SqFt

Section: 40 of 5 **From:** - **To:** - **Last Const.:** 4/1/2003

Surface: AAC **Family:** SC2_TWTL_AC **Zone:** **Category:** G **Rank:** P

Area: 99,506 SqFt **Length:** 2,430 Ft **Width:** 40 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 11/1/1988 **Work Type:** Surface Course - AC (Layer Construct) **Code:** LC-AC **Is Major M&R:** True

Work Date: 11/1/1988 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 11/1/1995 **Work Type:** Maintenance (Localized MR) **Code:** MAINT **Is Major M&R:** False

Work Date: 4/1/2003 **Work Type:** Overlay - AC Structural **Code:** OL-AS **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **TotalSamples:** 25 **Surveyed:** 5

Conditions: PCI: 70

Inspection Comments:

Sample Number: 04 **Type:** R **Area:** 4000.00 SqFt **PCI:** 77

Sample Comments:

48 L & T CR L 171.00 Ft
57 WEATHERING L 3400.00 SqFt
57 WEATHERING M 600.00 SqFt

Sample Number: 10 **Type:** R **Area:** 4000.00 SqFt **PCI:** 72

Sample Comments:

48 L & T CR L 273.00 Ft
57 WEATHERING L 3400.00 SqFt
57 WEATHERING M 600.00 SqFt

Sample Number: 14 **Type:** R **Area:** 4000.00 SqFt **PCI:** 70

Sample Comments:

48 L & T CR L 316.00 Ft
57 WEATHERING L 3400.00 SqFt
57 WEATHERING M 600.00 SqFt

Sample Number: 18 **Type:** R **Area:** 4000.00 SqFt **PCI:** 67


Sample Comments:

48 L & T CR L 405.00 Ft
57 WEATHERING L 3400.00 SqFt
57 WEATHERING M 600.00 SqFt

Sample Number: 22 **Type:** R **Area:** 4000.00 SqFt **PCI:** 67

Sample Comments:

48 L & T CR L 403.00 Ft
57 WEATHERING L 3400.00 SqFt
57 WEATHERING M 600.00 SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: TW A **Name:** TAXIWAY A **Use:** TAXIWAY **Area:** 206,032 SqFt

Section: 50 of 5 **From:** - **To:** - **Last Const.:** 4/1/2003

Surface: AAC **Family:** SC2_TWTL_AC **Zone:** **Category:** G **Rank:** P

Area: 36,093 SqFt **Length:** 1,037 Ft **Width:** 35 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 2/1/1989 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 2/1/1989 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 2/1/1989 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 2/1/1995 **Work Type:** Maintenance (Localized MR) **Code:** MAINT **Is Major M&R:** False

Work Date: 4/1/2003 **Work Type:** Overlay - AC Structural **Code:** OL-AS **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **Total Samples:** 10 **Surveyed:** 3

Conditions: PCI: 76

Inspection Comments:

Sample Number: 03 **Type:** R **Area:** 3500.00 SqFt **PCI:** 75

Sample Comments:

48 L & T CR L 175.00 Ft
57 WEATHERING L 2975.00 SqFt
57 WEATHERING M 525.00 SqFt

Sample Number: 06 **Type:** R **Area:** 3500.00 SqFt **PCI:** 77


Sample Comments:

48 L & T CR L 142.00 Ft
57 WEATHERING L 2975.00 SqFt
57 WEATHERING M 525.00 SqFt

Sample Number: 09 **Type:** R **Area:** 3500.00 SqFt **PCI:** 74

Sample Comments:

48 L & T CR L 195.00 Ft
57 WEATHERING L 2975.00 SqFt
57 WEATHERING M 525.00 SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: TW A1 **Name:** TAXIWAY A1 **Use:** TAXIWAY **Area:** 15,117 SqFt

Section: 10 of 1 **From:** - **To:** - **Last Const.:** 4/1/2003

Surface: AAC **Family:** SC2_TWTL_AC **Zone:** **Category:** G **Rank:** P

Area: 15,117 SqFt **Length:** 330 Ft **Width:** 35 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 2/1/1989 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 2/1/1989 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 2/1/1989 **Work Type:** Surface Course - AC (Layer Construct) **Code:** SU-AC **Is Major M&R:** False

Work Date: 2/1/1995 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

Work Date: 4/1/2003 **Work Type:** Overlay - AC Structural **Code:** OL-AS **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **Total Samples:** 4 **Surveyed:** 1

Conditions: PCI: 78

Inspection Comments:

Sample Number: 03 **Type:** R **Area:** 3500.00 SqFt **PCI:** 78

Sample Comments:

48 L & T CR L 126.00 Ft
57 WEATHERING L 2625.00 SqFt
57 WEATHERING M 875.00 SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: TW A2 **Name:** TAXIWAY A2 **Use:** TAXIWAY **Area:** 19,527 SqFt

Section: 10 of 1 **From:** - **To:** - **Last Const.:** 4/1/2003

Surface: AAC **Family:** SC2_TWTL_AC **Zone:** **Category:** G **Rank:** S

Area: 19,527 SqFt **Length:** 400 Ft **Width:** 40 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 11/1/1988 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 11/1/1988 **Work Type:** Surface Course - AC (Layer Construct) **Code:** LC-AC **Is Major M&R:** True

Work Date: 4/1/2003 **Work Type:** Overlay - AC Structural **Code:** OL-AS **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **TotalSamples:** 4 **Surveyed:** 2

Conditions: PCI: 76

Inspection Comments:

Sample Number: 02 **Type:** R **Area:** 4024.00 SqFt **PCI:** 73

Sample Comments:

48 L & T CR L 249.00 Ft
57 WEATHERING L 3420.00 SqFt
57 WEATHERING M 604.00 SqFt

Sample Number: 03 **Type:** R **Area:** 4000.00 SqFt **PCI:** 79

Sample Comments:

48 L & T CR L 141.00 Ft
57 WEATHERING L 3400.00 SqFt
57 WEATHERING M 600.00 SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: TW A3 **Name:** TAXIWAY A3 **Use:** TAXIWAY **Area:** 36,699 SqFt

Section: 10 of 1 **From:** - **To:** - **Last Const.:** 4/1/2003

Surface: AAC **Family:** SC2_TWTL_AC **Zone:** **Category:** G **Rank:** P

Area: 36,699 SqFt **Length:** 890 Ft **Width:** 40 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 6/1/1980 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 6/1/1980 **Work Type:** Surface Course - AC (Layer Construct) **Code:** LC-AC **Is Major M&R:** True

Work Date: 6/1/1995 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

Work Date: 4/1/2003 **Work Type:** Overlay - AC Structural **Code:** OL-AS **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **TotalSamples:** 8 **Surveyed:** 3

Conditions: PCI: 71

Inspection Comments:

Sample Number: 03 **Type:** R **Area:** 4000.00 SqFt **PCI:** 76

Sample Comments:

48 L & T CR L 161.00 Ft
56 SWELLING L 8.00 SqFt
57 WEATHERING L 3000.00 SqFt
57 WEATHERING M 1000.00 SqFt

Sample Number: 05 **Type:** R **Area:** 4000.00 SqFt **PCI:** 64


Sample Comments:

48 L & T CR L 361.00 Ft
56 SWELLING L 52.00 SqFt
57 WEATHERING L 3200.00 SqFt
57 WEATHERING M 800.00 SqFt

Sample Number: 07 **Type:** R **Area:** 4000.00 SqFt **PCI:** 74

Sample Comments:

45 DEPRESSION L 4.00 SqFt
48 L & T CR L 218.00 Ft
57 WEATHERING L 3400.00 SqFt
57 WEATHERING M 600.00 SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: TW A4 **Name:** TAXIWAY A4 **Use:** TAXIWAY **Area:** 31,651 SqFt

Section: 10 of 1 **From:** - **To:** - **Last Const.:** 4/1/2003

Surface: AAC **Family:** SC2_TWTL_AC **Zone:** **Category:** G **Rank:** P

Area: 31,651 SqFt **Length:** 740 Ft **Width:** 40 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 6/1/1980 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 6/1/1980 **Work Type:** Surface Course - AC (Layer Construct) **Code:** LC-AC **Is Major M&R:** True

Work Date: 6/1/1995 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

Work Date: 4/1/2003 **Work Type:** Overlay - AC Structural **Code:** OL-AS **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **TotalSamples:** 7 **Surveyed:** 2

Conditions: PCI: 73

Inspection Comments:

Sample Number: 02 **Type:** R **Area:** 4000.00 SqFt **PCI:** 75


Sample Comments:

48 L & T CR L 276.00 Ft
57 WEATHERING M 4000.00 SqFt

Sample Number: 05 **Type:** R **Area:** 4000.00 SqFt **PCI:** 72

Sample Comments:

48 L & T CR L 153.00 Ft
56 SWELLING L 42.00 SqFt
57 WEATHERING L 2000.00 SqFt
57 WEATHERING M 2000.00 SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: TW A5 **Name:** TAXIWAY A5 **Use:** TAXIWAY **Area:** 22,826 SqFt

Section: 10 of 1 **From:** - **To:** - **Last Const.:** 4/1/2003

Surface: AAC **Family:** SC2_TWTL_AC **Zone:** **Category:** G **Rank:** P

Area: 22,826 SqFt **Length:** 170 Ft **Width:** 40 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 6/1/1980 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 6/1/1980 **Work Type:** Surface Course - AC (Layer Construct) **Code:** LC-AC **Is Major M&R:** True

Work Date: 6/1/1995 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

Work Date: 4/1/2003 **Work Type:** Overlay - AC Structural **Code:** OL-AS **Is Major M&R:** True

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **TotalSamples:** 5 **Surveyed:** 2

Conditions: PCI: 74

Inspection Comments:

Sample Number: 02 **Type:** R **Area:** 4000.00 SqFt **PCI:** 75


Sample Comments:

48 L & T CR L 150.00 Ft
57 WEATHERING M 4000.00 SqFt

Sample Number: 04 **Type:** R **Area:** 4000.00 SqFt **PCI:** 72

Sample Comments:

48 L & T CR L 325.00 Ft
52 RAVELING L 4.00 SqFt
56 SWELLING L 4.00 SqFt
57 WEATHERING M 3996.00 SqFt



Network: SMS **Name:** Sumter Municipal Airport

Branch: TW A6 **Name:** TAXIWAY A6 **Use:** TAXIWAY **Area:** 17,699 SqFt

Section: 10 of 1 **From:** - **To:** - **Last Const.:** 8/1/2007

Surface: AC **Family:** SC2_TWTL_AC **Zone:** **Category:** **Rank:** P

Area: 17,699 SqFt **Length:** 330 Ft **Width:** 40 Ft

Slabs: **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

Shoulder: **Street Type:** **Grade:** 0 **Lanes:** 0

Section Comments:

Work Date: 8/1/2007 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

Work Date: 8/2/2007 **Work Type:** Base Course - Aggregate **Code:** BA-AG **Is Major M&R:** False

Work Date: 8/3/2007 **Work Type:** Surface Course - AC (Layer Construct) **Code:** LC-AC **Is Major M&R:** False

Work Date: 1/1/2018 **Work Type:** Surface Seal - Rejuvenating **Code:** SS-RE **Is Major M&R:** False

Last Insp. Date: 1/4/2023 **TotalSamples:** 4 **Surveyed:** 1

Conditions: PCI: 83

Inspection Comments:

Sample Number: 03 **Type:** R **Area:** 4118.00 SqFt **PCI:** 83

Sample Comments:

48 L & T CR L 84.00 Ft
52 RAVELING L 10.00 SqFt
57 WEATHERING L 3903.00 SqFt
57 WEATHERING M 205.00 SqFt





Kimley»»Horn