



SOUTH CAROLINA AERONAUTICS COMMISSION

STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

 DYB - Summerville Airport



Kimley»Horn

2024



Contents

Overview	3
Introduction	3
System Inventory	4
Functional Evaluation	8
Pavement Condition Index	8
Critical PCI	9
PCI Results	9
Pavement Condition Forecast	12
M&R Overview	15
Localized Maintenance and Repair	16
Major Rehabilitation Needs	16
Appendix A – Exhibits	A-1
Appendix B – Analysis Tables	B-1
Appendix C – Maintenance and Rehabilitation Tables	C-1
Appendix D – PCI Results Summary	D-1
Appendix E – Re-Inspection Report	E-1

Overview

Introduction

For over 20 years, the South Carolina Aeronautics Commission (SCAC) has implemented an airfield pavement management program for publicly owned South Carolina airports. As part of their grant assurances federally obligated airports are required to perform detailed inspections as outlined in the FAA Advisory Circular 150/5380-7B – “Airport Pavement Management Program (PMP)”. All inspections performed within this program follow the guidance documented within the ASTM D5340-23 – “Standard Test Method for Airport Pavement Condition Surveys”. This is an objective process to assess the pavement condition in a consistent and repeatable manner.

Due to ever-changing pavement conditions, the FAA AC 150/5380-7B recommends the PMP be updated every 3 years. The overall pavement conditions are analyzed using the ASTM PCI methodology. It provides decision makers with a comparison of pavement facilities and a relative indication of their required maintenance or level of repair to aid in project prioritization. A detailed explanation of the SCAC airfield pavement management program process and pavement management terminology can be found in the SCAC Statewide Report.

Project elements performed for this 2021-2024 program update include the development and updates of pavement inventories, documentation of pavement conditions, performance modeling, and maintenance and rehabilitation (M&R) needs for all participating airports. This report summarizes the results of the SCAC pavement program update at Summerville Airport (DYB).

Figure 1 – Airport Layout



System Inventory

The pavements at Summerville Airport (DYB) include approximately 1.0 million square feet of airfield pavements consisting of runways, taxiways, taxilanes, and aprons. Per the guidance in the ASTM D5340-23, all pavements were divided and subdivided into pavement management units (Network, Branch, Section, Sample). The divisions are documented in the **Network Definition Exhibit** providing the name and location of each branch, section, and sample.


Each pavement update included a review of documentation of any maintenance and major rehabilitation related activities performed on the airfield pavements. The following table summarizes the projects that have occurred since the previous inspection.


Table 1 - Recent Airfield Pavement Construction

Construction Year	Location	Work Type / Pavement Section
2019	AP 01, RW 6, TL 01, TW A, TW B, TW C	Crack Sealing - AC
2019	RW 6, TL 01, TW A, TW B, TW C	Surface Seal – Rejuvenating
2021	AP 01	New Construction - PCC 8" P-501, 6" P-209, 24" P-152
2022	AP 01	Surface Seal – Rejuvenating

The following figure summarizes the inventory items at Summerville Airport (DYB). The **Estimated Age Exhibit** provides the last major work date for each pavement section based on the collected documentation.

Figure 2 – System Inventory Summary





Functional Evaluation

Pavement Condition Index

A Pavement Condition Index (PCI) survey is the primary means of obtaining and recording pavement distress data. In adherence to FAA Advisory Circular 150/5380-7B, the SCAC Airfield Pavement Management System (APMS) Update utilizes the PCI survey methodology to collect pavement distress data and analyze the condition. This method uses a visual statistical sampling of pavements for recording primary distress types, associated severities, and quantities as defined by the ASTM D5340-23.

Visual condition data collected during the PCI survey is analyzed and used to calculate the current PCI for each inspected sample unit and section. The PCI is a value ranging from 0 to 100, which indicates the apparent structural integrity and surface operational condition of the pavement, with “100” indicating a pavement in new condition and “0” indicating a failed pavement section. Pavement Condition Ratings are associated with PCI categories that range from “Failed” to “Good”. Representative photos of varying Pavement Condition Ratings are displayed in **Figure 3**.

Figure 3 – Representation of Pavement Condition Index Values




Poor/Failed Pavement

Pavements that are Poor to Failed require significant and costly interventions such as reconstruction to restore the pavement to operational service.




Fair Pavement

Pavements with a Fair condition rating typically require rehabilitation, or maintenance activities if rehabilitation cannot be immediately performed.



Good/New Pavement

Pavements classified as Good require either no treatment or would benefit from the application of preventive maintenance activities such as crack sealing.




Critical PCI

From a pavement management perspective, one of the most valuable aspects of the PCI methodology is the ability to save money by effectively prioritizing the rehabilitation of pavement assets. Critical PCI refers to the condition beyond which the rate of pavement deterioration and the cost of applying a treatment increases significantly. In other words, it is the condition at which maintenance may no longer be cost effective and major rehabilitation should be considered. Based on the 2019 FAA Order 5100.38D Change 1 Airport Improvement Program Handbook, the FAA has established recommended PCI thresholds for pavement M&R. Accordingly, **the Critical PCI for all SCAC airfield pavements is defined at 70.**

PCI Results


The PCI survey for Summerville Airport (DYB) was performed in October 2023. **The overall area-weighted average PCI value of the network was 73**, representing a condition rating of **Satisfactory**. Approximately 62% of inspected pavements are in Good or Satisfactory condition, 34% of inspected pavements are in Fair condition, and the remaining 4% are in Poor or worse condition as summarized in **Figure 4**.

Figure 4 – Overall Network PCI Results



The area-weighted average PCIs by branch use are summarized in the figure below. The current PCIs at a section-level are displayed graphically on the **2023 Airfield Pavement Condition Index Exhibit** and are summarized in **Table 2**.

Figure 5 – Area Weighted Average Pavement Condition



DYB - Summerville Airport

Table 2 – Current Pavement Condition Index Summary – Section


Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
DYB	AP 01	Apron	10	227,081	AAC	61	Fair	100	0	0
DYB	AP 01	Apron	20	47,854	PCC	97	Good	0	100	0
DYB	RW 6	Runway	10	277,650	AAC	79	Satisfactory	100	0	0
DYB	RW 6	Runway	20	97,275	AC	90	Good	100	0	0
DYB	TL 01	Taxilane	10	51,256	AC	68	Fair	99	0	1
DYB	TL 01	Taxilane	15	12,369	AC	27	Very Poor	50	50	0
DYB	TL 01	Taxilane	20	10,294	AC	28	Very Poor	34	49	17
DYB	TL 01	Taxilane	30	14,306	AC	56	Fair	67	23	10
DYB	TL 01	Taxilane	40	17,124	AC	23	Serious	44	52	4
DYB	TL 01	Taxilane	50	48,065	AC	65	Fair	100	0	0
DYB	TL 01	Taxilane	60	15,586	AC	64	Fair	100	0	0
DYB	TW A	Taxiway	05	56,874	AC	90	Good	100	0	0
DYB	TW A	Taxiway	10	85,889	AC	75	Satisfactory	100	0	0
DYB	TW A	Taxiway	20	47,370	AC	73	Satisfactory	100	0	0
DYB	TW A	Taxiway	30	3,832	AAC	79	Satisfactory	78	0	22
DYB	TW B	Taxiway	10	15,960	AAC	78	Satisfactory	100	0	0
DYB	TW C	Taxiway	10	8,568	AAC	91	Good	100	0	0
DYB	TW C	Taxiway	20	4,888	AAC	75	Satisfactory	100	0	0

**For further PCI details and photos see Appendix D – Detailed PCI Results.*

Pavement Condition Forecast

A primary objective of this APMS is to estimate the future condition of each individual pavement section. PAVER™ was utilized to develop prediction curves and determine typical deterioration rates that are then used to forecast a future PCI value. This value will assist decision makers in determining at what point in time certain pavement sections will require rehabilitation. The figure below shows the current and 5-year area-weighted forecasted pavement condition distribution of each functional use (Runway, Taxiway, Taxilane, Apron) found at the Airport. The forecasted 5-year PCIs at a section-level are displayed graphically on the **2029 Forecasted Airfield Pavement Condition Index Exhibit** and are summarized in **Table 3**. All forecasts presented assume that no maintenance or rehabilitation is performed within the 5-year analysis period. **Figure 6** displays the forecasted pavement conditions at the branch-level for DYB.

Figure 6 – Forecasted 5-Year PCI by Branch Use



All condition forecasts are based on historical observations and analysis of South Carolina airfield pavements. The forecasts are not a guarantee of future PCI: - rather, they are a planning tool to aid in the timing of maintenance and rehabilitation activities.

DYB - Summerville Airport

Table 3 – Forecast (2025-2029) Section Pavement Condition Index - Section

Network ID	Branch ID	Section ID	Current PCI	Forecasted PCI				
				2025	2026	2027	2028	2029
DYB	AP 01	10	61	60	58	57	56	55
DYB	AP 01	20	97	96	96	96	95	95
DYB	RW 6	10	79	77	76	74	73	72
DYB	RW 6	20	90	87	85	83	81	80
DYB	TL 01	10	68	67	66	65	64	62
DYB	TL 01	15	27	26	24	23	22	21
DYB	TL 01	20	28	27	25	24	23	22
DYB	TL 01	30	56	55	54	53	53	52
DYB	TL 01	40	23	22	21	20	20	19
DYB	TL 01	50	65	64	63	62	61	60
DYB	TL 01	60	64	63	62	61	60	59
DYB	TW A	05	90	88	86	84	83	81
DYB	TW A	10	75	74	72	71	70	69
DYB	TW A	20	73	72	71	69	68	67
DYB	TW A	30	79	77	76	75	74	73
DYB	TW B	10	78	77	75	74	73	72
DYB	TW C	10	91	88	87	85	83	82
DYB	TW C	20	75	74	72	71	70	69


M&R Overview

An analysis was performed to assess the pavement maintenance and rehabilitation (M&R) needs at DYB over a 5-year period. The analysis compared the forecasted condition of each pavement section to the Critical PCI threshold to develop a resultant recommendation and associated cost for each year of the 5-year plan. The M&R analysis should enable responsible parties to do the following:

- **Maintain** existing airport infrastructure at an acceptable condition
- Make timely and cost-effective **decisions** to appropriately allocate funding
- **Apply** global maintenance, localized maintenance, and major M&R activities in a timely manner to maintain an acceptable operational condition of a pavement network.

M&R planning considers various methods of repair to address the cause of the problem rather than just treating the symptom. As pavements deteriorate, repair costs can increase significantly. Once pavements have deteriorated below a certain condition threshold (the Critical PCI value), the pavement benefits more from substantial rehabilitation in lieu of maintenance activities. The figure below illustrates how the cost of pavement repairs can exponentially increase if M&R activities are delayed.

Figure 7 – Pavement Life and the Effect of Treatments



Localized Maintenance and Repair

Localized maintenance is best used as a preservation measure and is applied to slow the rate of deterioration. These activities typically include crack sealing and patching. Localized maintenance differs from major rehabilitation in that it is applied based on the distresses observed rather than based on a PCI value. Treatments are selected based on the appropriate corrective measure for a given distress type and severity level. Localized maintenance applied on pavements with PCIs above the Critical PCI of 70 is known as Preventive Localized Maintenance, while Stopgap Localized Maintenance is typically applied to pavement sections that are at or below the Critical PCI value as a temporary repair due to safety concerns. The current localized maintenance needs are summarized in the table below.

Table 4 – Localized Maintenance Summary by Policy Type

Localized Maintenance Category	Localized Work Type	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
Localized Preventive Maintenance	AC Crack Sealing Narrow	26,119	LF	\$ 111,060
	Surface Seal	5,866	SF	\$ 9,700
	AC Partial-Depth Patching	62	SF	\$ 1,190
	PCC Crack Seal	46	LF	\$ 340
Localized Preventive Maintenance Total=				\$ 122,290
Localized Stopgap Maintenance	AC Crack Sealing Narrow	769	LF	\$ 3,300
	Surface Seal	22,829	SF	\$ 37,690
	AC Full-Depth Patching	3,334	SF	\$ 129,190
Localized Stopgap Maintenance Total =				\$ 170,180
Planning-Level Localized M&R Needs =				\$ 292,470

Major Rehabilitation Needs

Major rehabilitation needs are identified by analyzing the Airport's pavement condition in relationship to the Critical PCI value, density of load-related distresses, and major rehabilitation policies, assuming there are no budget constraints. The needs analysis is performed over a 5-year analysis period. Major rehabilitation is divided into two policy categories:


- ➔ **Intermediate Major Rehabilitation (PCI 56 to 70) –**
 - **AC:** Milling of the upper surface course and replacing with new AC with isolated areas of full-depth reconstruction
 - **PCC:** Combination of crack sealing, joint seal replacement, limited patching, and slab replacement
- ➔ **Full-Depth Reconstruction (PCI 0 to 55) –** Removal and replacement of the existing pavement section down to the subgrade

The 5-year major rehabilitation needs analysis at DYB results in a total 5-year cost of \$9.43M. The **5-Year Major Rehabilitation Needs Exhibit** graphically depicts the major rehabilitation needs at a section-level which are also summarized in **Table 5** with rounded costs. Annual needs are displayed graphically in **Figure 8**.

Table 5 – 5-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2025	DYB	AP 01	10	AAC	227,081	60	AC Rehabilitation	\$ 3,350,000
2025	DYB	TL 01	10	AC	51,256	67	AC Rehabilitation	\$ 757,000
2025	DYB	TL 01	15	AC	12,369	26	AC Reconstruction	\$ 535,000
2025	DYB	TL 01	20	AC	10,294	27	AC Reconstruction	\$ 446,000
2025	DYB	TL 01	30	AC	14,306	55	AC Reconstruction	\$ 619,000
2025	DYB	TL 01	40	AC	17,124	22	AC Reconstruction	\$ 741,000
2025	DYB	TL 01	50	AC	48,065	64	AC Rehabilitation	\$ 709,000
2025	DYB	TL 01	60	AC	15,586	63	AC Rehabilitation	\$ 230,000
2027	DYB	TW A	20	AC	47,370	69	AC Rehabilitation	\$ 699,000
2029	DYB	TW A	10	AC	85,889	69	AC Rehabilitation	\$ 1,267,000
2029	DYB	TW C	20	AAC	4,888	69	AC Rehabilitation	\$ 73,000
Total 5-Year Major Rehabilitation Needs =								\$ 9,426,000

Figure 8 – 5-Year Major Rehabilitation Needs by Program Year



SECTION I

Appendices






Appendix A – Exhibits



STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE


SUMMERVILLE AIRPORT (DYB)

AIRFIELD PAVEMENT NETWORK DEFINITION EXHIBIT



TOTAL SAMPLES INSPECTED = 52
AC: 48 PCC: 4

RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR
PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT
MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE.





Appendix B – Analysis Tables

Table B1 – System Inventory Data - Section

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface Type	Estimate of Last Construction Date
DYB	AP 01	Apron	10	227,081	AAC	5/1/2005
DYB	AP 01	Apron	20	47,854	PCC	1/1/2021
DYB	RW 6	Runway	10	277,650	AAC	2/1/2007
DYB	RW 6	Runway	20	97,275	AC	1/1/2013
DYB	TL 01	Taxilane	10	51,256	AC	8/1/2006
DYB	TL 01	Taxilane	15	12,369	AC	12/1/1984
DYB	TL 01	Taxilane	20	10,294	AC	6/1/2000
DYB	TL 01	Taxilane	30	14,306	AC	6/1/2001
DYB	TL 01	Taxilane	40	17,124	AC	6/1/2000
DYB	TL 01	Taxilane	50	48,065	AC	8/1/2006
DYB	TL 01	Taxilane	60	15,586	AC	6/1/2000
DYB	TW A	Taxiway	05	56,874	AC	1/1/2013
DYB	TW A	Taxiway	10	85,889	AC	8/1/1994
DYB	TW A	Taxiway	20	47,370	AC	8/1/1994
DYB	TW A	Taxiway	30	3,832	AAC	2/1/2007
DYB	TW B	Taxiway	10	15,960	AAC	2/1/2007
DYB	TW C	Taxiway	10	8,568	AAC	1/1/2013
DYB	TW C	Taxiway	20	4,888	AAC	2/1/2007

Table B2 – Current Pavement Condition Index Summary - Branch

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Area-Weighted Avg PCI	Condition Rating
AP 01	Apron	2	274,935	67	Fair
RW 6	Runway	2	374,925	82	Satisfactory
TL 01	Taxilane	7	169,000	56	Fair
TW A	Taxiway	4	193,965	79	Satisfactory
TW B	Taxiway	1	15,960	78	Satisfactory
TW C	Taxiway	2	13,456	85	Satisfactory

Table B3 – Current (2023) Pavement Condition Index Summary - Section

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	Surface	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other	Sample Units Inspected	Total Sample Units in Section
DYB	AP 01	Apron	10	227,081	AAC	61	Fair	100	0	0	9	45
DYB	AP 01	Apron	20	47,854	PCC	97	Good	0	100	0	4	16
DYB	RW 6	Runway	10	277,650	AAC	79	Satisfactory	100	0	0	10	50
DYB	RW 6	Runway	20	97,275	AC	90	Good	100	0	0	4	18
DYB	TL 01	Taxilane	10	51,256	AC	68	Fair	99	0	1	3	10
DYB	TL 01	Taxilane	15	12,369	AC	27	Very Poor	50	50	0	1	2
DYB	TL 01	Taxilane	20	10,294	AC	28	Very Poor	34	49	17	1	2
DYB	TL 01	Taxilane	30	14,306	AC	56	Fair	67	23	10	2	3
DYB	TL 01	Taxilane	40	17,124	AC	23	Serious	44	52	4	1	3
DYB	TL 01	Taxilane	50	48,065	AC	65	Fair	100	0	0	2	10
DYB	TL 01	Taxilane	60	15,586	AC	64	Fair	100	0	0	1	3
DYB	TW A	Taxiway	05	56,874	AC	90	Good	100	0	0	3	11
DYB	TW A	Taxiway	10	85,889	AC	75	Satisfactory	100	0	0	4	16
DYB	TW A	Taxiway	20	47,370	AC	73	Satisfactory	100	0	0	3	9
DYB	TW A	Taxiway	30	3,832	AAC	79	Satisfactory	78	0	22	1	1
DYB	TW B	Taxiway	10	15,960	AAC	78	Satisfactory	100	0	0	1	4
DYB	TW C	Taxiway	10	8,568	AAC	91	Good	100	0	0	1	2
DYB	TW C	Taxiway	20	4,888	AAC	75	Satisfactory	100	0	0	1	1



STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

DYB - Summerville Airport

Table B4 –Forecasted (2025-2029) Pavement Condition Index Summary - Section

Network ID	Branch ID	Section ID	Current PCI	Forecasted PCI				
				2025	2026	2027	2028	2029
DYB	AP 01	10	61	60	58	57	56	55
DYB	AP 01	20	97	96	96	96	95	95
DYB	RW 6	10	79	77	76	74	73	72
DYB	RW 6	20	90	87	85	83	81	80
DYB	TL 01	10	68	67	66	65	64	62
DYB	TL 01	15	27	26	24	23	22	21
DYB	TL 01	20	28	27	25	24	23	22
DYB	TL 01	30	56	55	54	53	53	52
DYB	TL 01	40	23	22	21	20	20	19
DYB	TL 01	50	65	64	63	62	61	60
DYB	TL 01	60	64	63	62	61	60	59
DYB	TW A	05	90	88	86	84	83	81
DYB	TW A	10	75	74	72	71	70	69
DYB	TW A	20	73	72	71	69	68	67
DYB	TW A	30	79	77	76	75	74	73
DYB	TW B	10	78	77	75	74	73	72
DYB	TW C	10	91	88	87	85	83	82
DYB	TW C	20	75	74	72	71	70	69



Appendix C – Maintenance and Rehabilitation Tables

Table C1 – Localized Maintenance Summary by Policy Type

Localized Maintenance Category	Localized Work Type	Rough Estimate of Work Quantity	Work Units	Planning Material Cost
Localized Preventive Maintenance	AC Crack Sealing Narrow	26,119	LF	\$ 111,060
	Surface Seal	5,866	SF	\$ 9,700
	AC Partial-Depth Patching	62	SF	\$ 1,190
	PCC Crack Seal	46	LF	\$ 340
Localized Preventive Maintenance Total=				\$ 122,290
Localized Stopgap Maintenance	AC Crack Sealing Narrow	769	LF	\$ 3,300
	Surface Seal	22,829	SF	\$ 37,690
	AC Full-Depth Patching	3,334	SF	\$ 129,190
Localized Stopgap Maintenance Total =				\$ 170,180
Planning-Level Localized M&R Needs =				\$ 292,470

Table C2 – Section – Level Year 1 Localized Maintenance Planning Cost Summary

Network ID	Branch ID	Section ID	Area (SF)	Start PCI	End PCI	Cost
DYB	AP 01	10	227,081	61	61	\$ -
DYB	AP 01	20	47,854	97	99	\$ 340
DYB	RW 6	10	277,650	79	80	\$ 70,360
DYB	RW 6	20	97,275	90	90	\$ 13,050
DYB	TL 01	10	51,256	68	69	\$ 60
DYB	TL 01	15	12,369	27	50	\$ 41,420
DYB	TL 01	20	10,294	28	56	\$ 24,730
DYB	TL 01	30	14,306	56	64	\$ 3,310
DYB	TL 01	40	17,124	23	57	\$ 100,110
DYB	TL 01	50	48,065	65	67	\$ 270
DYB	TL 01	60	15,586	64	68	\$ 240
DYB	TW A	05	56,874	90	90	\$ 2,510
DYB	TW A	10	85,889	75	79	\$ 16,120
DYB	TW A	20	47,370	73	76	\$ 12,120
DYB	TW A	30	3,832	79	84	\$ 1,320
DYB	TW B	10	15,960	78	79	\$ 4,710
DYB	TW C	10	8,568	91	91	\$ 230
DYB	TW C	20	4,888	75	83	\$ 1,500

Table C3 – Localized Maintenance and Repair Needs Based on Current Distresses

Network ID	Branch ID	Section ID	Description	Severity	Distress Qty	Distress Unit	Distress Density	Policy Type	Localized Work Type	Work Qty	Work Unit	Unit Cost	Work Cost
DYB	AP 01	20	LINEAR CR	Medium	4	Slabs	1.2%	Preventive	PCC Crack Seal	46	LF	\$ 7.25	\$ 340
DYB	RW 6	10	BLEEDING	N/A	10	SF		Preventive	AC Partial-Depth Patching	10	SF	\$ 19.00	\$ 190
DYB	RW 6	10	L & T CR	Low	14,423	LF	5.2%	Preventive	AC Crack Sealing Narrow	14,423	LF	\$ 4.25	\$ 61,300
DYB	RW 6	10	L & T CR	Medium	350	LF	0.1%	Preventive	AC Crack Sealing Narrow	350	LF	\$ 4.25	\$ 1,490
DYB	RW 6	10	WEATHERING	Medium	4,472	SF	1.6%	Preventive	Surface Seal	4,472	SF	\$ 1.65	\$ 7,380
DYB	RW 6	20	L & T CR	Low	3,070	LF	3.2%	Preventive	AC Crack Sealing Narrow	3,070	LF	\$ 4.25	\$ 13,050
DYB	TW A	05	L & T CR	Low	589	LF	1.0%	Preventive	AC Crack Sealing Narrow	589	LF	\$ 4.25	\$ 2,510
DYB	TW A	10	L & T CR	Low	3,288	LF	3.8%	Preventive	AC Crack Sealing Narrow	3,288	LF	\$ 4.25	\$ 13,980
DYB	TW A	10	L & T CR	Medium	503	LF	0.6%	Preventive	AC Crack Sealing Narrow	503	LF	\$ 4.25	\$ 2,140
DYB	TW A	20	L & T CR	Low	2,348	LF	5.0%	Preventive	AC Crack Sealing Narrow	2,347	LF	\$ 4.25	\$ 9,980
DYB	TW A	20	L & T CR	Medium	502	LF	1.1%	Preventive	AC Crack Sealing Narrow	502	LF	\$ 4.25	\$ 2,140
DYB	TW A	30	BLEEDING	N/A	34	SF	0.9%	Preventive	AC Partial-Depth Patching	34	SF	\$ 19.00	\$ 650
DYB	TW A	30	L & T CR	Low	83	LF	2.2%	Preventive	AC Crack Sealing Narrow	83	LF	\$ 4.25	\$ 360
DYB	TW A	30	WEATHERING	Medium	192	SF	5.0%	Preventive	Surface Seal	192	SF	\$ 1.65	\$ 320
DYB	TW B	10	BLEEDING	N/A	18	SF	0.1%	Preventive	AC Partial-Depth Patching	18	SF	\$ 19.00	\$ 350
DYB	TW B	10	L & T CR	Low	716	LF	4.5%	Preventive	AC Crack Sealing Narrow	716	LF	\$ 4.25	\$ 3,050
DYB	TW B	10	WEATHERING	Medium	798	SF	5.0%	Preventive	Surface Seal	798	SF	\$ 1.65	\$ 1,320
DYB	TW C	10	L & T CR	Low	53	LF	0.6%	Preventive	AC Crack Sealing Narrow	54	LF	\$ 4.25	\$ 230
DYB	TW C	20	L & T CR	Low	194	LF	4.0%	Preventive	AC Crack Sealing Narrow	194	LF	\$ 4.25	\$ 830
DYB	TW C	20	RAVELING	Low	76	SF	1.6%	Preventive	Surface Seal	76	SF	\$ 1.65	\$ 130
DYB	TW C	20	WEATHERING	Medium	328	SF	6.7%	Preventive	Surface Seal	328	SF	\$ 1.65	\$ 550
DYB	TL 01	10	L & T CR	Medium	14	LF	0.0%	Stopgap	AC Crack Sealing Narrow	14	LF	\$ 4.25	\$ 60
DYB	TL 01	15	ALLIGATOR CR	Medium	782	SF	6.3%	Stopgap	AC Full-Depth Patching	899	SF	\$ 38.75	\$ 34,840
DYB	TL 01	15	BLOCK CR	Medium	1,143	SF	9.2%	Stopgap	AC Crack Sealing Narrow	348	LF	\$ 4.25	\$ 1,490
DYB	TL 01	15	WEATHERING	Medium	3,092	SF	25.0%	Stopgap	Surface Seal	3,093	SF	\$ 1.65	\$ 5,110
DYB	TL 01	20	ALLIGATOR CR	Medium	436	SF	4.2%	Stopgap	AC Full-Depth Patching	524	SF	\$ 38.75	\$ 20,330
DYB	TL 01	20	L & T CR	Medium	37	LF	0.4%	Stopgap	AC Crack Sealing Narrow	37	LF	\$ 4.25	\$ 160
DYB	TL 01	20	WEATHERING	Medium	2,570	SF	25.0%	Stopgap	Surface Seal	2,570	SF	\$ 1.65	\$ 4,250
DYB	TL 01	30	ALLIGATOR CR	Medium	43	SF	0.3%	Stopgap	AC Full-Depth Patching	74	SF	\$ 38.75	\$ 2,870
DYB	TL 01	30	L & T CR	Medium	86	LF	0.6%	Stopgap	AC Crack Sealing Narrow	86	LF	\$ 4.25	\$ 370
DYB	TL 01	30	RAVELING	Medium	45	SF	0.3%	Stopgap	Surface Seal	45	SF	\$ 1.65	\$ 80
DYB	TL 01	40	ALLIGATOR CR	Medium	1,668	SF	9.7%	Stopgap	AC Full-Depth Patching	1,836	SF	\$ 38.75	\$ 71,150
DYB	TL 01	40	L & T CR	Medium	166	LF	1.0%	Stopgap	AC Crack Sealing Narrow	166	LF	\$ 4.25	\$ 710



STATEWIDE AIRFIELD PAVEMENT MANAGEMENT SYSTEM UPDATE

DYB - Summerville Airport

Network ID	Branch ID	Section ID	Description	Severity	Distress Qty	Distress Unit	Distress Density	Policy Type	Localized Work Type	Work Qty	Work Unit	Unit Cost	Work Cost
DYB	TL 01	40	WEATHERING	Medium	17,121	SF	100.0%	Stopgap	Surface Seal	17,121	SF	\$ 1.65	\$ 28,250
DYB	TL 01	50	L & T CR	Medium	63	LF	0.1%	Stopgap	AC Crack Sealing Narrow	63	LF	\$ 4.25	\$ 270
DYB	TL 01	60	L & T CR	Medium	54	LF	0.4%	Stopgap	AC Crack Sealing Narrow	54	LF	\$ 4.25	\$ 240

Table C4 – 5-Year Major Rehabilitation Needs

Program Year	Network ID	Branch ID	Section ID	Surface	Area (SF)	PCI Before	Rehabilitation Type	Planning Cost Estimate
2025	DYB	AP 01	10	AAC	227,081	60	AC Rehabilitation	\$ 3,350,000
2025	DYB	TL 01	10	AC	51,256	67	AC Rehabilitation	\$ 757,000
2025	DYB	TL 01	15	AC	12,369	26	AC Reconstruction	\$ 535,000
2025	DYB	TL 01	20	AC	10,294	27	AC Reconstruction	\$ 446,000
2025	DYB	TL 01	30	AC	14,306	55	AC Reconstruction	\$ 619,000
2025	DYB	TL 01	40	AC	17,124	22	AC Reconstruction	\$ 741,000
2025	DYB	TL 01	50	AC	48,065	64	AC Rehabilitation	\$ 709,000
2025	DYB	TL 01	60	AC	15,586	63	AC Rehabilitation	\$ 230,000
2027	DYB	TW A	20	AC	47,370	69	AC Rehabilitation	\$ 699,000
2029	DYB	TW A	10	AC	85,889	69	AC Rehabilitation	\$ 1,267,000
2029	DYB	TW C	20	AAC	4,888	69	AC Rehabilitation	\$ 73,000
Total 5-Year Major Rehabilitation Needs =								\$ 9,426,000



Appendix D – PCI Results Summary

RW 6

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
RW 6	RUNWAY	2	374,925	82	Satisfactory

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	277,650	AAC	2007	2019	79	Satisfactory	100	0	0
20	97,275	AC	2013	2019	90	Good	100	0	0



RW 6-10



RW 6-20

TW A

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW A	TAXIWAY	4	193,965	79	Satisfactory

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
05	56,874	AC	2013	2019	90	Good	100	0	0
10	85,889	AC	1994	2019	75	Satisfactory	100	0	0
20	47,370	AC	1994	2019	73	Satisfactory	100	0	0
30	3,832	AAC	2007	2019	79	Satisfactory	78	0	22



TW A-05



TW A-10



TW A-20



TW A-30

TW B

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW B	TAXIWAY	1	15,960	78	Satisfactory

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	15,960	AAC	2007	2019	78	Satisfactory	100	0	0



TW B-10

TW C

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TW C	TAXIWAY	2	13,456	85	Satisfactory

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	8,568	AAC	2013	2019	91	Good	100	0	0
20	4,888	AAC	2007	2019	75	Satisfactory	100	0	0



TW C-10



TW C-20

TL 01

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
TL 01	TAXILANE	7	169,000	56	Fair

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	51,256	AC	2006	2019	68	Fair	99	0	1
15	12,369	AC	1984	2019	27	Very Poor	50	50	0
20	10,294	AC	2000	2019	28	Very Poor	34	49	17
30	14,306	AC	2001	2019	56	Fair	67	23	10
40	17,124	AC	2000	2019	23	Serious	44	52	4
50	48,065	AC	2006	2019	65	Fair	100	0	0
60	15,586	AC	2000	2019	64	Fair	100	0	0



TL 01-15



TL 01-30



TL 01-40



TL 01-50

AP 01

Branch ID	Branch Use	Number of Sections	Branch Area (SF)	Branch Area-Weighted Avg PCI	Branch Condition Rating
AP 01	APRON	2	274,935	67	Fair

Section ID	Area (SF)	Surface	Est. Last Major Work Year	Est. Last Global Treatment Year	PCI	Condition Rating	PCI % Climate	PCI % Load	PCI % Other
10	227,081	AAC	2005	2022	61	Fair	100	0	0
20	47,854	PCC	2021	-	97	Good	0	100	0



AP 01-10



AP 01-20



Appendix E – Re-Inspection Report

Re-Inspection Report

SCAC_2024

Generated Date

6/17/2024

Page 1 of 20

Network:		DYB		Name:		SUMMERVILLE AIRPORT					
Branch:	AP 01		Name:	APRON 01		Use:	APRON	Area:	274,935 SqFt		
Section:	10	of 2		From:	-		To:	-		Last Const.:	5/1/2005
Surface:	AAC		Family:	2024_SC II-AP-AC		Zone:			Category:	G	
Area:	227,081 SqFt		Length:	760 Ft		Width:	299 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:				Grade:	0		Lanes:	0		
Section Comments:											
Work Date:	12/1/1986		Work Type: Surface Course - AC (Layer Construct)				Code:	SU-AC		Is Major M&R: False	
Work Date:	12/1/1986		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: False	
Work Date:	12/1/1986		Work Type: Subgrade - Stabilized				Code:	SG-ST		Is Major M&R: False	
Work Date:	12/1/1986		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Work Date:	12/1/1993		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R: False	
Work Date:	5/1/2005		Work Type: Overlay - AC				Code:	OL-AC		Is Major M&R: True	
Work Date:	6/1/2009		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R: False	
Work Date:	1/1/2019		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False	
Work Date:	7/1/2022		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R: False	
Last Insp. Date:	10/23/2023		TotalSamples:	45		Surveyed:		9			
Conditions:	PCI: 61										
Inspection Comments:											
Sample Number:	01		Type:	R		Area:	5000.00 SqFt		PCI: 59		
Sample Comments:											
43	BLOCK CR		L	5000.00 SqFt							
52	RAVELING		L	750.00 SqFt							
Sample Number:	09		Type:	R		Area:	4950.00 SqFt		PCI: 59		
Sample Comments:											
43	BLOCK CR		L	4950.00 SqFt							
52	RAVELING		L	1238.00 SqFt							
Sample Number:	14		Type:	R		Area:	5000.00 SqFt		PCI: 59		
Sample Comments:											
43	BLOCK CR		L	5000.00 SqFt							
52	RAVELING		L	750.00 SqFt							
Sample Number:	19		Type:	R		Area:	5000.00 SqFt		PCI: 59		
Sample Comments:											
43	BLOCK CR		L	5000.00 SqFt							
52	RAVELING		L	500.00 SqFt							
Sample Number:	22		Type:	R		Area:	4950.00 SqFt		PCI: 64		
Sample Comments:											
43	BLOCK CR		L	4950.00 SqFt							
Sample Number:	26		Type:	R		Area:	5000.00 SqFt		PCI: 59		
Sample Comments:											
43	BLOCK CR		L	5000.00 SqFt							
52	RAVELING		L	500.00 SqFt							

Sample Number: 36		Type: R	Area: 5000.00 SqFt	PCI: 59
Sample Comments:				
43	BLOCK CR	L	5000.00 SqFt	
52	RAVELING	L	1250.00 SqFt	
Sample Number: 39		Type: R	Area: 4950.00 SqFt	PCI: 64
Sample Comments:				
43	BLOCK CR	L	4950.00 SqFt	
Sample Number: 41		Type: R	Area: 5000.00 SqFt	PCI: 59
Sample Comments:				
43	BLOCK CR	L	5000.00 SqFt	
52	RAVELING	L	500.00 SqFt	



Network:	DYB	Name:	SUMMERVILLE AIRPORT						
Branch:	AP 01	Name:	APRON 01	Use:	APRON	Area:	274,935 SqFt		
Section:	20	of	2	From:	-	To:	-	Last Const.:	1/1/2021
Surface:	PCC	Family:	2024_SC II III IV-PCC	Zone:		Category:		Rank:	P
Area:	47,854 SqFt	Length:	427 Ft	Width:	125 Ft				
Slabs:	306	Slab Length:	12 Ft	Slab Width:	12 Ft	Joint Length:	7,988 Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2021	Work Type:	New Construction - PCC		Code:	NC-PC	Is Major M&R:	True	
Work Date:	1/2/2021	Work Type:	Surface Course - PCC (Layer Construct)		Code:	SU-PC	Is Major M&R:	False	
Work Date:	1/3/2021	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R:	False	
Last Insp. Date:	10/23/2023	TotalSamples:	16	Surveyed:	4				
Conditions:	PCI: 97								
Inspection Comments:									
Sample Number:	02	Type:	R	Area:	23.00 Slabs	PCI:	90		
Sample Comments:									
63	LINEAR CR	M	1.00	Slabs					
Sample Number:	04	Type:	R	Area:	20.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									
Sample Number:	09	Type:	R	Area:	20.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									
Sample Number:	12	Type:	R	Area:	20.00 Slabs	PCI:	100		
Sample Comments:									
<No Distress>									




Network:	DYB	Name:	SUMMERVILLE AIRPORT						
Branch:	RW 6	Name:	RUNWAY 6-24	Use:	RUNWAY	Area:	374,925 SqFt		
Section:	10	of	2	From:	-	To:	-	Last Const.:	2/1/2007
Surface:	AAC	Family:	2024_SC II-RW-AC	Zone:		Category:	G	Rank:	P
Area:	277,650 SqFt	Length:	3,750 Ft	Width:			75 Ft		
Slabs:		Slab Length:	Ft	Slab Width:		Ft	Joint Length:		Ft
Shoulder:		Street Type:		Grade:	0		Lanes:	0	
Section Comments:									
Work Date:	12/1/1986	Work Type:	Subgrade - Stabilized			Code:	SG-ST	Is Major M&R:	False
Work Date:	12/1/1986	Work Type:	Base Course - Aggregate			Code:	BA-AG	Is Major M&R:	False
Work Date:	12/1/1986	Work Type:	Surface Course - AC (Layer Construct)			Code:	SU-AC	Is Major M&R:	False
Work Date:	12/1/1986	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	12/1/1993	Work Type:	Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Work Date:	2/1/2007	Work Type:	Overlay - AC			Code:	OL-AC	Is Major M&R:	True
Work Date:	6/1/2009	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Work Date:	1/1/2019	Work Type:	Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Work Date:	1/1/2019	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Last Insp. Date:	10/23/2023	TotalSamples:	50	Surveyed:	10				
Conditions:	PCI:	79							
Inspection Comments:									
Sample Number:	04	Type:	R	Area:	5625.00 SqFt	PCI:	78		
Sample Comments:									
48	L & T CR	L	240.00 Ft						
57	WEATHERING	L	2600.00 SqFt						
57	WEATHERING	M	425.00 SqFt						
Sample Number:	09	Type:	R	Area:	5625.00 SqFt	PCI:	77		
Sample Comments:									
48	L & T CR	L	274.00 Ft						
57	WEATHERING	L	2625.00 SqFt						
57	WEATHERING	M	375.00 SqFt						
Sample Number:	13	Type:	R	Area:	5625.00 SqFt	PCI:	78		
Sample Comments:									
42	BLEEDING	N	2.00 SqFt						
48	L & T CR	L	276.00 Ft						
57	WEATHERING	L	2760.00 SqFt						
57	WEATHERING	M	106.00 SqFt						
Sample Number:	17	Type:	R	Area:	5625.00 SqFt	PCI:	76		
Sample Comments:									
48	L & T CR	L	269.00 Ft						
48	L & T CR	M	29.00 Ft						
57	WEATHERING	L	2812.00 SqFt						
Sample Number:	22	Type:	R	Area:	5625.00 SqFt	PCI:	85		
Sample Comments:									
48	L & T CR	L	177.00 Ft						
57	WEATHERING	L	2812.00 SqFt						
Sample Number:	31	Type:	R	Area:	5625.00 SqFt	PCI:	80		
Sample Comments:									
48	L & T CR	L	280.00 Ft						
57	WEATHERING	L	2812.00 SqFt						

Sample Number: 36		Type: R	Area: 5625.00 SqFt	PCI: 70
Sample Comments:				
48	L & T CR	L	447.00 Ft	
48	L & T CR	M	42.00 Ft	
57	WEATHERING	L	2812.00 SqFt	
Sample Number: 40		Type: R	Area: 5625.00 SqFt	PCI: 86
Sample Comments:				
48	L & T CR	L	153.00 Ft	
57	WEATHERING	L	2812.00 SqFt	
Sample Number: 44		Type: R	Area: 5625.00 SqFt	PCI: 85
Sample Comments:				
48	L & T CR	L	167.00 Ft	
57	WEATHERING	L	2812.00 SqFt	
Sample Number: 48		Type: R	Area: 5625.00 SqFt	PCI: 70
Sample Comments:				
48	L & T CR	L	639.00 Ft	
57	WEATHERING	L	2812.00 SqFt	



Network:	DYB	Name:	SUMMERVILLE AIRPORT						
Branch:	RW 6	Name:	RUNWAY 6-24	Use:	RUNWAY	Area:	374,925 SqFt		
Section:	20	of	2	From:	-	To:	-	Last Const.:	1/1/2013
Surface:	AC	Family:	2024_SC II-RW-AC	Zone:		Category:		Rank:	P
Area:	97,275 SqFt	Length:	1,297 Ft	Width:	75 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2013	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/2/2013	Work Type:	Surface Course - AC (Layer Construct)		Code:	SU-AC	Is Major M&R:	False	
Work Date:	1/3/2013	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R:	False	
Work Date:	1/1/2019	Work Type:	Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False	
Last Insp. Date:	10/23/2023	TotalSamples:	18	Surveyed:	4				
Conditions:	PCI: 90								
Inspection Comments:									
Sample Number:	03	Type:	R	Area:	5625.00 SqFt	PCI:	95		
Sample Comments:									
48	L & T CR	L	62.00	Ft					
Sample Number:	07	Type:	R	Area:	5625.00 SqFt	PCI:	91		
Sample Comments:									
48	L & T CR	L	147.00	Ft					
Sample Number:	12	Type:	R	Area:	5625.00 SqFt	PCI:	90		
Sample Comments:									
48	L & T CR	L	172.00	Ft					
Sample Number:	17	Type:	R	Area:	5625.00 SqFt	PCI:	83		
Sample Comments:									
48	L & T CR	L	329.00	Ft					



Network:	DYB		Name:	SUMMERVILLE AIRPORT							
Branch:	TL 01		Name:	TAXILANE 01		Use:	TAXILANE	Area:	169,000 SqFt		
Section:	10	of	7	From:	-		To:	-		Last Const.:	8/1/2006
Surface:	AC	Family:	2024_SC II-TW TL-AC		Zone:		Category:	G		Rank:	T
Area:	51,256 SqFt		Length:	775 Ft		Width:	72 Ft				
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft		
Shoulder:	Street Type:		Grade:		0		Lanes:	0			
Section Comments:											
Work Date:	12/1/1984		Work Type:	New Construction - AC			Code:	NC-AC		Is Major M&R:	True
Work Date:	12/1/1984		Work Type:	Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False
Work Date:	12/1/1992		Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC		Is Major M&R:	False
Work Date:	8/1/2006		Work Type:	Reconstruction - AC			Code:	RC-AC		Is Major M&R:	True
Work Date:	6/1/2009		Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC		Is Major M&R:	False
Work Date:	1/1/2019		Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC		Is Major M&R:	False
Work Date:	1/1/2019		Work Type:	Crack Sealing - AC			Code:	CS-AC		Is Major M&R:	False
Last Insp. Date:	10/23/2023		TotalSamples:	10		Surveyed:	3				
Conditions:	PCI:		68								
Inspection Comments:											
Sample Number:	02		Type:	R		Area:	4428.00 SqFt		PCI:	67	
Sample Comments:											
42	BLEEDING		N	22.00 SqFt							
48	L & T CR		L	381.00 Ft							
48	L & T CR		M	4.00 Ft							
57	WEATHERING		L	4428.00 SqFt							
Sample Number:	06		Type:	R		Area:	5852.00 SqFt		PCI:	64	
Sample Comments:											
48	L & T CR		L	720.00 Ft							
50	PATCHING		L	175.00 SqFt							
57	WEATHERING		L	5677.00 SqFt							
Sample Number:	10		Type:	R		Area:	4274.00 SqFt		PCI:	76	
Sample Comments:											
48	L & T CR		L	314.00 Ft							
57	WEATHERING		L	4274.00 SqFt							

Network:	DYB			Name:	SUMMERVILLE AIRPORT				
Branch:	TL 01	Name:	TAXILANE 01		Use:	TAXILANE	Area:	169,000 SqFt	
Section:	15	of 7	From:	-	To:	-	Last Const.:	12/1/1984	
Surface:	AC	Family:	2024_SC II-TW TL-AC	Zone:		Category:	G	Rank:	T
Area:	12,369 SqFt	Length:	530 Ft	Width:	20 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	12/1/1984	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	12/1/1984	Work Type:	Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Work Date:	12/1/1992	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Work Date:	6/1/2009	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Work Date:	1/1/2019	Work Type:	Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Work Date:	1/1/2019	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False

Last Insp. Date:	10/23/2023	TotalSamples:	2	Surveyed:	1
Conditions:	PCI:	27			

Inspection Comments:

Sample Number:	01	Type:	R	Area:	5312.00 SqFt	PCI:	27
-----------------------	----	--------------	---	--------------	--------------	-------------	----

Sample Comments:

41	ALLIGATOR CR	L	66.00	SqFt
41	ALLIGATOR CR	M	336.00	SqFt
43	BLOCK CR	L	4419.00	SqFt
43	BLOCK CR	M	491.00	SqFt
57	WEATHERING	L	3984.00	SqFt
57	WEATHERING	M	1328.00	SqFt



Network:	DYB	Name:	SUMMERVILLE AIRPORT						
Branch:	TL 01	Name:	TAXILANE 01	Use:	TAXILANE	Area:	169,000 SqFt		
Section:	20	of	7	From:	-	To:	-	Last Const.:	6/1/2000
Surface:	AC	Family:	2024_SC II-TW TL-AC	Zone:		Category:	G	Rank:	T
Area:	10,294 SqFt	Length:	270 Ft	Width:	32 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	6/1/2000	Work Type:	Surface Course - AC (Layer Construct)			Code:	SU-AC	Is Major M&R:	False
Work Date:	6/1/2000	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	6/1/2009	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Work Date:	1/1/2019	Work Type:	Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Work Date:	1/1/2019	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Last Insp. Date:	10/23/2023	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI:	28							
Inspection Comments:									
Sample Number:	02	Type:	R	Area:	4670.00 SqFt	PCI:	28		
Sample Comments:									

41	ALLIGATOR CR	L	38.00	SqFt
41	ALLIGATOR CR	M	198.00	SqFt
45	DEPRESSION	L	318.00	SqFt
48	L & T CR	L	358.00	Ft
48	L & T CR	M	17.00	Ft
50	PATCHING	L	5.00	SqFt
57	WEATHERING	L	3499.00	SqFt
57	WEATHERING	M	1166.00	SqFt



Network:	DYB	Name:	SUMMERVILLE AIRPORT						
Branch:	TL 01	Name:	TAXILANE 01	Use:	TAXILANE	Area:	169,000 SqFt		
Section:	30	of	7	From:	-	To:	-	Last Const.:	6/1/2001
Surface:	AC	Family:	2024_SC II-TW TL-AC	Zone:		Category:	G	Rank:	T
Area:	14,306 SqFt	Length:	336 Ft	Width:	40 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	6/1/2001	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Work Date:	6/1/2001	Work Type:	Surface Course - AC (Layer Construct)		Code:	SU-AC	Is Major M&R:	False	
Work Date:	6/1/2009	Work Type:	Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False	
Work Date:	1/1/2019	Work Type:	Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False	
Work Date:	1/1/2019	Work Type:	Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False	
Last Insp. Date:	10/23/2023	TotalSamples:	3	Surveyed:	2				
Conditions:	PCI: 56								
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	4933.00 SqFt	PCI:	49		
Sample Comments:									
41	ALLIGATOR CR	M	34.00	SqFt					
48	L & T CR	L	594.00	Ft					
48	L & T CR	M	25.00	Ft					
50	PATCHING	M	58.00	SqFt					
52	RAVELING	M	35.00	SqFt					
57	WEATHERING	L	4840.00	SqFt					
Sample Number:	03	Type:	R	Area:	6248.00 SqFt	PCI:	61		
Sample Comments:									
45	DEPRESSION	L	115.00	SqFt					
48	L & T CR	L	514.00	Ft					
48	L & T CR	M	42.00	Ft					
50	PATCHING	L	20.00	SqFt					
56	SWELLING	L	5.00	SqFt					
57	WEATHERING	L	6228.00	SqFt					

Network:	DYB	Name:	SUMMERVILLE AIRPORT						
Branch:	TL 01	Name:	TAXILANE 01	Use:	TAXILANE	Area:	169,000 SqFt		
Section:	40	of	7	From:	-	To:	-	Last Const.:	6/1/2000
Surface:	AC	Family:	2024_SC II-TW TL-AC	Zone:		Category:	G	Rank:	T
Area:	17,124 SqFt	Length:	228 Ft	Width:	75 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	6/1/2000	Work Type:	Surface Course - AC (Layer Construct)			Code:	SU-AC	Is Major M&R:	False
Work Date:	6/1/2000	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	6/1/2009	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Work Date:	1/1/2019	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Work Date:	1/1/2019	Work Type:	Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Last Insp. Date:	10/23/2023	TotalSamples:	3	Surveyed:	1				
Conditions:	PCI:	23							
Inspection Comments:									
Sample Number:	02	Type:	R	Area:	5658.00 SqFt	PCI:	23		
Sample Comments:									

41	ALLIGATOR CR	L	46.00	SqFt
41	ALLIGATOR CR	M	551.00	SqFt
43	BLOCK CR	L	88.00	SqFt
45	DEPRESSION	L	48.00	SqFt
48	L & T CR	L	499.00	Ft
48	L & T CR	M	55.00	Ft
50	PATCHING	L	1.00	SqFt
57	WEATHERING	M	5657.00	SqFt



Network:	DYB	Name:	SUMMERVILLE AIRPORT						
Branch:	TL 01	Name:	TAXILANE 01	Use:	TAXILANE	Area:	169,000 SqFt		
Section:	50	of	7	From:	-	To:	-	Last Const.:	8/1/2006
Surface:	AC	Family:	2024_SC II-TW TL-AC	Zone:		Category:		Rank:	T
Area:	48,065 SqFt	Length:	675 Ft	Width:	75 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	8/1/2006	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Work Date:	8/2/2006	Work Type:	Surface Course - AC (Layer Construct)		Code:	SU-AC	Is Major M&R:	False	
Work Date:	8/3/2006	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R:	False	
Work Date:	6/1/2009	Work Type:	Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False	
Work Date:	1/1/2019	Work Type:	Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False	
Work Date:	1/2/2019	Work Type:	Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False	
Last Insp. Date: 10/23/2023									
		Total Samples:	10	Surveyed:		2			
Conditions: PCI: 65									
Inspection Comments:									
Sample Number:	05	Type:	R	Area:	5624.00 SqFt	PCI:	60		
Sample Comments:									
43	BLOCK CR	L	286.00	SqFt					
48	L & T CR	L	659.00	Ft					
48	L & T CR	M	14.00	Ft					
57	WEATHERING	L	5624.00	SqFt					
Sample Number:	09	Type:	R	Area:	5000.00 SqFt	PCI:	71		
Sample Comments:									
48	L & T CR	L	528.00	Ft					
57	WEATHERING	L	5000.00	SqFt					

Network:	DYB	Name:	SUMMERVILLE AIRPORT							
Branch:	TL 01	Name:	TAXILANE 01	Use:	TAXILANE	Area:	169,000 SqFt			
Section:	60	of	7	From:	-	To:	-	Last Const.:	6/1/2000	
Surface:	AC	Family:	2024_SC II-TW TL-AC	Zone:		Category:	G	Rank:	T	
Area:	15,586 SqFt	Length:	214 Ft	Width:	68 Ft					
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft			
Shoulder:		Street Type:		Grade:	0	Lanes:	0			
Section Comments:										
Work Date:	6/1/2000	Work Type:			Surface Course - AC (Layer Construct)		Code:	SU-AC	Is Major M&R:	False
Work Date:	6/1/2000	Work Type:			New Construction - AC		Code:	NC-AC	Is Major M&R:	True
Work Date:	6/1/2009	Work Type:			Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False
Work Date:	1/1/2019	Work Type:			Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False
Work Date:	1/1/2019	Work Type:			Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False
Last Insp. Date:	10/23/2023	TotalSamples:	3	Surveyed:		1				
Conditions:	PCI:	64								
Inspection Comments:										
Sample Number:	02	Type:	R	Area:	5467.00 SqFt	PCI:	64			
Sample Comments:										

- 48

L & T CR

L

689.00 Ft
- 48

L & T CR

M

19.00 Ft
- 57


WEATHERING



L

5467.00 SqFt



Network:	DYB	Name:	SUMMERVILLE AIRPORT						
Branch:	TW A	Name:	TAXIWAY A	Use:	TAXIWAY	Area:	193,965 SqFt		
Section:	05	of	4	From:	-	To:	-	Last Const.:	1/1/2013
Surface:	AC	Family:	2024_SC II-TW TL-AC	Zone:		Category:		Rank:	P
Area:	56,874 SqFt	Length:	1,650 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	1/1/2013	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Work Date:	1/2/2013	Work Type:	Surface Course - AC (Layer Construct)		Code:	SU-AC	Is Major M&R:	False	
Work Date:	1/3/2013	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R:	False	
Work Date:	1/1/2019	Work Type:	Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False	
Last Insp. Date:	10/23/2023	TotalSamples:	11	Surveyed:	3				
Conditions:	PCI: 90								
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	4762.00 SqFt	PCI:	90		
Sample Comments:									
48	L & T CR	L	53.00	Ft					
57	WEATHERING	L	2381.00	SqFt					
Sample Number:	04	Type:	R	Area:	5250.00 SqFt	PCI:	91		
Sample Comments:									
48	L & T CR	L	44.00	Ft					
57	WEATHERING	L	2625.00	SqFt					
Sample Number:	09	Type:	R	Area:	5250.00 SqFt	PCI:	90		
Sample Comments:									
48	L & T CR	L	61.00	Ft					
57	WEATHERING	L	2625.00	SqFt					



Network:		DYB		Name:		SUMMERVILLE AIRPORT																					
Branch:		TW A		Name:		TAXIWAY A		Use:		TAXIWAY		Area:		193,965 SqFt													
Section:		10		of		4		From:		-		To:		-		Last Const.:		8/1/1994									
Surface:		AC		Family:		2024_SC II-TW TL-AC		Zone:				Category:		G		Rank:		P									
Area:		85,889 SqFt		Length:		1,650 Ft		Width:		35 Ft																	
Slabs:				Slab Length:		Ft		Slab Width:		Ft		Joint Length:				Ft											
Shoulder:				Street Type:				Grade:		0		Lanes:		0													
Section Comments:																											
Work Date:				8/1/1994				Work Type:				Surface Course - AC (Layer Construct)				Code:		SU-AC		Is Major M&R:		False					
Work Date:				8/1/1994				Work Type:				Subgrade - Stabilized				Code:		SG-ST		Is Major M&R:		False					
Work Date:				8/1/1994				Work Type:				New Construction - AC				Code:		NC-AC		Is Major M&R:		True					
Work Date:				8/1/1994				Work Type:				Base Course - Aggregate				Code:		BA-AG		Is Major M&R:		False					
Work Date:				6/1/2009				Work Type:				Surface Treatment - Seal Coat				Code:		ST-SC		Is Major M&R:		False					
Work Date:				1/1/2019				Work Type:				Surface Treatment - Seal Coat				Code:		ST-SC		Is Major M&R:		False					
Work Date:				1/1/2019				Work Type:				Crack Sealing - AC				Code:		CS-AC		Is Major M&R:		False					
Last Insp. Date:				10/23/2023				TotalSamples:				16				Surveyed:				4							
Conditions:				PCI:				75																			
Inspection Comments:																											
Sample Number:				03				Type:		R		Area:				5250.00 SqFt				PCI:				75			
Sample Comments:																											
48		L & T CR		L		188.00		Ft																			
48		L & T CR		M		33.00		Ft																			
50		PATCHING		L		58.00		SqFt																			
57		WEATHERING		L		2596.00		SqFt																			
Sample Number:				06				Type:		R		Area:				5250.00 SqFt				PCI:				78			
Sample Comments:																											
48		L & T CR		L		207.00		Ft																			
48		L & T CR		M		30.00		Ft																			
57		WEATHERING		L		2625.00		SqFt																			
Sample Number:				09				Type:		R		Area:				5250.00 SqFt				PCI:				74			
Sample Comments:																											
48		L & T CR		L		183.00		Ft																			
48		L & T CR		M		31.00		Ft																			
50		PATCHING		L		78.00		SqFt																			
57		WEATHERING		L		2588.00		SqFt																			
Sample Number:				14				Type:		R		Area:				5250.00 SqFt				PCI:				74			
Sample Comments:																											
48		L & T CR		L		226.00		Ft																			
48		L & T CR		M		29.00		Ft																			
50		PATCHING		L		28.00		SqFt																			
57		WEATHERING		L		2611.00		SqFt																			

Network:	DYB	Name:	SUMMERVILLE AIRPORT						
Branch:	TW A	Name:	TAXIWAY A	Use:	TAXIWAY	Area:	193,965 SqFt		
Section:	20	of	4	From:	-	To:	-	Last Const.:	8/1/1994
Surface:	AC	Family:	2024_SC II-TW TL-AC	Zone:		Category:	G	Rank:	P
Area:	47,370 SqFt	Length:	1,350 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	8/1/1994	Work Type:	Base Course - Aggregate		Code:	BA-AG	Is Major M&R:	False	
Work Date:	8/1/1994	Work Type:	Surface Course - AC (Layer Construct)		Code:	SU-AC	Is Major M&R:	False	
Work Date:	8/1/1994	Work Type:	New Construction - AC		Code:	NC-AC	Is Major M&R:	True	
Work Date:	8/1/1994	Work Type:	Subgrade - Stabilized		Code:	SG-ST	Is Major M&R:	False	
Work Date:	6/1/2009	Work Type:	Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False	
Work Date:	1/1/2019	Work Type:	Surface Treatment - Seal Coat		Code:	ST-SC	Is Major M&R:	False	
Work Date:	1/1/2019	Work Type:	Crack Sealing - AC		Code:	CS-AC	Is Major M&R:	False	
Last Insp. Date:	10/23/2023	TotalSamples:	9	Surveyed:	3				
Conditions:	PCI:	73							
Inspection Comments:									
Sample Number:	02	Type:	R	Area:	5250.00 SqFt	PCI:	73		
Sample Comments:									
48	L & T CR	L	260.00 Ft						
48	L & T CR	M	10.00 Ft						
50	PATCHING	L	36.00 SqFt						
57	WEATHERING	L	2607.00 SqFt						
Sample Number:	05	Type:	R	Area:	5250.00 SqFt	PCI:	78		
Sample Comments:									
48	L & T CR	L	197.00 Ft						
48	L & T CR	M	64.00 Ft						
57	WEATHERING	L	2625.00 SqFt						
Sample Number:	08	Type:	R	Area:	5441.00 SqFt	PCI:	68		
Sample Comments:									
48	L & T CR	L	333.00 Ft						
48	L & T CR	M	95.00 Ft						
50	PATCHING	L	132.00 SqFt						
57	WEATHERING	L	2655.00 SqFt						

Network:	DYB			Name:	SUMMERVILLE AIRPORT							
Branch:	TW A		Name:	TAXIWAY A		Use:	TAXIWAY		Area:	193,965 SqFt		
Section:	30	of	4	From:	-		To:	-		Last Const.:	2/1/2007	
Surface:	AAC		Family:	2024_SC II-TW TL-AC		Zone:			Category:	G	Rank:	P
Area:	3,832 SqFt		Length:	75 Ft		Width:	35 Ft					
Slabs:	Slab Length:		Ft		Slab Width:	Ft		Joint Length:	Ft			
Shoulder:	Street Type:				Grade:	0		Lanes:	0			
Section Comments:												
Work Date:	8/1/1994		Work Type: Subgrade - Stabilized				Code:	SG-ST		Is Major M&R:	False	
Work Date:	8/1/1994		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R:	True	
Work Date:	8/1/1994		Work Type: Surface Course - AC (Layer Construct)				Code:	SU-AC		Is Major M&R:	False	
Work Date:	8/1/1994		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R:	False	
Work Date:	2/1/2007		Work Type: Overlay - AC				Code:	OL-AC		Is Major M&R:	True	
Work Date:	1/1/2019		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R:	False	
Work Date:	1/1/2019		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R:	False	

Last Insp. Date: 10/23/2023

TotalSamples: 1

Surveyed: 1

Conditions: PCI: 79

Inspection Comments:

Sample Number: 01

Type: R

Area: 3832.00 SqFt

PCI: 79


Sample Comments:

42 BLEEDING N 34.00 SqFt

48 L & T CR L 83.00 Ft


57 WEATHERING L 3640.00 SqFt

57 WEATHERING M 192.00 SqFt



Network:	DYB	Name:	SUMMERVILLE AIRPORT						
Branch:	TW B	Name:	TAXIWAY B	Use:	TAXIWAY	Area:	15,960 SqFt		
Section:	10	of	1	From:	-	To:	-	Last Const.:	2/1/2007
Surface:	AAC	Family:	2024_SC II-TW TL-AC	Zone:		Category:	G	Rank:	P
Area:	15,960 SqFt	Length:	400 Ft	Width:	35 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	12/1/1986	Work Type:	Subgrade - Stabilized			Code:	SG-ST	Is Major M&R:	False
Work Date:	12/1/1986	Work Type:	Surface Course - AC (Layer Construct)			Code:	SU-AC	Is Major M&R:	False
Work Date:	12/1/1986	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	12/1/1986	Work Type:	Base Course - Aggregate			Code:	BA-AG	Is Major M&R:	False
Work Date:	2/1/2007	Work Type:	Overlay - AC			Code:	OL-AC	Is Major M&R:	True
Work Date:	6/1/2009	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Work Date:	1/1/2019	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Work Date:	1/1/2019	Work Type:	Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Last Insp. Date:	10/23/2023	TotalSamples:	4	Surveyed:	1				
Conditions:	PCI:	78							
Inspection Comments:									

Sample Number:	02	Type:	R	Area:	3500.00 SqFt	PCI:	78
Sample Comments:							
42	BLEEDING	N	4.00	SqFt			
48	L & T CR	L	157.00	Ft			
57	WEATHERING	L	3325.00	SqFt			
57	WEATHERING	M	175.00	SqFt			



Network:	DYB	Name:	SUMMERVILLE AIRPORT						
Branch:	TW C	Name:	TAXIWAY C	Use:	TAXIWAY	Area:	13,456 SqFt		
Section:	10	of	2	From:	-	To:	-	Last Const.:	1/1/2013
Surface:	AAC	Family:	2024_SC II-TW TL-AC	Zone:		Category:	G	Rank:	P
Area:	8,568 SqFt	Length:	340 Ft	Width:	38 Ft				
Slabs:		Slab Length:	Ft	Slab Width:	Ft	Joint Length:	Ft		
Shoulder:		Street Type:		Grade:	0	Lanes:	0		
Section Comments:									
Work Date:	8/1/1994	Work Type:	New Construction - AC			Code:	NC-AC	Is Major M&R:	True
Work Date:	8/1/1994	Work Type:	Subgrade - Stabilized			Code:	SG-ST	Is Major M&R:	False
Work Date:	8/1/1994	Work Type:	Base Course - Aggregate			Code:	BA-AG	Is Major M&R:	False
Work Date:	8/1/1994	Work Type:	Surface Course - AC (Layer Construct)			Code:	SU-AC	Is Major M&R:	False
Work Date:	6/1/2009	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Work Date:	1/1/2013	Work Type:	Overlay - AC			Code:	OL-AC	Is Major M&R:	True
Work Date:	1/1/2019	Work Type:	Surface Treatment - Seal Coat			Code:	ST-SC	Is Major M&R:	False
Work Date:	1/1/2019	Work Type:	Crack Sealing - AC			Code:	CS-AC	Is Major M&R:	False
Last Insp. Date:	10/23/2023	TotalSamples:	2	Surveyed:	1				
Conditions:	PCI:	91							
Inspection Comments:									
Sample Number:	01	Type:	R	Area:	3849.00 SqFt	PCI:	91		
Sample Comments:									
48	L & T CR	L	24.00 Ft						
57	WEATHERING	L	1924.00 SqFt						



Network:	DYB			Name:	SUMMERVILLE AIRPORT						
Branch:	TW C		Name:	TAXIWAY C		Use:	TAXIWAY		Area:	13,456 SqFt	
Section:	20 of 2		From:	-			To:	-		Last Const.:	2/1/2007
Surface:	AAC		Family:	2024_SC II-TW TL-AC		Zone:	Category: G		Rank: P		
Area:	4,888 SqFt		Length:	75 Ft		Width:	38 Ft				
Slabs:	Slab Length:		Ft		Slab Width:		Ft		Joint Length:		Ft
Shoulder:	Street Type:		Grade:		0		Lanes:		0		
Section Comments:											
Work Date:	8/1/1994		Work Type: New Construction - AC				Code:	NC-AC		Is Major M&R: True	
Work Date:	8/1/1994		Work Type: Base Course - Aggregate				Code:	BA-AG		Is Major M&R: False	
Work Date:	8/1/1994		Work Type: Subgrade - Stabilized				Code:	SG-ST		Is Major M&R: False	
Work Date:	8/1/1994		Work Type: Surface Course - AC (Layer Construct)				Code:	SU-AC		Is Major M&R: False	
Work Date:	2/1/2007		Work Type: Overlay - AC				Code:	OL-AC		Is Major M&R: True	
Work Date:	6/1/2009		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R: False	
Work Date:	1/1/2019		Work Type: Surface Treatment - Seal Coat				Code:	ST-SC		Is Major M&R: False	
Work Date:	1/1/2019		Work Type: Crack Sealing - AC				Code:	CS-AC		Is Major M&R: False	
Last Insp. Date:	10/23/2023		TotalSamples:	1		Surveyed:	1				


Conditions:
 PCI: 75

Inspection Comments:

Sample Number:	01	Type:	R	Area:	4888.00 SqFt	PCI:	75
-----------------------	----	--------------	---	--------------	--------------	-------------	----

Sample Comments:

48	L & T CR	L	194.00	Ft
52	RAVELING	L	76.00	SqFt
57	WEATHERING	L	3678.00	SqFt
57	WEATHERING	M	328.00	SqFt





Kimley»Horn