

5J9 - TWIN CITY
 CHARLOTTE SECTIONAL
 12/28/2023

LORIS - 42

Latitude: 34° 05' 18.3000" N
 Longitude: 78° 51' 53.7000" W



Elevation - 99' MSL

Mag Var - 08° W

Runway						Edge	Approach	Traffic
ID	Length	Width	Surface	VGSI	REILS	Lights	Lights	Pattern
08/26	3694'	60'	ASPH	26		LOW		Standard

Runway Pavement Strength					Navigation			
Runway	SW	DW	DTW	DDTW	IDENT	Type	FREQ	Direct/Dist
08/26	8.0				CRE	VORTAC	114.40	r340° 17.9 NM to fld

Communications				ATC		AWOS/ASOS	
UniCom	CTAF	GCO	RCO	FREQ	FAA ID	FREQ	Phone
	122.900			119.2	MYR		

Manager Judi Olmstead	Storage TIE	Repairs N
GPS 1326 Tory Hill Rd	Landing Fee N	Oxygen N
Address Loris, SC 29569	Lighting Sched DUSK-DAWN	Fuel Type N
Phone (843) 839-7359		
Fax (843) 626-9096	Att Schedule UNATTENDED	
Email olmsteaj@horrycountysc.org	Remarks ACTVT LIRL - CTAF	
FBO Phone/Fax		