

DLC - DILLON COUNTY
CHARLOTTE SECTIONAL
 12/28/2023

DILLON - 22

Latitude: 34° 26' 56.6000" N
Longitude: 79° 22' 06.9000" W



Elevation - 133' MSL

Mag Var - 09° W

Runway						Edge	Approach	Traffic
ID	Length	Width	Surface	VGSI	REILS	Lights	Lights	Pattern
07/25	3000'	60'	ASPH			MED		Standard

Runway Pavement Strength					Navigation			
Runway	SW	DW	DTW	DDTW	IDENT	Type	FREQ	Direct/Dist
07/25	10.0				FLO	VORTAC	115.20	r051° 19.3 NM to fld

Communications				ATC		AWOS/ASOS	
UniCom	CTAF	GCO	RCO	FREQ	FAA ID	FREQ	Phone
	122.900			118.6	FLO		

Manager	Tim Harper	Storage	TIE	Repairs	N
GPS	1088 Airport Rd	Landing Fee	N	Oxygen	N
Address	Dillon, SC 29536	Lighting Sched	SS-SR	Fuel Type	N
Phone	(843) 774-1400				
Fax	(843) 774-1443	Att Schedule	UNATTENDED		
Email	tharper@dilloncountysc.org	Remarks	RWY 7/25 in fair condition		
FBO Phone/Fax					