



Elevation - 92' MSL

Mag Var - 09° W

Runway						Edge	Approach	Traffic
ID	Length	Width	Surface	VGSI	REILS	Lights	Lights	Pattern
04/22	4504'	100'	ASPH	04/22		MED		04,22 - RH

Runway Pavement Strength					Navigation			
Runway	SW	DW	DTW	DDTW	IDENT	Type	FREQ	Direct/Dist
04/22	30.5	46.5			FLO	VORTAC	115.20	r104° 16.3NM to fld

Communications				ATC		AWOS/ASOS	
UniCom	CTAF	GCO	RCO	FREQ	FAA ID	FREQ	Phone
122.800	122.800			135.25	FLO	119.875	(843) 423-4231

Manager Charles Taylor, Director
GPS 225 Airport Ct
Address Mullins, SC 29574
Phone (843) 423-8265
Fax
Email ctaylor@marionsc.org
FBO Phone/Fax

Storage HGR,TIE
Repairs N
Landing Fee N
Oxygen N
Lighting Sched SS-SR
Fuel Type 100LL, JET A
Att Schedule Daily 0700-1700
Remarks Self Service 100LL and JET A