

S17 - TWIN LAKES
 ATLANTA SECTIONAL
 5/18/2023

GRANITEVILLE - 25

Latitude: 33° 38' 44.4890" N
Longitude: 81° 52' 01.4030" W



Elevation - 540' MSL

Mag Var - 07° W

Runway						Edge	Approach	Traffic
ID	Length	Width	Surface	VGSI	REILS	Lights	Lights	Pattern
06/24	4000'	60'	ASPH			NSTD		Standard

Runway Pavement Strength					Navigation			
Runway	SW	DW	DTW	DDTW	IDENT	Type	FREQ	Direct/Dist
06/24	12.5				IRQ	VORTAC	113.90	r108° 15.2 NM to fld

Communications				ATC		AWOS/ASOS	
UniCom	CTAF	GCO	RCO	FREQ	FAA ID	FREQ	Phone

122.900

Manager John Johnson
GPS 150 Piper Drive
Address Trenton, SC 29847
Phone (803) 300-2438
Fax
Email j.johnson@pmf-inc.com
FBO Phone/Fax

Storage
Landing Fee N
Lighting Sched SEE RMK
Att Schedule UNATTENDED
Remarks RWY 6 displaced thld. 636'
 Flying Community/Airpark
 Runway CLOSED DUSK-DAWN
 Private Airport - Public Use

Repairs N
Oxygen N
Fuel Type N