

3JØ - HAMPTON COUNTY
CHARLOTTE SECTIONAL
 12/28/2023

HAMPTON - 31

Latitude: 32° 51' 59.4400" N
Longitude: 81° 04' 51.4930" W



Elevation - 113' MSL

Mag Var - 07° W

Runway						Edge	Approach	Traffic
ID	Length	Width	Surface	VGSI	REILS	Lights	Lights	Pattern
11/29	3601'	60'	ASPH					Standard

Runway Pavement Strength					Navigation			
Runway	SW	DW	DTW	DDTW	IDENT	Type	FREQ	Direct/Dist
11/29	8.0				SAV	VORTAC	115.95	r014° 43.5 NM to fld

Communications				ATC		AWOS/ASOS	
UniCom	CTAF	GCO	RCO	FREQ	FAA ID	FREQ	Phone
							122.900

Manager David Steinmeyer	Storage Tie	Repairs N
GPS 740 Airport Rd	Landing Fee N	Oxygen N
Address Varnville, SC 29944	Lighting Sched	Fuel Type 100LL, JET A
Phone (803) 942-3369		
Fax	Att Schedule M-F 0800-1700	
Email dsteinmeyer@hamptoncountysc.org	Remarks AFTER HRS CALL (803) 942-3369	
FBO Phone/Fax	SELF SERVE 100LL and JET A	
	4 CLICKS ON CTAF FOR WX	
	3 CLICKS ON CTAF FOR WIND	