

52J - LEE COUNTY-BUTTERS FLD

CHARLOTTE SECTIONAL
12/28/2023

BISHOPVILLE - 9

Latitude: 34° 14' 40.1460" N
Longitude: 80° 14' 09.7210" W



Elevation - 211' MSL

Mag Var - 08° W

Runway						Edge	Approach	Traffic
ID	Length	Width	Surface	VGSI	REILS	Lights	Lights	Pattern
06/24	3200'	60'	ASPH	06/24		MED		Standard

Runway Pavement Strength					Navigation				
Runway	SW	DW	DTW	DDTW	IDENT	Type	FREQ	Direct/Dist	
06/24	12.5	25.0			CTF	VOR/DME	114.55	r178° 24.4 NM to fld	

Communications				ATC		AWOS/ASOS	
UniCom	CTAF	GCO	RCO	FREQ	FAA ID	FREQ	Phone

122.900

Manager George Roberts
GPS 145 Airport Rd
Address Bishopville, SC 29010
Phone (803) 229-2679
Fax
Email mwatkins1@sc.rr.com
FBO Phone/Fax

Storage TIE **Repairs** N
Landing Fee N **Oxygen** N
Lighting Sched SEE RMK **Fuel Type** 100LL
Att Schedule UNATTENDED
Remarks BCN - SS to SR, PAPI - SR to SS
NIGHT ACTVT PAPI/MIRL W CTAF PCL
SELF SERVICE 100LL