

5J5 - HOLLY HILL
 CHARLOTTE SECTIONAL
 12/28/2023

HOLLY HILL - 35
 Latitude: 33° 18' 05.4900" N
 Longitude: 80° 23' 35.0900" W



Elevation - 96' MSL

Mag Var - 08° W

Runway						Edge	Approach	Traffic
ID	Length	Width	Surface	VGSI	REILS	Lights	Lights	Pattern
04/22	3900'	75'	TURF					Standard

Runway Pavement Strength					Navigation			
Runway	SW	DW	DTW	DDTW	IDENT	Type	FREQ	Direct/Dist
04/22					VAN	VORTAC	110.40	r171° 10.8 NM to fld

Communications				ATC		AWOS/ASOS	
UniCom	CTAF	GCO	RCO	FREQ	FAA ID	FREQ	Phone
							122.900

Manager Billy N. Chavis	Storage TIE	Repairs N
GPS 140 Airport Rd	Landing Fee N	Oxygen N
Address Holly Hill, SC 29059	Lighting Sched	Fuel Type N
Phone (803) 496-3330		
Fax	Att Schedule UNATTENDED	
Email mayorofhollyhill@gmail.com	Remarks	
FBO Phone/Fax		